

HAZARDOUS MATERIALS PRE-DEMOLITION SURVEY

**CITY OF ALABASTER
FORMER POLICE STATION
201 1ST STREET NORTH
ALABASTER, ALABAMA**

PPM PROJECT NO. 40024103-HM

JANUARY 30, 2026



HAZARDOUS MATERIALS PRE-DEMOLITION SURVEY

FOR

**FORMER POLICE STATION
201 1ST STREET NORTH
ALABASTER, AL 35007**

PREPARED FOR:

**CITY OF ALABASTER
1953 MUNICIPAL WAY
ALABASTER, ALABAMA 35007**

PPM PROJECT NO. 40024103-HM

JANUARY 30, 2026

**PPM CONSULTANTS, INC.
5555 BANKHEAD HIGHWAY
BIRMINGHAM, ALABAMA 35210
(205) 836-5650**

TABLE OF CONTENTS

	<u>PAGE</u>
1.0 SURVEY INFORMATION	1
1.1 Summary	1
1.2 Introduction.....	3
1.3 Site Description	3
1.4 Methodology.....	3
1.5 Asbestos-Containing Materials Survey.....	4
1.6 Lead Based Paint Survey	5
1.7 Polychlorinated Biphenyls Survey	5
2.0 SURVEY INFORMATION AND RESULTS.....	6
2.1 Asbestos Sampling and Analytical Results.....	6
2.2 Polychlorinated Biphenyls (PCBs) Sampling and Analytical Results .	7
2.3 Lead Paint Sampling and Analytical Results	7
3.0 CONCLUSIONS AND RECOMMENDATIONS.....	7
3.1 Asbestos Regulatory Information.....	8
3.2 PCBs Regulatory Information	9
3.3 Lead Regulatory Information	9
3.4 Fluorescent Light Tubes and PCB Light Ballasts.....	10
3.5 Thermostats with Mercury Switches	10
3.6 Freon and Fluorocarbons	10
4.0 ASSUMPTIONS AND LIMITATIONS	10

APPENDICES

- Appendix A Sample Location Maps
- Appendix B Laboratory Results & Sample Logs
- Appendix C Photograph Logs
- Appendix D Certifications

1.0 SURVEY INFORMATION

1.1 SUMMARY

The United States Environmental Protection Agency (US EPA), National Emission Standards for Hazardous Air Pollutants (NESHAP), 40 CFR Part 61 - Nov. 20, 1990 require an owner or operator of a demolition or renovation project to thoroughly inspect a facility or part of a facility where a demolition or renovation operation will occur for the presence of asbestos-containing materials (ACM) prior to the commencement of that project. This inspection report was requested by the City of Alabaster (Alabaster).

The purpose of the inspection was to comply with the US EPA NESHAP requirements to determine if ACM, polychlorinated biphenyls (PCB), lead based paint (LBP) or lead containing paint (LCP) are present and may be impacted during the upcoming demolition of the former Alabaster Police Station with an address of 201 1st Street North, in Alabaster, Alabama, herein referred to as the Site.

This is a summary of the report. The report must be read in its entirety, and the reader must review all the detailed information provided in the body of the report prior to making any interpretations or conclusions pertaining to the information. Any conclusions made by the reader about the information provided in the body of this report, which are contradictory or not included in this report are the responsibility of the reader.

Asbestos

On January 6-8, 2026, PPM Consultants (PPM) conducted a pre-demolition inspection of the interior and exterior of the Site. The results of the survey indicated asbestos was detected in the following materials/locations sampled from the former Police Station located at 201 1st Street North:

- Grey Duct Work Tape – hallway of main floor and air handler closet in basement – 80% Chrysotile
- Black and yellow mastic – main floor NE office, middle office, and hallway under dark brown wood flooring – 8% Chrysotile
- Tan floor tile – main floor hallway and southeast closet – 2% Chrysotile
- Black mastic – under tan floor tile main floor hallway and southeast closet – 8% Chrysotile

- Black mastic – under light brown laminate flooring main floor middle and south hallway – 8% Chrysotile
- Tan Herringbone Laminate flooring – main entry at main floor – 2% Chrysotile
- Black and yellow mastic – under tan herringbone laminate flooring – 8% Chrysotile
- Black mastic – under tan tile (2nd layer) entry and within dispatch office – 8% Chrysotile
- Grey tile – under tan tile/mastic entry and within dispatch office (3rd layer of tile in sample) – 2% Chrysotile
- Black mastic – under red/white/blue tile (2nd layer mastic) SW office, computer room, and plumbing access area in basement – 8% Chrysotile

Lead Paint

PPM collected 17 samples of suspect lead-containing paints and coatings during this inspection. The analytical results indicate the following materials sampled were determined to contain more than 0.5 percent by weight and are considered to be lead-based paints per the EPA:

- Tan paint, metal gutter at west entry– 0.83% by weight
- Black paint, metal railing, and bollards at west entry– 0.56% by weight

The analytical results indicate the following materials sampled were determined to have measurable amounts of lead below the 0.5 percent by weight threshold and are classified as lead containing by Occupational Safety and Health Administration (OSHA) Regulations:

- Light green paint on concrete masonry unit (CMU) wall SW closet on main level – 0.0064% by weight
- Multi-layer/color paint on metal walls, CMU walls, and concrete floor in jail cell in basement – 0.057% by weight

PCBs

PPM did not identify suspect PCB-contaminated caulking during this inspection.

1.2 INTRODUCTION

The survey was conducted in accordance with PPM's proposal for a pre-demolition hazardous materials inspection. This report presents results of a hazardous materials pre-demolition inspection performed by PPM which included the interior and exterior of the Site.

The inspection was conducted by Chuck Gooden and Joanna Rowlen of PPM on January 6-8, 2026. Mr. Chuck Gooden and Ms. Joanna Rowlen are US EPA Asbestos Hazard Emergency Response Act (AHERA) accredited Building Inspectors and have their Alabama Asbestos Accreditation numbers. Each have lead awareness training and are also OSHA 40-hour Hazardous Waste Operations and Emergency Response (HAZWOPER) trained, in accordance with federal, state, and local regulations.

The purpose of this pre-demolition inspection was to locate, inspect, assess, and sample interior and exterior building materials that are expected to be impacted by the demolition activities and determine if they were ACM, LBP, or PCB.

1.3 SITE DESCRIPTION

The Site consists of a two-story commercial structure with a partial basement foundation and CMU and wood framing. The interior finishes include gypsum wallboard systems, drop ceiling systems and various flooring types. The exterior building components consist of wood, brick and a built up roof system.

1.4 METHODOLOGY

The Site was visually inspected for the presence of building materials that were suspected to contain ACM, LBP, and PCBs. Bulk samples of suspect ACM and LBP were collected from the structure and placed into individual containers for transport to a National Voluntary Laboratory Accreditation Program (NVLAP)- accredited laboratory for analysis. Materials typically known as non-asbestos items (i.e., unpainted glass, metal, or wood) were not sampled.

PPM had full access to the Site and all areas that were visually and physically accessible were evaluated as part of this survey. PPM used demolition methods to look within enclosed wall or ceiling cavities during this investigation. PPM did include all suspect materials observed in, on, or associated with the areas expected to be impacted by the

demolition project included in this report with the exception of sampling the roofing system due to lack of safe access.

1.5 ASBESTOS-CONTAINING MATERIALS SURVEY

The asbestos inspection was conducted in accordance with the US EPA AHERA regulations, which also meet the sampling requirements found in the OSHA Construction regulations, 29 CFR 1926.1101, National Emission Standards for Hazardous Air Pollutants (NESHAP) 40 CFR 61 and the Alabama Department of Environmental Management (ADEM) asbestos demolition and renovation operations regulations set forth in Alabama Admin. Code, Chapter 335-3-11.

Samples were handled according to accepted procedures for the collection, packaging, chain-of- custody documentation and transport of bulk samples to the analytical laboratory for analysis using approved methodology.

Under current US EPA guidelines for conducting building inspections for ACM, all “suspect” materials must be assumed to contain asbestos until otherwise determined by laboratory testing. Destructive sampling was conducted to investigate concealed areas and suspect materials in the spaces; however, not all concealed areas with suspect materials have been surveyed (see Limitations).

Actual number of presumed asbestos samples collected from each homogeneous sampling area may vary, based on the type and amount of material, the sampling protocol used listed in Title II of the Federal Toxic Substances Control Act (TSCA) found in 40 CFR Part 763.86, and the professional opinion of the inspector. Asbestos sample locations are located on **Figure 1, Sample Location Map Former Police Station (Main Level)** and **Figure 2, Sample Location Map Former Police Station (Basement Level)** in **Appendix A, Sample Location Maps**.

The condition (e.g., good, fair, poor) and friability (i.e., able to be readily crumbled, pulverized, or reduced to powder by hand pressure) of suspect ACM was noted for each work area. Friability of each sampled material was determined by hand-touch.

Representative bulk samples of suspect ACM were analyzed by EMSL in Baton Rouge, Louisiana in accordance with the US EPA “Method for Determination of Asbestos in Bulk Building Materials” (US EPA/600/R93/116, July 1993). Eurofins is accredited to perform

Polarized Light Microscopy (PLM) analysis through the American Industrial Hygiene Association Laboratory Accreditation Program (AIHA LAP) and NVLAP.

1.6 LEAD BASED PAINT SURVEY

The US EPA defines LBP as any paint with a lead concentration equal to or more than 1.0 milligram per square centimeter (mg/cm^2), 0.5 percent (%) lead by weight for paint chip samples or 5,000 parts per million (ppm). OSHA does not define LBP on content. OSHA defines LCP as any detectable lead in paint for purpose of complying with OSHA regulations to determine worker exposure.

The lead in paint survey was completed and included physical sampling of paint/coatings that were deemed representative of the predominant paint coatings observed within the building. Paints and coatings were collected during this inspection and submitted to EMSL in Baton Rouge, Louisiana to be analyzed by flame atomic absorption spectrometry (FAAS). Eurofins participates in the Environmental Lead Proficiency Analytical Testing (ELPAT) program administered by the AIHA. Materials coated with paint identified to have detectable concentrations of lead are regulated by OSHA.

Pursuant to ASTM International (ASTM) E 1729-05 sub-section 9.2.4, field data was collected to include a unique sample identifier, the sample location, the sample description, sample component, condition of the paint, and color. Paint chip sample locations are located on the sample location map in **Appendix A**.

Pursuant to ASTM E 1729-05 sub-section 7.4.2, using the appropriate cutting tool, paint was scraped down to the substrate within the marked area and collected for analysis. For brick or concrete substrates, the minimum amount needed to completely remove the paint from the substrate was collected. On wood substrates, scraping in the direction of the wood grain was conducted in order to minimize inclusion of the substrate in the collected sample.

1.7 POLYCHLORINATED BIPHENYLS SURVEY

The methodologies and procedures employed during the survey were based on the US EPA inspection protocol. PPM field staff did not identify caulking likely to contain PCBs and therefore did not collect any samples.

2.0 SURVEY INFORMATION AND RESULTS

2.1 ASBESTOS SAMPLING AND ANALYTICAL RESULTS

A total of 76 bulk samples were collected with 148 layers analyzed by PLM during the inspection of the Site located at 201 1st Street North. The results of testing for asbestos during this inspection indicate asbestos is present in the materials listed in the table below:

Sample Number	Location	Homogenous Material	Friable?	Asbestos Content
10, 11, 12	Entry hall of basement floor and air handler closet on main	Grey Duct Work Tape	Yes	80% Chrysotile
16, 17, 18	Main floor NE office, middle office, and hallway under dark brown wood flooring	Black and yellow mastic	No	8% Chrysotile
17, 18	Main floor hallway, middle office main floor (2 nd layer)	Tan floor tile	No	2% Chrysotile
17, 18	Main floor hallway, middle office main floor (under 2 nd layer)	Black mastic	No	8% Chrysotile
25	Main entry at main floor	Tan Herringbone Laminate flooring	No	2% Chrysotile
25	Under tan herringbone laminate flooring	Black and yellow mastic	No	8% Chrysotile
20, 21, 40	Main floor hallway and southeast closet	Tan floor tile	No	2% Chrysotile
20, 21, 40	Under tan floor tile, main floor hallway, and southeast closet	Black mastic	No	8% Chrysotile
48, 49, 50	Under tan tile (2 nd layer), entry and within dispatch office	Black mastic	No	8% Chrysotile
48, 49, 50	Under tan tile/mastic, entry and within dispatch office (3 rd layer of tile in sample)	Grey tile	No	2% Chrysotile
54, 55, 56	Under red/white/blue tile (2 nd layer mastic), SW office, computer room, and plumbing access area in basement	Black mastic	No	8% Chrysotile

Copies of the asbestos sample laboratory analytical report and corresponding chain-of-custody forms are included in **Appendix B, Laboratory Results and Sample Logs**. Photographs are provided in **Appendix C, Photograph Logs**. Inspector accreditations are provided in **Appendix D, Certifications**.

2.2 POLYCHLORINATED BIPHENYLS (PCBS) SAMPLING AND ANALYTICAL RESULTS

PPM staff investigated and did not identify caulking and equipment likely containing PCBs at the Site. Building structures were wood framed or wood framed with cement block foundations. Insulation consisted of fiberglass over the wood framing.

2.3 LEAD PAINT SAMPLING AND ANALYTICAL RESULTS

A total of 13 paint/coating samples were collected from the Site located at 201 1st Street North during this inspection and analyzed by FAAS. Results indicating the presence of lead in the paint chip analysis are listed in the following table:

Sample Number	Material	Location	Condition	Lead Content (% by weight)
L16	Tan Paint	Gutter at west entrance	Poor	0.83
L17	Black Paint	Metal railing and bollards at west entrance	Poor	0.56
L7	Light Green Paint	CMU wall SW closet on main level	Good	0.0064
L15	Multi-Layer/Color Paint	Jail cell walls and floor in basement	Poor	0.057

Paints determined not to contain lead for the purposes of this report are those samples which, when analyzed, did not indicate lead to be present at or above the limit of detection for the analysis method used. As a result, any paints shown not to contain lead will not require any special training or work practices related to lead when impacted during demolition activities.

3.0 CONCLUSIONS AND RECOMMENDATIONS

During any renovation, repair or demolition activity, engineering controls such as barriers and water should be used to minimize dust levels. The public should be prevented from unauthorized access to the work area. Ambient air monitoring should be conducted to document engineering controls that are adequate and that ambient airborne concentrations do not exceed permissible exposure levels during any renovation or demolition activities.

3.1 ASBESTOS REGULATORY INFORMATION

A material is considered by the US EPA and ADEM to be asbestos containing if at least one sample collected from the homogeneous area has asbestos present in concentrations greater than one percent (>1.0%). PPM conducted condition assessments and collected bulk samples of suspect ACMs. The table in **Section 2.1** presents a summary of the laboratory analysis of confirmed ACMs. The results of the survey indicated asbestos was detected in the following materials/locations sampled from the former Police Station located at 201 1st Street North:

- Grey Duct Work Tape – hallway of main floor and air handler closet in basement – 80% Chrysotile
- Black and yellow mastic – main floor NE office, middle office, and hallway under dark brown wood flooring – 8% Chrysotile
- Tan floor tile – main floor hallway and southeast closet – 2% Chrysotile
- Black mastic – under tan floor tile main floor hallway and southeast closet – 8% Chrysotile
- Black mastic – under light brown laminate flooring main floor middle and south hallway – 8% Chrysotile
- Tan Herringbone Laminate flooring – main entry at main floor – 2% Chrysotile
- Black and yellow mastic – under tan herringbone laminate flooring – 8% Chrysotile
- Black mastic – under tan tile (2nd layer) entry and within dispatch office – 8% Chrysotile
- Grey tile – under tan tile/mastic entry and within dispatch office (3rd layer of tile in sample) – 2% Chrysotile
- Black mastic – under red/white/blue tile (2nd layer mastic) SW office, computer room, and plumbing access area in basement – 8% Chrysotile

Regulated Asbestos Containing Material (RACM) is required to be removed in accordance with OSHA, EPA and State of Alabama rules and regulations prior to disturbance from renovation or demolition activities. PPM recommends the asbestos containing materials be abated by a licensed asbestos abatement contractor.

The remaining materials were reported as non-detect for the presence of asbestos and are not regulated and can be removed and disposed of as construction debris. If any additional materials are discovered during renovation activities, these materials must be assumed to contain asbestos until sampling and analysis proves otherwise.

Any contractors or employees working in this building should be made aware of the possibility that concealed asbestos-containing building materials (ACBMs) may be found during demolition/renovation. They should be advised not to disturb known or suspect ACBMs without owner approval. Any concealed building materials discovered during any maintenance or renovation activities, which are suspected to contain asbestos, should be sampled and analyzed to confirm the presence of asbestos prior to disturbing.

The EPA has not prohibited the manufacture and import of miscellaneous materials, such as vinyl floorings, mastics, roofing materials, etc. As a result, any future replacement materials should be checked for the presence of asbestos prior to installation.

3.2 PCBS REGULATORY INFORMATION

The management of PCB-containing materials is regulated by the US EPA TSCA and associated 40 CFR §761 Regulations, as administered by the US EPA. Depending upon PCB concentrations and source, sealants, paints, and building materials with detectable PCBs are classified under TSCA as either PCB Bulk Product Wastes, PCB Remediation Wastes, or Excluded PCB Products.

Since no suspect PCB containing caulking was identified during this inspection, materials associated with this Site are not regulated under TSCA and may be managed as typical demolition debris.

3.3 LEAD REGULATORY INFORMATION

Based on the analytical results, the one paint (white) observed at the Site located at 201 1st Street North was below the method detection limit for lead and, therefore, is not classified as lead-containing by OSHA regulations.

If, however, any hidden paints are discovered that may be affected by planned renovations or demolition activities then they should be tested prior to disturbance.

3.4 FLUORESCENT LIGHT TUBES AND PCB LIGHT BALLASTS

PPM identified fluorescent light tubes, some of which were marked as mercury-containing light bulbs, and potentially PCB containing ballasts throughout both floors of the building. These should be disposed of in accordance with applicable regulations.

3.5 THERMOSTATS WITH MERCURY SWITCHES

PPM identified four thermostats during the survey. It is unknown whether these thermostats contained mercury switches.

3.6 FREON AND FLUOROCARBONS

PPM identified heating, ventilation, and air conditioning (HVAC) equipment at the west side of the building and within the air handler rooms on both floors of the building, which could be potential sources of fluorocarbons during the survey.

4.0 ASSUMPTIONS AND LIMITATIONS

PPM'S survey was limited to the observation, destructive sampling and analysis of suspect ACMs and lead-containing paints in accessible portions of the Site that will be impacted by the upcoming demolition activities. The survey was completed by PPM on December 20, 2025. Common construction techniques render portions of any building inaccessible and, as a result, additional suspect ACMs and/or lead-containing painted surfaces may be present in inaccessible areas (i.e., between walls, enclosed ceiling spaces, interior of metal fire doors, behind mirrors, etc.) and other portions of the building that were not assessed during the survey.

Contractors should use caution during construction-related activities as concealed ACMs and LCPs that were not previously analyzed may be encountered. If materials not sampled during this investigation are later identified to contain regulated quantities of asbestos, then they should be removed and disposed in accordance with federal, state, and local regulations, prior to disturbance. Abatement of ACMs must be performed by a licensed abatement contractor.

This report should not be utilized as a bidding document; it does not have all the components required to serve as an Asbestos Abatement Project Design document or an Abatement Work Plan.

The opinions presented within this report apply to the site conditions existing at the time of PPM's investigation and interpretation of current regulations pertaining to ACMs and LCPs. Therefore, PPM's opinions and recommendations may not apply to future conditions that may exist at the site which we have not had the opportunity to evaluate. All applicable federal, state, and local regulations should be verified prior to any work that will disturb suspect limited hazardous building materials.

If you have any questions regarding this report or require further clarification, please contact our office at (205) 909-1498.

Respectfully Submitted,
PPM Consultants, Inc.

Survey and Report:




Chuck Gooden – Senior Geologist
Email: chuck.gooden@ppmco.com



Joanna Rowlen – Staff Professional
joanna.rowlen@ppmco.com


Review:



Stephanie Pryor - Project Director
Email: stephanie.pryor@ppmco.com

APPENDICES

APPENDIX A – SAMPLE LOCATION MAPS



NOT TO SCALE



LEGEND:


- ⊗ NEGATIVE ASBESTOS SAMPLE LOCATION
- ⊗ POSITIVE ASBESTOS SAMPLE LOCATION
- NEGATIVE LBP SAMPLE LOCATION

PPM PPM CONSULTANTS, INC. www.ppmco.com	
DRAWN BY: MRS	DRAWN DATE: 01/29/26
PROJECT NUMBER: 40024103	PHASE: HM


**CITY OF ALABASTER
FORMER POLICE STATION**
201 1ST STREET NORTH
ALABASTER, ALABAMA

**SAMPLE LOCATION MAP FORMER POLICE STATION
(MAIN LEVEL)**

FIGURE
NUMBER
1



NOT TO SCALE



LEGEND:

- ⊗ NEGATIVE ASBESTOS SAMPLE LOCATION
- ⊗ POSITIVE ASBESTOS SAMPLE LOCATION
- NEGATIVE LBP SAMPLE LOCATION
- POSITIVE LBP SAMPLE LOCATION

PPM PPM CONSULTANTS, INC. www.ppmco.com	
DRAWN BY: MRS	DRAWN DATE: 01/29/26
PROJECT NUMBER: 40024103	PHASE: HM

**CITY OF ALABASTER
FORMER POLICE STATION**
201 1ST STREET NORTH
ALABASTER, ALABAMA

**SAMPLE LOCATION MAP FORMER POLICE STATION
(BASEMENT LEVEL)**

FIGURE NUMBER

2

APPENDIX B – LABORATORY RESULTS AND SAMPLE LOGS



EMSL Analytical, Inc.

18369 Petroleum Drive Baton Rouge, LA 70809

Tel/Fax: (225) 755-1920 / (225) 755-1989

<http://www.EMSL.com/batonrougelab@emsl.com>

EMSL Order: 252600081

Customer ID: PPMC25

Customer PO: 40024103

Project ID:

Attention: Chuck Gooden
PPM Consultants, Inc.
5555 Bankhead Highway
Birmingham, AL 35210

Phone: (205) 836-5650

Fax:

Received Date: 01/09/2026 9:50 AM

Analysis Date: 01/13/2026 - 01/14/2026

Collected Date: 01/08/2026

Project: City of Alabaster Former Police Station

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
1 252600081-0001	NE Office-Main Floor - White Ceiling Tile-Wormhole	Gray/White Fibrous Homogeneous	45% Cellulose 15% Glass	40% Non-fibrous (Other)	None Detected
2 252600081-0002	Hallway-Main Floor - White Ceiling Tile-Wormhole	Gray/White Fibrous Homogeneous	45% Cellulose 15% Glass	40% Non-fibrous (Other)	None Detected
3 252600081-0003	SW Office-Main Floor - White Ceiling Tile-Wormhole	Gray/White Fibrous Homogeneous	45% Cellulose 15% Glass	40% Non-fibrous (Other)	None Detected
4 252600081-0004	NE Office-Main Floor - White Ceiling Tile-Round Hole	Gray/Tan Fibrous Homogeneous	45% Cellulose 15% Glass	40% Non-fibrous (Other)	None Detected
5 252600081-0005	Hallway-Main Floor - White Ceiling Tile-Round Hole	Gray/Tan Fibrous Homogeneous	45% Cellulose 15% Glass	40% Non-fibrous (Other)	None Detected
6 252600081-0006	SW Office-Main Floor - White Ceiling Tile-Round Hole	Gray/White Fibrous Homogeneous	45% Cellulose 15% Glass	40% Non-fibrous (Other)	None Detected
7-Texture 252600081-0007	NE Office-Main Floor - White Sheetrock-joint Compound	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
7-Joint Compound 252600081-0007A	NE Office-Main Floor - White Sheetrock-joint Compound				Insufficient Material
7-Sheetrock 252600081-0007B	NE Office-Main Floor - White Sheetrock-joint Compound	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
8-Texture 252600081-0008	Hallway-Main Floor - White Sheetrock-joint Compound				Insufficient Material
8-Joint Compound 252600081-0008A	Hallway-Main Floor - White Sheetrock-joint Compound				Layer Not Present
8-Sheetrock 252600081-0008B	Hallway-Main Floor - White Sheetrock-joint Compound	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
9-Texture 252600081-0009	SW Office-Main Floor - White Sheetrock-joint Compound	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
9-Joint Compound 252600081-0009A	SW Office-Main Floor - White Sheetrock-joint Compound	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 01/16/2026 15:07:19



EMSL Analytical, Inc.

18369 Petroleum Drive Baton Rouge, LA 70809

Tel/Fax: (225) 755-1920 / (225) 755-1989

<http://www.EMSL.com/batonrougelab@emsl.com>

EMSL Order: 252600081
Customer ID: PPMC25
Customer PO: 40024103
Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
9-Sheetrock 252600081-0009B	SW Office-Main Floor - White Sheetrock-joint Compound	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
10 252600081-0010	Hallway-Main Floor - Gray Duct Work Tape	Gray Fibrous Homogeneous		20% Non-fibrous (Other)	80% Chrysotile
11 252600081-0011	Air Handler Closet-Basement - Gray Duct Work Tape				Positive Stop (Not Analyzed)
12 252600081-0012	Air Handler Closet-Basement - Gray Duct Work Tape				Positive Stop (Not Analyzed)
13 252600081-0013	Office North of Foyer - White Ceiling Tile-Pock	Tan/White Fibrous Homogeneous	45% Cellulose 15% Glass	40% Non-fibrous (Other)	None Detected
14 252600081-0014	Office North of Foyer - White Ceiling Tile-Pock	Tan/White Fibrous Homogeneous	45% Cellulose 15% Glass	40% Non-fibrous (Other)	None Detected
15 252600081-0015	Office North of Foyer - White Ceiling Tile-Pock	Gray/White Fibrous Homogeneous	45% Cellulose 15% Glass	40% Non-fibrous (Other)	None Detected
16-Flooring 252600081-0016	NE Office-Main Floor - Dark Brown Wood Floor-Black Mastic	Brown/Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
16-Mastic 1 252600081-0016A	NE Office-Main Floor - Dark Brown Wood Floor-Black Mastic	Black/Yellow Non-Fibrous Homogeneous		92% Non-fibrous (Other)	8% Chrysotile
16-Floor Tile 252600081-0016B	NE Office-Main Floor - Dark Brown Wood Floor-Black Mastic				Layer Not Present
16-Mastic 2 252600081-0016C	NE Office-Main Floor - Dark Brown Wood Floor-Black Mastic				Layer Not Present
16-Leveler 252600081-0016D	NE Office-Main Floor - Dark Brown Wood Floor-Black Mastic	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
17-Flooring 252600081-0017	Hallway-Main Floor - Dark Brown Wood Floor-Black Mastic	Brown/Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
17-Mastic 1 252600081-0017A	Hallway-Main Floor - Dark Brown Wood Floor-Black Mastic				Positive Stop (Not Analyzed)
17-Floor Tile 252600081-0017B	Hallway-Main Floor - Dark Brown Wood Floor-Black Mastic	Tan Non-Fibrous Homogeneous		98% Non-fibrous (Other)	2% Chrysotile
17-Mastic 2 252600081-0017C	Hallway-Main Floor - Dark Brown Wood Floor-Black Mastic	Black Non-Fibrous Homogeneous		92% Non-fibrous (Other)	8% Chrysotile
17-Leveler 252600081-0017D	Hallway-Main Floor - Dark Brown Wood Floor-Black Mastic	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
18-Flooring 252600081-0018	Middle Office-Main Floor - Dark Brown Wood Floor-Black Mastic	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 01/16/2026 15:07:19



EMSL Analytical, Inc.

18369 Petroleum Drive Baton Rouge, LA 70809

Tel/Fax: (225) 755-1920 / (225) 755-1989

<http://www.EMSL.com> / batonrougelab@emsl.com

EMSL Order: 252600081
Customer ID: PPMC25
Customer PO: 40024103
Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
18-Mastic 1 252600081-0018A	Middle Office-Main Floor - Dark Brown Wood Floor-Black Mastic				Positive Stop (Not Analyzed)
18-Floor Tile 252600081-0018B	Middle Office-Main Floor - Dark Brown Wood Floor-Black Mastic				Positive Stop (Not Analyzed)
18-Mastic 2 252600081-0018C	Middle Office-Main Floor - Dark Brown Wood Floor-Black Mastic				Positive Stop (Not Analyzed)
18-Leveler 252600081-0018D	Middle Office-Main Floor - Dark Brown Wood Floor-Black Mastic				Layer Not Present
19-Flooring 252600081-0019	Hallway-Main Floor - Light Brown Laminate Flooring-Mastic	Brown/Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19-Mastic 252600081-0019A	Hallway-Main Floor - Light Brown Laminate Flooring-Mastic	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
20-Flooring 252600081-0020	Middle Hallway-Main Floor - Light Brown Laminate Flooring-Mastic	Brown/Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
20-Mastic 252600081-0020A	Middle Hallway-Main Floor - Light Brown Laminate Flooring-Mastic	Black Non-Fibrous Homogeneous		92% Non-fibrous (Other)	8% Chrysotile
21-Flooring 252600081-0021	South Hallway-Main Floor - Light Brown Laminate Flooring-Mastic	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
21-Mastic 252600081-0021A	South Hallway-Main Floor - Light Brown Laminate Flooring-Mastic				Positive Stop (Not Analyzed)
22-Ceramic Tile 252600081-0022	Mens RR-Main Floor - Brown Tile-Gray Mortar	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
22-Mortar 252600081-0022A	Mens RR-Main Floor - Brown Tile-Gray Mortar	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
23-Ceramic Tile 252600081-0023	Womens RR-Main Floor - Brown Tile-Gray Mortar	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
23-Mortar 252600081-0023A	Womens RR-Main Floor - Brown Tile-Gray Mortar	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
24-Ceramic Tile 252600081-0024	Womens RR-Main Floor - Brown Tile-Gray Mortar	Red Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
24-Mortar 252600081-0024A	Womens RR-Main Floor - Brown Tile-Gray Mortar	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 01/16/2026 15:07:19



EMSL Analytical, Inc.

18369 Petroleum Drive Baton Rouge, LA 70809

Tel/Fax: (225) 755-1920 / (225) 755-1989

<http://www.EMSL.com/batonrougelab@emsl.com>

EMSL Order: 252600081
Customer ID: PPMC25
Customer PO: 40024103
Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
25-Flooring 252600081-0025	Main Entry-Main Floor - Tan Laminate Flooring-Black Mastic-Herringbone Pattern	Brown/Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
25-Mastic 1 252600081-0025A	Main Entry-Main Floor - Tan Laminate Flooring-Black Mastic-Herringbone Pattern	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
25-Floor Tile 252600081-0025B	Main Entry-Main Floor - Tan Laminate Flooring-Black Mastic-Herringbone Pattern	Tan Non-Fibrous Homogeneous		98% Non-fibrous (Other)	2% Chrysotile
25-Mastic 2 252600081-0025C	Main Entry-Main Floor - Tan Laminate Flooring-Black Mastic-Herringbone Pattern	Black Non-Fibrous Homogeneous		92% Non-fibrous (Other)	8% Chrysotile
25-Leveler 252600081-0025D	Main Entry-Main Floor - Tan Laminate Flooring-Black Mastic-Herringbone Pattern				Insufficient Material
26-Flooring 252600081-0026	Main Entry-Main Floor - Tan Laminate Flooring-Black Mastic-Herringbone Pattern	Brown/Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
26-Mastic 1 252600081-0026A	Main Entry-Main Floor - Tan Laminate Flooring-Black Mastic-Herringbone Pattern	Black/Yellow Non-Fibrous Homogeneous		92% Non-fibrous (Other)	8% Chrysotile
26-Floor Tile 252600081-0026B	Main Entry-Main Floor - Tan Laminate Flooring-Black Mastic-Herringbone Pattern				Positive Stop (Not Analyzed)
26-Mastic 2 252600081-0026C	Main Entry-Main Floor - Tan Laminate Flooring-Black Mastic-Herringbone Pattern				Positive Stop (Not Analyzed)
26-Leveler 252600081-0026D	Main Entry-Main Floor - Tan Laminate Flooring-Black Mastic-Herringbone Pattern	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
27-Flooring 252600081-0027	Main Entry-Main Floor - Tan Laminate Flooring-Black Mastic-Herringbone Pattern	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
27-Mastic 1 252600081-0027A	Main Entry-Main Floor - Tan Laminate Flooring-Black Mastic-Herringbone Pattern				Positive Stop (Not Analyzed)

Initial report from: 01/16/2026 15:07:19



EMSL Analytical, Inc.

18369 Petroleum Drive Baton Rouge, LA 70809

Tel/Fax: (225) 755-1920 / (225) 755-1989

<http://www.EMSL.com> / batonrougelab@emsl.com

EMSL Order: 252600081
Customer ID: PPMC25
Customer PO: 40024103
Project ID:

**Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E
Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
27-Floor Tile 252600081-0027B	Main Entry-Main Floor - Tan Laminate Flooring-Black Mastic-Herringbone Pattern				Positive Stop (Not Analyzed)
27-Mastic 2 252600081-0027C	Main Entry-Main Floor - Tan Laminate Flooring-Black Mastic-Herringbone Pattern				Positive Stop (Not Analyzed)
27-Leveler 252600081-0027D	Main Entry-Main Floor - Tan Laminate Flooring-Black Mastic-Herringbone Pattern				Layer Not Present
28 252600081-0028	Mens RR-Main Floor - White Ceiling Tile-Long Wormhole	Tan/White Fibrous Homogeneous	45% Cellulose 15% Glass	40% Non-fibrous (Other)	None Detected
29 252600081-0029	Mens RR-Main Floor - White Ceiling Tile-Long Wormhole	Tan/White Fibrous Homogeneous	45% Cellulose 15% Glass	40% Non-fibrous (Other)	None Detected
30 252600081-0030	Womens RR-Main Floor - White Ceiling Tile-Long Wormhole	Gray/White Fibrous Homogeneous	45% Cellulose 15% Glass	40% Non-fibrous (Other)	None Detected
31 252600081-0031	Air Handler-Main Floor - Silver Duct Tape	Silver Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
32 252600081-0032	Air Handler Basement - Silver Duct Tape	Silver Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
33 252600081-0033	Air Handler Basement - Silver Duct Tape	Silver Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
34 252600081-0034	East Side Office - Green Wallpaper-White Mastic	White/Green Fibrous Homogeneous	98% Cellulose	2% Non-fibrous (Other)	None Detected
35 252600081-0035	East Side Office - Green Wallpaper-White Mastic	White/Green Fibrous Homogeneous	98% Cellulose	2% Non-fibrous (Other)	None Detected
36 252600081-0036	East Side Office - Green Wallpaper-White Mastic	White/Green Fibrous Homogeneous	98% Cellulose	2% Non-fibrous (Other)	None Detected
37 252600081-0037	Basement-Hallway - White Ceiling Tile-WormHole (B)	Gray/White Fibrous Homogeneous	45% Cellulose 15% Glass	40% Non-fibrous (Other)	None Detected
38 252600081-0038	Basement-Booking - White Ceiling Tile-WormHole (B)	Gray/White Fibrous Homogeneous	45% Cellulose 15% Glass	40% Non-fibrous (Other)	None Detected
39 252600081-0039	Basement-North Day Room - White Ceiling Tile-WormHole (B)	Gray/White Fibrous Homogeneous	45% Cellulose 15% Glass	40% Non-fibrous (Other)	None Detected
40-Floor Tile 252600081-0040	SE Closet-Main Floor - Tan Floor Tile-Black Mastic	Tan Non-Fibrous Homogeneous		98% Non-fibrous (Other)	2% Chrysotile

Initial report from: 01/16/2026 15:07:19



EMSL Analytical, Inc.

18369 Petroleum Drive Baton Rouge, LA 70809

Tel/Fax: (225) 755-1920 / (225) 755-1989

<http://www.EMSL.com/batonrougelab@emsl.com>

EMSL Order: 252600081
Customer ID: PPMC25
Customer PO: 40024103
Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
40-Mastic <small>252600081-0040A</small>	SE Closet-Main Floor - Tan Floor Tile-Black Mastic	Black Non-Fibrous Homogeneous		92% Non-fibrous (Other)	8% Chrysotile
40-Leveler <small>252600081-0040B</small>	SE Closet-Main Floor - Tan Floor Tile-Black Mastic	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
41 <small>252600081-0041</small>	Stairwell - Ceiling Tile-White-Textured	Tan/White Fibrous Homogeneous	45% Cellulose 15% Glass	40% Non-fibrous (Other)	None Detected
42 <small>252600081-0042</small>	Stairwell - Ceiling Tile-White-Textured	Tan/White Fibrous Homogeneous	45% Cellulose 15% Glass	40% Non-fibrous (Other)	None Detected
43 <small>252600081-0043</small>	Stairwell - Ceiling Tile-White-Textured	Tan/White Fibrous Homogeneous	45% Cellulose 15% Glass	40% Non-fibrous (Other)	None Detected
44-Stair Tread <small>252600081-0044</small>	Top Stair - Black Stair Tread-Mastic	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
44-Mastic <small>252600081-0044A</small>	Top Stair - Black Stair Tread-Mastic	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
45-Stair Tread <small>252600081-0045</small>	Stair Case Landing - Black Stair Tread-Mastic	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
45-Mastic <small>252600081-0045A</small>	Stair Case Landing - Black Stair Tread-Mastic	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
46-Stair Tread <small>252600081-0046</small>	Bottom Stair - Black Stair Tread-Mastic	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
46-Mastic <small>252600081-0046A</small>	Bottom Stair - Black Stair Tread-Mastic	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
47-Carpet <small>252600081-0047</small>	Stairwell - Black Carpet-Tan Mastic	Gray/Blue Fibrous Homogeneous	98% Synthetic	2% Non-fibrous (Other)	None Detected
47-Mastic <small>252600081-0047A</small>	Stairwell - Black Carpet-Tan Mastic	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
48-Floor Tile 1 <small>252600081-0048</small>	Entry to Dispatch Office - MultiLayer-Tile-Black Mastic	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
48-Mastic 1 <small>252600081-0048A</small>	Entry to Dispatch Office - MultiLayer-Tile-Black Mastic	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
48-Floor Tile 2 <small>252600081-0048B</small>	Entry to Dispatch Office - MultiLayer-Tile-Black Mastic	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
48-Mastic 2 <small>252600081-0048C</small>	Entry to Dispatch Office - MultiLayer-Tile-Black Mastic	Black Non-Fibrous Homogeneous		92% Non-fibrous (Other)	8% Chrysotile

Initial report from: 01/16/2026 15:07:19



EMSL Analytical, Inc.

18369 Petroleum Drive Baton Rouge, LA 70809

Tel/Fax: (225) 755-1920 / (225) 755-1989

<http://www.EMSL.com> / batonrougelab@emsl.com

EMSL Order: 252600081
Customer ID: PPMC25
Customer PO: 40024103
Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
48-Floor Tile 3 252600081-0048D	Entry to Dispatch Office - MultiLayer-Tile-Black Mastic	Gray Non-Fibrous Homogeneous		98% Non-fibrous (Other)	2% Chrysotile
48-Mastic 3 252600081-0048E	Entry to Dispatch Office - MultiLayer-Tile-Black Mastic				Insufficient Material
48-Floor Tile 4 252600081-0048F	Entry to Dispatch Office - MultiLayer-Tile-Black Mastic				Layer Not Present
48-Mastic 4 252600081-0048G	Entry to Dispatch Office - MultiLayer-Tile-Black Mastic				Layer Not Present
48-Leveler 252600081-0048H	Entry to Dispatch Office - MultiLayer-Tile-Black Mastic	Gray/Red Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
49-Floor Tile 1 252600081-0049	NE Corner Dispatch Office - MultiLayer-Tile-Black Mastic	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
49-Mastic 1 252600081-0049A	NE Corner Dispatch Office - MultiLayer-Tile-Black Mastic	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
49-Floor Tile 2 252600081-0049B	NE Corner Dispatch Office - MultiLayer-Tile-Black Mastic	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
49-Mastic 2 252600081-0049C	NE Corner Dispatch Office - MultiLayer-Tile-Black Mastic				Positive Stop (Not Analyzed)
49-Floor Tile 3 252600081-0049D	NE Corner Dispatch Office - MultiLayer-Tile-Black Mastic				Positive Stop (Not Analyzed)
49-Mastic 3 252600081-0049E	NE Corner Dispatch Office - MultiLayer-Tile-Black Mastic	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
49-Floor Tile 4 252600081-0049F	NE Corner Dispatch Office - MultiLayer-Tile-Black Mastic	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
49-Mastic 4 252600081-0049G	NE Corner Dispatch Office - MultiLayer-Tile-Black Mastic	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
49-Leveler 252600081-0049H	NE Corner Dispatch Office - MultiLayer-Tile-Black Mastic	Gray/Red Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 01/16/2026 15:07:19



EMSL Analytical, Inc.

18369 Petroleum Drive Baton Rouge, LA 70809

Tel/Fax: (225) 755-1920 / (225) 755-1989

<http://www.EMSL.com/batonrougelab@emsl.com>

EMSL Order: 252600081
Customer ID: PPMC25
Customer PO: 40024103
Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
50-Floor Tile 1 252600081-0050	SE Corner-Dispatch Office - MultiLayer-Tile-Black Mastic	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
50-Mastic 1 252600081-0050A	SE Corner-Dispatch Office - MultiLayer-Tile-Black Mastic	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
50-Floor Tile 2 252600081-0050B	SE Corner-Dispatch Office - MultiLayer-Tile-Black Mastic	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
50-Mastic 2 252600081-0050C	SE Corner-Dispatch Office - MultiLayer-Tile-Black Mastic				Positive Stop (Not Analyzed)
50-Floor Tile 3 252600081-0050D	SE Corner-Dispatch Office - MultiLayer-Tile-Black Mastic				Positive Stop (Not Analyzed)
50-Mastic 3 252600081-0050E	SE Corner-Dispatch Office - MultiLayer-Tile-Black Mastic				Layer Not Present
50-Floor Tile 4 252600081-0050F	SE Corner-Dispatch Office - MultiLayer-Tile-Black Mastic	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
50-Mastic 4 252600081-0050G	SE Corner-Dispatch Office - MultiLayer-Tile-Black Mastic				Insufficient Material
50-Leveler 252600081-0050H	SE Corner-Dispatch Office - MultiLayer-Tile-Black Mastic	Gray/Red Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
51-Floor Tile 252600081-0051	Basement Bathroom - Brown Tile-Underlain by Red Tile-Mastic	Brown/Gray/White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
51-Mastic 252600081-0051A	Basement Bathroom - Brown Tile-Underlain by Red Tile-Mastic	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
51-Leveler 252600081-0051B	Basement Bathroom - Brown Tile-Underlain by Red Tile-Mastic	Gray/Red Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
52-Floor Tile 252600081-0052	Basement Bathroom - Brown Tile-Underlain by Red Tile-Mastic	Brown/Gray/White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
52-Mastic 252600081-0052A	Basement Bathroom - Brown Tile-Underlain by Red Tile-Mastic	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
52-Leveler 252600081-0052B	Basement Bathroom - Brown Tile-Underlain by Red Tile-Mastic	Gray/Red Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
53-Floor Tile 252600081-0053	Basement Bathroom - Brown Tile-Underlain by Red Tile-Mastic	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 01/16/2026 15:07:19



EMSL Analytical, Inc.

18369 Petroleum Drive Baton Rouge, LA 70809

Tel/Fax: (225) 755-1920 / (225) 755-1989

<http://www.EMSL.com> / batonrougelab@emsl.com

EMSL Order: 252600081
Customer ID: PPMC25
Customer PO: 40024103
Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
53-Mastic <i>252600081-0053A</i>	Basement Bathroom - Brown Tile-Underlain by Red Tile-Mastic	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
53-Leveler <i>252600081-0053B</i>	Basement Bathroom - Brown Tile-Underlain by Red Tile-Mastic	Gray/Red Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
54-Floor Tile 1 <i>252600081-0054</i>	Plumbing Access-Basement - Tile-Multilayer-Mastic	White/Red/Blue Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
54-Mastic 1 <i>252600081-0054A</i>	Plumbing Access-Basement - Tile-Multilayer-Mastic	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
54-Floor Tile 2 <i>252600081-0054B</i>	Plumbing Access-Basement - Tile-Multilayer-Mastic	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
54-Mastic 2 <i>252600081-0054C</i>	Plumbing Access-Basement - Tile-Multilayer-Mastic	Black Non-Fibrous Homogeneous		92% Non-fibrous (Other)	8% Chrysotile
54-Floor Tile 3 <i>252600081-0054D</i>	Plumbing Access-Basement - Tile-Multilayer-Mastic	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
54-Mastic 3 <i>252600081-0054E</i>	Plumbing Access-Basement - Tile-Multilayer-Mastic	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
54-Leveler <i>252600081-0054F</i>	Plumbing Access-Basement - Tile-Multilayer-Mastic	Gray/Red Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
55-Floor Tile 1 <i>252600081-0055</i>	SW Office - Tile-Multilayer-Mastic	White/Red/Blue Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
55-Mastic 1 <i>252600081-0055A</i>	SW Office - Tile-Multilayer-Mastic				Insufficient Material
55-Floor Tile 2 <i>252600081-0055B</i>	SW Office - Tile-Multilayer-Mastic				Layer Not Present
55-Mastic 2 <i>252600081-0055C</i>	SW Office - Tile-Multilayer-Mastic				Layer Not Present
55-Floor Tile 3 <i>252600081-0055D</i>	SW Office - Tile-Multilayer-Mastic				Layer Not Present
55-Mastic 3 <i>252600081-0055E</i>	SW Office - Tile-Multilayer-Mastic				Layer Not Present
55-Leveler <i>252600081-0055F</i>	SW Office - Tile-Multilayer-Mastic	Gray/Red Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
56-Floor Tile 1 <i>252600081-0056</i>	Computer Room - Tile-Multilayer-Mastic	White/Red/Blue Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
56-Mastic 1 <i>252600081-0056A</i>	Computer Room - Tile-Multilayer-Mastic	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
56-Floor Tile 2 <i>252600081-0056B</i>	Computer Room - Tile-Multilayer-Mastic				Layer Not Present

Initial report from: 01/16/2026 15:07:19



EMSL Analytical, Inc.

18369 Petroleum Drive Baton Rouge, LA 70809

Tel/Fax: (225) 755-1920 / (225) 755-1989

<http://www.EMSL.com> / batonrougelab@emsl.com

EMSL Order: 252600081
Customer ID: PPMC25
Customer PO: 40024103
Project ID:

**Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E
Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
56-Mastic 2 <i>252600081-0056C</i>	Computer Room - Tile-Multilayer-Mastic				Positive Stop (Not Analyzed)
56-Floor Tile 3 <i>252600081-0056D</i>	Computer Room - Tile-Multilayer-Mastic				Layer Not Present
56-Mastic 3 <i>252600081-0056E</i>	Computer Room - Tile-Multilayer-Mastic				Layer Not Present
56-Leveler <i>252600081-0056F</i>	Computer Room - Tile-Multilayer-Mastic				Layer Not Present
57-Carpet <i>252600081-0057</i>	Middle of Day Room - Carpet-Mastic	Brown Fibrous Homogeneous	98% Synthetic	2% Non-fibrous (Other)	None Detected
57-Mastic <i>252600081-0057A</i>	Middle of Day Room - Carpet-Mastic	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
57-Padding <i>252600081-0057B</i>	Middle of Day Room - Carpet-Mastic	Gray/Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
58-Carpet <i>252600081-0058</i>	Day room entry - Carpet-Mastic	Brown Fibrous Homogeneous	98% Synthetic	2% Non-fibrous (Other)	None Detected
58-Mastic <i>252600081-0058A</i>	Day room entry - Carpet-Mastic	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
58-Padding <i>252600081-0058B</i>	Day room entry - Carpet-Mastic	Gray/Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
59-Carpet <i>252600081-0059</i>	Computer Room Entry - Carpet-Mastic	Tan Fibrous Homogeneous	98% Synthetic	2% Non-fibrous (Other)	None Detected
59-Mastic <i>252600081-0059A</i>	Computer Room Entry - Carpet-Mastic	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
59-Padding <i>252600081-0059B</i>	Computer Room Entry - Carpet-Mastic	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
60-Carpet <i>252600081-0060</i>	Investigation Office - Blue Carpet	Blue Fibrous Homogeneous	98% Synthetic	2% Non-fibrous (Other)	None Detected
60-Mastic <i>252600081-0060A</i>	Investigation Office - Blue Carpet	White/Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
61-Carpet <i>252600081-0061</i>	Chief Office - Brown Multi Color Carpet-Padding	Brown Fibrous Homogeneous	98% Synthetic	2% Non-fibrous (Other)	None Detected
61-Mastic <i>252600081-0061A</i>	Chief Office - Brown Multi Color Carpet-Padding	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
61-Padding <i>252600081-0061B</i>	Chief Office - Brown Multi Color Carpet-Padding	Yellow/Green Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 01/16/2026 15:07:19



EMSL Analytical, Inc.

18369 Petroleum Drive Baton Rouge, LA 70809

Tel/Fax: (225) 755-1920 / (225) 755-1989

<http://www.EMSL.com> / batonrougelab@emsl.com

EMSL Order: 252600081
Customer ID: PPMC25
Customer PO: 40024103
Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
62-Carpet 1 252600081-0062	Adjacent to Chiefs Office - Brown Multi Color Carpet-Padding and blue carpet with mastic	Brown Fibrous Homogeneous	98% Synthetic	2% Non-fibrous (Other)	None Detected
62-Mastic 1 252600081-0062A	Adjacent to Chiefs Office - Brown Multi Color Carpet-Padding and blue carpet with mastic	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
62-Padding 252600081-0062B	Adjacent to Chiefs Office - Brown Multi Color Carpet-Padding and blue carpet with mastic	Yellow/Green Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
62-Carpet 2 252600081-0062C	Adjacent to Chiefs Office - Brown Multi Color Carpet-Padding and blue carpet with mastic	Blue Fibrous Homogeneous	98% Synthetic	2% Non-fibrous (Other)	None Detected
62-Mastic 2 252600081-0062D	Adjacent to Chiefs Office - Brown Multi Color Carpet-Padding and blue carpet with mastic	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
63-Carpet 1 252600081-0063	Lieutenants Office - Brown Multi Color Carpet-Padding	Brown Fibrous Homogeneous	98% Synthetic	2% Non-fibrous (Other)	None Detected
63-Mastic 1 252600081-0063A	Lieutenants Office - Brown Multi Color Carpet-Padding	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
63-Padding 252600081-0063B	Lieutenants Office - Brown Multi Color Carpet-Padding	Yellow/Green Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
63-Carpet 2 252600081-0063C	Lieutenants Office - Brown Multi Color Carpet-Padding	Blue Fibrous Homogeneous	98% Synthetic	2% Non-fibrous (Other)	None Detected
63-Mastic 2 252600081-0063D	Lieutenants Office - Brown Multi Color Carpet-Padding	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
64 252600081-0064	Compter Room - CMU and mortar	Gray Non-Fibrous Heterogeneous		100% Non-fibrous (Other)	None Detected
65 252600081-0065	Booking - CMU and mortar	Gray Non-Fibrous Heterogeneous		100% Non-fibrous (Other)	None Detected
66 252600081-0066	South Entry - CMU and mortar	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
67-Ceramic Tile 252600081-0067	Cell Shower - White Tile-Mortar	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
67-Mortar 252600081-0067A	Cell Shower - White Tile-Mortar	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
68-Brick 252600081-0068	Exterior-West Entry - Red Brick and Mortar	Red Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 01/16/2026 15:07:19



EMSL Analytical, Inc.

18369 Petroleum Drive Baton Rouge, LA 70809
Tel/Fax: (225) 755-1920 / (225) 755-1989
[http://www.EMSL.com / batonrougelab@emsl.com](http://www.EMSL.com/batonrougelab@emsl.com)

EMSL Order: 252600081
Customer ID: PPMC25
Customer PO: 40024103
Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
68-Mortar <i>252600081-0068A</i>	Exterior-West Entry - Red Brick and Mortar	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
69-Brick <i>252600081-0069</i>	Exterior-Main Entry - Red Brick and Mortar	Red Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
69-Mortar <i>252600081-0069A</i>	Exterior-Main Entry - Red Brick and Mortar	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
70-Brick <i>252600081-0070</i>	Exterior-NE Corner - Red Brick and Mortar	Red Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
70-Mortar <i>252600081-0070A</i>	Exterior-NE Corner - Red Brick and Mortar	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
71 <i>252600081-0071</i>	South Front-Exterior - Black Window Caulk	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
72 <i>252600081-0072</i>	Back Exterior Mid Building - Black Window Caulk	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
73 <i>252600081-0073</i>	N Front Exterior - Black Window Caulk	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
74 <i>252600081-0074</i>	South Front Exterior - Grey Caulk	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
75 <i>252600081-0075</i>	N Front-Exterior - Grey Caulk	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
76 <i>252600081-0076</i>	Back N End - Grey Caulk	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Analyst(s) _____

Brett Fairchild (36)
Bailey Gunter (112)

Martiana Beach, Laboratory Manager
or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is available on request.

Samples analyzed by EMSL Analytical, Inc. Baton Rouge, LA NVLAP Lab Code 200375-0, LELAP 01950, TX 300238

Initial report from: 01/16/2026 15:07:19



EMSL Analytical, Inc.

18369 Petroleum Drive, Baton Rouge, LA, 70809
Telephone: (225)-755-1920 Fax:(225)-755-1989
www.emsl.com

EMSL Order ID: 252650021
LIMS Reference ID: PE50021
EMSL Customer ID: PPMC25

Attention: Chuck Gooden
PPM Consultants, Inc. [PPMC25]
5555 Bankhead Highway
Birmingham, AL 35210
(205) 836-5650
chuck.gooden@ppmco.com

Project Name: City of Alabaster Former Police Station

Customer PO: 40024103
EMSL Sales Rep: Natalie Murphy
Received: 01/09/2026 09:50
Reported: 01/16/2026 12:54

Analytical Results

Analyte	Results	RL	Weight(g)	Prep Date & Tech	Prep Method	Analysis Date & Analyst	Analytical Method	Q	DF
Client Sample ID: L1/Tan paint -Sheetrock							Date Sampled: 01/08/26		
Matrix: Chips							LIMS Reference ID: PE50021-01		
Lead	<0.0064 % wt	0.0064 % wt	0.2584	01/16/26 B.F.	SW-846 3050B	01/16/26 B.F.	SW 846-7000B	1	
Sample Comments:									
Client Sample ID: L2/White Trim Pain							Date Sampled: 01/08/26		
Matrix: Chips							LIMS Reference ID: PE50021-02		
Lead	<0.012 % wt	0.012 % wt	0.1288	01/16/26 B.F.	SW-846 3050B	01/16/26 B.F.	SW 846-7000B	1	
Sample Comments:									
Client Sample ID: L3/Pink - Sheetrock							Date Sampled: 01/08/26		
Matrix: Chips							LIMS Reference ID: PE50021-03		
Lead	<0.0064 % wt	0.0064 % wt	0.2513	01/16/26 B.F.	SW-846 3050B	01/16/26 B.F.	SW 846-7000B	1	
Sample Comments:									
Client Sample ID: L4/Dark Green Paint							Date Sampled: 01/08/26		
Matrix: Chips							LIMS Reference ID: PE50021-04		
Lead	<0.0064 % wt	0.0064 % wt	0.254	01/16/26 B.F.	SW-846 3050B	01/16/26 B.F.	SW 846-7000B	1	
Sample Comments:									
Client Sample ID: L5/Blue Paneling							Date Sampled: 01/08/26		
Matrix: Chips							LIMS Reference ID: PE50021-05		
Lead	<0.0064 % wt	0.0064 % wt	0.2518	01/16/26 B.F.	SW-846 3050B	01/16/26 B.F.	SW 846-7000B	1	
Sample Comments:									
Client Sample ID: L6/Ligth Tan Sheetrock							Date Sampled: 01/08/26		
Matrix: Chips							LIMS Reference ID: PE50021-06		
Lead	<0.0064 % wt	0.0064 % wt	0.2547	01/16/26 B.F.	SW-846 3050B	01/16/26 B.F.	SW 846-7000B	1	
Sample Comments:									
Client Sample ID: L7/Light Green CMU							Date Sampled: 01/08/26		
Matrix: Chips							LIMS Reference ID: PE50021-07		
Lead	0.0064 % wt	0.0064 % wt	0.2536	01/16/26 B.F.	SW-846 3050B	01/16/26 B.F.	SW 846-7000B	1	
Sample Comments:									
Client Sample ID: L9/Green Paint							Date Sampled: 01/08/26		
Matrix: Chips							LIMS Reference ID: PE50021-09		
Lead	<0.0064 % wt	0.0064 % wt	0.2486	01/16/26 B.F.	SW-846 3050B	01/16/26 B.F.	SW 846-7000B	1	
Sample Comments:									
Client Sample ID: L10/Cream Paint							Date Sampled: 01/08/26		
Matrix: Chips							LIMS Reference ID: PE50021-10		
Lead	<0.0064 % wt	0.0064 % wt	0.249	01/16/26 B.F.	SW-846 3050B	01/16/26 B.F.	SW 846-7000B	1	
Sample Comments:									

**EMSL Analytical, Inc.**

18369 Petroleum Drive, Baton Rouge, LA, 70809
 Telephone: (225)-755-1920 Fax:(225)-755-1989
 www.emsl.com

EMSL Order ID: 252650021
LIMS Reference ID: PE50021
EMSL Customer ID: PPMC25

Attention: Chuck Gooden
 PPM Consultants, Inc. [PPMC25]
 5555 Bankhead Highway
 Birmingham, AL 35210
 (205) 836-5650
 chuck.gooden@ppmco.com

Project Name: City of Alabaster Former Police Station

Customer PO: 40024103
EMSL Sales Rep: Natalie Murphy
Received: 01/09/2026 09:50
Reported: 01/16/2026 12:54

Analytical Results (Continued)

Analyte	Results	RL	Weight(g)	Prep Date & Tech	Prep Method	Analysis Date & Analyst	Analytical Method	Q	DF
Client Sample ID: L11/Pinkish Tan							Date Sampled: 01/08/26		
Matrix: Chips							LIMS Reference ID: PE50021-11		
Lead	<0.011 % wt	0.011 % wt	0.1486	01/16/26 B.F.	SW-846 3050B	01/16/26 B.F.	SW 846-7000B	1	
Sample Comments:									
Client Sample ID: L12/White							Date Sampled: 01/08/26		
Matrix: Chips							LIMS Reference ID: PE50021-12		
Lead	<0.0064 % wt	0.0064 % wt	0.2514	01/16/26 B.F.	SW-846 3050B	01/16/26 B.F.	SW 846-7000B	1	
Sample Comments:									
Client Sample ID: L13/White Red Star Rail							Date Sampled: 01/08/26		
Matrix: Chips							LIMS Reference ID: PE50021-13		
Lead	<0.0064 % wt	0.0064 % wt	0.2535	01/16/26 B.F.	SW-846 3050B	01/16/26 B.F.	SW 846-7000B	1	
Sample Comments:									
Client Sample ID: L14/Multi Blue							Date Sampled: 01/08/26		
Matrix: Chips							LIMS Reference ID: PE50021-14		
Lead	<0.0064 % wt	0.0064 % wt	0.2538	01/16/26 B.F.	SW-846 3050B	01/16/26 B.F.	SW 846-7000B	1	
Sample Comments:									
Client Sample ID: L15/Multi Layer - Jail Cell							Date Sampled: 01/08/26		
Matrix: Chips							LIMS Reference ID: PE50021-15		
Lead	0.057 % wt	0.0064 % wt	0.2513	01/16/26 B.F.	SW-846 3050B	01/16/26 B.F.	SW 846-7000B	1	
Sample Comments:									
Client Sample ID: L16/Tan							Date Sampled: 01/08/26		
Matrix: Chips							LIMS Reference ID: PE50021-16		
Lead	0.83 % wt	0.031 % wt	0.2543	01/16/26 B.F.	SW-846 3050B	01/16/26 B.F.	SW 846-7000B	D	5
Sample Comments:									
Client Sample ID: L17/Black							Date Sampled: 01/08/26		
Matrix: Chips							LIMS Reference ID: PE50021-17		
Lead	0.56 % wt	0.013 % wt	0.2504	01/16/26 B.F.	SW-846 3050B	01/16/26 B.F.	SW 846-7000B	D	2
Sample Comments:									



EMSL Analytical, Inc.

18369 Petroleum Drive, Baton Rouge, LA, 70809
Telephone: (225)-755-1920 Fax:(225)-755-1989
www.emsl.com

EMSL Order ID: 252650021
LIMS Reference ID: PE50021
EMSL Customer ID: PPMC25

Attention: Chuck Gooden
PPM Consultants, Inc. [PPMC25]
5555 Bankhead Highway
Birmingham, AL 35210
(205) 836-5650
chuck.gooden@ppmco.com

Project Name: City of Alabaster Former Police Station

Customer PO: 40024103
EMSL Sales Rep: Natalie Murphy
Received: 01/09/2026 09:50
Reported: 01/16/2026 12:54

Work Order Case Narrative

Sample 8 not analyzed due to insufficient material - MB 1/16/26

**EMSL Analytical, Inc.**

18369 Petroleum Drive, Baton Rouge, LA, 70809
 Telephone: (225)-755-1920 Fax:(225)-755-1989
 www.emsl.com

EMSL Order ID: 252650021
LIMS Reference ID: PE50021
EMSL Customer ID: PPMC25

Attention: Chuck Gooden
 PPM Consultants, Inc. [PPMC25]
 5555 Bankhead Highway
 Birmingham, AL 35210
 (205) 836-5650
 chuck.gooden@ppmco.com

Project Name: City of Alabaster Former Police Station

Customer PO: 40024103
EMSL Sales Rep: Natalie Murphy
Received: 01/09/2026 09:50
Reported: 01/16/2026 12:54

Certified Analyses included in this Report

Analyte	Certifications
SW 846-7000B in Chips	
Lead	25-A2LA Lead and Micro,25-LA (LELAP)

List of Certifications

Code	Description	Number	Expires
25-LA (LELAP)	Lead, Fungi, PCM. TEM, PLM	01950	06/30/2026
25-A2LA Lead and Micro	A2LA for Environmental Lead and Micro	2845.03	03/31/2027

Please see the specific Field of Testing (FOT) on www.emsl.com for a complete listing of parameters for which EMSL is certified.

Notes and Definitions

Item	Definition
D	Analyte was reported from a dilution run.
(Dig)	For metals analysis, sample was digested.
[2C]	Reported from the second channel in dual column analysis.
DA	Direct Analysis
DF	Dilution Factor
MDL	Method Detection Limit.
ND	Analyte was NOT DETECTED at or above the detection limit.
NR	Spike/Surrogate showed no recovery.
Q	Qualifier
RCS	Respirable Crystalline Silica
RL	Reporting Limit
Wet	Sample is not dry weight corrected.

Measurement of uncertainty and any applicable definitions of method modifications are available upon request. Per EPA NLLAP policy, sample results are not blank corrected.



EMSL Analytical, Inc.

18369 Petroleum Drive, Baton Rouge, LA, 70809
Telephone: (225)-755-1920 Fax:(225)-755-1989
www.emsl.com

EMSL Order ID: 252650021
LIMS Reference ID: PE50021
EMSL Customer ID: PPMC25

Attention: Chuck Gooden
PPM Consultants, Inc. [PPMC25]
5555 Bankhead Highway
Birmingham, AL 35210
(205) 836-5650
chuck.gooden@ppmco.com

Project Name: City of Alabaster Former Police Station

Customer PO: 40024103
EMSL Sales Rep: Natalie Murphy
Received: 01/09/2026 09:50
Reported: 01/16/2026 12:54

Martiana Beach Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. QC sample results are within quality control criteria and met method specifications unless otherwise noted. All results for soil samples are reported on a dry weight basis, unless otherwise noted.

Analysis following EMSL SOP for the Determination of Environmental Lead by FLAA. The laboratory has a reporting limit of 0.0064% by wt., based upon a minimum sample weight of 0.25g submitted to the lab, and is not responsible for any result or reporting limit provided in mg/cm² since it is dependent upon an area value provided by non-lab personnel. A "<" (less than) result signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty and definitions of modifications are available upon request. Results in this report are not blank corrected unless specified.



Lead Chain of Custody

EMSL Order Number / Lab Use Only

EMSL Analytical, Inc.
200 Route 130 North
Cinnaminson, NJ 08077

EMSL ANALYTICAL, INC.
TESTING LABS • PRODUCTS • TRAINING

PE50021 | 252650021

PHONE: (800) 220-3675
EMAIL: CinnaminsonLeadLab@emsl.com

Customer Information	Customer ID: PPMC25	Billing Information	Billing ID:
	Company Name: PPM Consultants, Inc.		Company Name: PPM Consultants, Inc.
	Contact Name: Chuck Gooden		Billing Contact: Leslie Hunt
	Street Address: 5555 Bankhead Highway		Street Address: 5555 Bankhead Highway
	City, State, Zip: Birmingham, AL 35210 Country:		City, State, Zip: Birmingham, AL Country: 35210
Phone: 205-541-6391	Phone: 205-909-1449	Email(s) for Invoice: leslie.hunt@ppmco.com	
Email(s) for Report: chuck.gooden@ppmco.com	Email(s) for Report: chuck.gooden@ppmco.com		

Project Name/No: City of Alabaster Former Police Station		Purchase Order: 40024103
EMSL LIMS Project ID: (if applicable, EMSL will provide)	US State where samples collected:	State of Connecticut (CT) must select project location: <input type="checkbox"/> Commercial (Taxable) <input type="checkbox"/> Residential (Non-Taxable)
Sampled By Name: Chuck Gooden	Sampled By Signature: <i>Chuck Gooden</i>	No. of Samples in Shipment

Turn-Around-Time (TAT)

3 Hour
 6 Hour
 24 Hour
 32 Hour
 48 Hour
 72 Hour
 96 Hour
 1 Week
 2 Week

Please call ahead for large projects and/or turnaround times 6 Hours or Less. *32 Hour TAT available for select tests only; samples must be submitted by 11:30am.

MATRIX	METHOD	INSTRUMENT	REPORTING LIMIT	SELECTION
CHIPS <input type="checkbox"/> % by wt. <input type="checkbox"/> ppm (mg/kg) <input type="checkbox"/> mg/cm ²	SW 846-7000B	Flame Atomic Absorption	0.008% (80ppm)	<input checked="" type="checkbox"/>
Reporting Limit based on a minimum 0.25g sample weight	SW 846-6010D	ICP-OES	0.0004% (4ppm)	<input type="checkbox"/>
AIR	NIOSH 7082	Flame Atomic Absorption	4µg/filter	<input type="checkbox"/>
	NIOSH 7300M / NIOSH 7303M	ICP-OES	0.5µg/filter	<input type="checkbox"/>
	NIOSH 7300M / NIOSH 7303M	ICP-MS	0.05µg/filter	<input type="checkbox"/>
	WIPE <input type="checkbox"/> ASTM <input type="checkbox"/> NON-ASTM	SW 846-7000B	Flame Atomic Absorption	10µg/wipe
If no box is checked, non-ASTM Wipe is assumed	SW 846-6010D	ICP-OES	1.0µg/wipe	<input type="checkbox"/>
TCLP	SW 846-1311 / 7000B / SM 3111B	Flame Atomic Absorption	0.4 mg/L (ppm)	<input type="checkbox"/>
	SW 846-1311 / SW 846-6010D*	ICP-OES	0.1 mg/L (ppm)	<input type="checkbox"/>
SPLP	SW 846-1312 / 7000B / SM 3111B	Flame Atomic Absorption	0.4 mg/L (ppm)	<input type="checkbox"/>
	SW 846-1312 / SW 846-6010D*	ICP-OES	0.1 mg/L (ppm)	<input type="checkbox"/>
TTLC	22 CCR App. II, 7000B	Flame Atomic Absorption	40mg/kg (ppm)	<input type="checkbox"/>
	22 CCR App. II, SW 846-6010D*	ICP-OES	2mg/kg (ppm)	<input type="checkbox"/>
STLC	22 CCR App. II, 7000B	Flame Atomic Absorption	0.4 mg/L (ppm)	<input type="checkbox"/>
	22 CCR App. II, SW 846-6010D*	ICP-OES	0.1 mg/L (ppm)	<input type="checkbox"/>
Soil	SW 846-7000B	Flame Atomic Absorption	40mg/kg (ppm)	<input type="checkbox"/>
	SW 846-6010D*	ICP-OES	2mg/kg (ppm)	<input type="checkbox"/>
Wastewater Unpreserved <input type="checkbox"/> Preserved with HNO3 <input type="checkbox"/> PH<2	SM 3111B / SW 846-7000B	Flame Atomic Absorption	0.4 mg/L (ppm)	<input type="checkbox"/>
	EPA 200.7	ICP-OES	0.020 mg/L (ppm)	<input type="checkbox"/>
Drinking Water Unpreserved <input type="checkbox"/> Preserved with HNO3 <input type="checkbox"/> PH<2	EPA 200.5	ICP-OES	0.003 mg/L (ppm)	<input type="checkbox"/>
	EPA 200.8	ICP-MS	0.001 mg/L (ppm)	<input type="checkbox"/>
TSP/SPM Filter	40 CFR Part 50	ICP-OES	12 µg/filter	<input type="checkbox"/>
Other:				<input type="checkbox"/>

Sample Number	Sample Location	Volume / Area	Date / Time Sampled
L1	Tan Paint-Sheetrock	Main Floor	
L2	White Trim Pain	Main Floor	
L3	Pink-Sheetrock	Main Floor	
L4	Dark Green Paint	Office	
L5	Blue Paneling	Middle Main Floor	

Method of Shipment:	Sample Condition Upon Receipt:		
Relinquished by: <i>Chuck Gooden</i>	Date/Time: 1-8-26 1:30 PM	Received by: <i>DM</i>	Date/Time: 1/9/26 9:50 AM
Relinquished by:	Date/Time:	Received by:	Date/Time:

Controlled Document - COC-25 Lead R16 4/19/2021

*6010C Available Upon Request

AGREE TO ELECTRONIC SIGNATURE (By checking, I consent to signing this Chain of Custody document by electronic signature.)

EMSL Analytical, Inc.'s Laboratory Terms and Conditions are incorporated into this Chain of Custody by reference in their entirety. Submission of samples to EMSL Analytical, Inc. constitutes acceptance and acknowledgment of all terms and conditions by Customer.

②7921 1590 7046

APPENDIX C – PHOTOGRAPH LOGS

**FORMER POLICE STATION
ALABASTER, ALABAMA
PPM PROJECT NO. 40024103**



Photo 1 – Grey Duct Work Tape in hallway of main floor and air handler closet in basement




Photo 2 – Black and yellow mastic on main floor NE office, middle office, and hallway under dark brown wood flooring



Photo 3 – Tan floor tile and black mastic on main floor hallway and southeast closet



Photo 4 – Black mastic under light brown laminate flooring on main floor middle and south hallway

**FORMER POLICE STATION
ALABASTER, ALABAMA
PPM PROJECT NO. 40024103**



Photo 5 – Tan Herringbone Laminate flooring and black and yellow mastic in main entry at main floor



Photo 6 – Black mastic under tan tile (2nd layer) and grey tile in entry to and within dispatch office



Photo 7 – White exterior paint, west entry gutter



Photo 8 – HVAC equipment and black exterior paint on the west side of the building

**FORMER POLICE STATION
ALABASTER, ALABAMA
PPM PROJECT NO. 40024103**



Photo 9 – Air handler on basement floor




Photo 10 – Fluorescent bulbs throughout building




Photo 11 – Light ballasts throughout building




Photo 12 – Computer equipment in computer room on basement floor

APPENDIX D – CERTIFICATIONS

THE UNIVERSITY OF
ALABAMA[®]
COLLEGE OF ENGINEERING

Certifies that

Charles Gooden

629 Mermont Drive
Trussville, AL 35173

*has attended and satisfactorily passed an examination
for the*

AHERA Inspector Update Course

May 8, 2025

in

Tuscaloosa, Alabama

*under the AHERA Model Accreditation Plan as required by EPA
to obtain this certificate numbered*

SS-2505-ASINSU-04

This certificate of training expires on

May 7, 2026



Michael E. Hamm

Principal Instructor

Arupp Cabel

Environmental Program Manager, SafeState

Christopher F. Schenel

Executive Director, SafeState

THE UNIVERSITY OF ALABAMA®



has examined the documentation of asbestos training and qualifications of the person named below and confers this

Certificate of Accreditation

Asbestos Inspector

Joanna Rowlen

Alabama Accreditation Number

AIN0625FEFA0440

Certificate Expiration Date

June 11, 2026

This certificate has been issued pursuant to the authority granted to The University of Alabama SafeState Program by the Alabama Asbestos Contractor Accreditation Act, Alabama Act No. 89-517, May, 1989 and Alabama Act No. 97-626, May, 1997.

A handwritten signature in blue ink that reads "Kalyn Tew".

Environmental Services Manager

A handwritten signature in blue ink that reads "Michael K. Brown".

Associate Director for Environmental Programs