

City of Beaumont, California

Beaumont Plunge Pool Study

January 2021



AUDIT

STUDY

DESIGN

OPERATE

WEB-APPS

COUNSILMANHUNSAKER.COM



# Process Overview

The City of Beaumont, California commissioned Councilman-Hunsaker (CH) to provide a swimming pool assessment and feasibility study for the Beaumont Plunge Swimming Pool. The purpose of the swimming pool assessment is to identify items that are substandard in the pools, identify items not to current industry swimming pool design standards, or equipment not operating as designed, and to assist in defining a course of action regarding the future of the aquatic facility.

The Pool was opened in 1963 making it 57 years old and it contains a 3,981 square foot main pool and 500 square foot children’s pool. Councilman-Hunsaker typically assigns a 30-to-40-year lifespan for an outdoor aquatic facility. The Beaumont Plunge Swimming Pool has exceeded that lifespan by 17 years. As pools age, they tend to require more regular care to remain open. Due to restricted budgets, pool operators are often required to keep their pools operational with small to medium repairs over the course of several years. For this reason, the City is looking at long-term goals that need to be considered to maintain an excellent aquatic experience for its residents.

As with other pools built at this same time, they are facing both physical and functional obsolescence. Physical obsolescence refers to physical issues such as equipment that needs to be replaced or is not operating as designed. Functional obsolescence describes the pools meeting the wants and needs of the community and the various aquatic user groups. Physical obsolescence requires increasing capital budgets on an annual basis due to repairs the facility needs to keep it operational. Functional obsolescence typically requires increased annual subsidies from the City’s general fund due to declining attendance and the inability to charge a sustainable admission fee since the facility does not have modern aquatic amenities that drive admission prices and guest length of stay.

<b>Review Existing Information</b>	Facility Drawings
	Prior Studies/Reports
	Observations/Goals of City
<b>Conduct On-Site Audit of Facility</b>	Pools and All Equipment
	Support Facilities
	Code Compliance including ADA Review
<b>Review Findings with City</b>	Recommendations for Physical Issue Corrections
	Recommendations for Addressing Functional Issues
	Cost Implications of Identified Action Plan
	Forecasting Remaining Life of Systems
	Identification of “fatal flaws” or Major Concerns

# Applicable Codes

The state administrative swimming pool code referenced as “California Building Code” in the report is as follows.

California Building Code  
Chapter 31B – Public Pools

Virginia Graeme Baker Pool and Spa Safety Act (VGB)  
ASME/ANSI A112.19.81  
Signed into Law on December 19, 2007  
CPSC Staff Interpretation of Section 1404 issued on June 18, 2008

Americans with Disabilities Act (ADA)  
U.S.C. 12101 et seq.  
Signed into Law on July 26, 1990 (2010 Update)

The administrative code requirements must be satisfied if a major modification of the pool is undertaken or if a particular item or piece of equipment is in need of repair. The recommended repairs address all administrative code items identified in this report.

AUDIT

STUDY

DESIGN

OPERATE

WEB-APPS

COUNSILMANHUNSAKER.COM



# Existing Conditions Assessment

AUDIT



STUDY



DESIGN



OPERATE



WEB-APPS



COUNSILMANHUNSAKER.COM



# Beaumont Plunge Swimming Pool

## General Pool Information

### Main Pool

Date Opened: 1963

Size: 3,981 square feet

Number of Gallons: 160,000

Depth Range: 3 feet to 10 feet

Turnover Rate: 350 GPM (7.9 hours)

### Children's Pool

Size: 500 square feet

Number of Gallons: 5,000

Depth Range: 1 ½ feet (constant depth)

Turnover Rate: 30 GPM (2.77 hours)



AUDIT

STUDY

DESIGN

OPERATE

WEB-APPS

COUNSILMANHUNSAKER.COM



# Pool Surface

The swimming pool is a concrete structure with a pebble-tec/sheen finish that was installed in 2014 and a tile perimeter band. Cracking was prevalent in the pool's surface near the main drain covers, and in both the shallow and deep ends on the slope where the pool wall and floor meet.

When structural cracking in a pool occurs, it can be created by many factors including shifting soils around the perimeter of the pool. Structural failure will continue until the issue is addressed. Furthermore, structural cracking allows water (pool or hydrostatic ground water) to penetrate the concrete and reach the embedded rebar. The result is corroded and eventual failed rebar, further weakening the pool structure.

Industry experience has shown that Pebbletec pools, if maintained in a wet or moist condition, will typically have a lifespan of 7 to 10 years. In most cases achieving a 10-year life on a Pebbletec surface is expected.

Staff report they started finding black mold on the pool's surface and have received a quote from a contractor to acid wash the affected areas.



AUDIT

STUDY

DESIGN

OPERATE

WEB-APPS

COUNSILMANHUNSAKER.COM



# Pool Surface

The City commissioned So-Cal Leak Detections to perform a leak detection test in April 2020. Three leaks were confirmed during their analysis.

- Leak found under slab approximately 2 feet away from return in pool on far side of diving board
- Suction leak found in equipment room approximately 5 feet in front of pump.
- Plaster crack on shallow end of pool in 3 ½ foot area.



(760)895-5959

13039 Cactus Dr Desert Hot Springs, CA 92240

To: Lilian/ Board Members  
 Address: 985 Maple Ave.  
 Technician: Armando Gomez

Date Ordered: 2/20/20 Starting Date  
 Job Location: Beaumont, CA  
 Job Phone: 951-769-8524 Terms  
 Customer Name

DESCRIPTION	AMOUNT
1) Leak found under slab approx. 2ft away from return in pool on far side of diving board ( if back is toward equipment) . cut concrete exeavate dirt to locate area where leak is located repair and put dirt back to prepare area for concrete.	<b>Repair total</b> <b>\$2900.00</b>
2) Suction leak found in equipment room approx. 5ft from front of pump. Repairs would need to be addressed in order to properly pressurize suction. Concrete would need to be removed and excavate to plumbing once broken plumbing is found, fix and return dirt to prepare for concrete (6" inch plumbing is located underground)	<b>\$4600.00</b>
3) Plaster crack on shallow end of pool leaking approx. 3 ½ ft. cut out crack with grinder ,chip out plaster until gunite is exposed and replaster once gunite is completely dry.	<b>\$1600.00</b>
4) Pool lights not properly bonded , if issue is not addressed with bonding wire casualty can occur for if the GFI fails the water will become electrified causing death. X _____ (I know of incident and will take full responsibility in this matter.)	<b>\$4600.00</b>
<small>Guarantee on Detection: All Leak Location and Detection work is guaranteed for 30 Days from the date of Completion. We will retest the system or refund the detection fee (at our sole option). If it is reported within the above 30 Day period, that a leak still exists. We will not be liable for other consequential loses.</small>	
<small>Guarantee on Repair: Minor Repair are guaranteed for 30 Days. Major Repairs are Guaranteed for 12 Months. All Repairs are Guaranteed from the date of completion and for detective workmanship only, unless stated on bid.</small>	
<small>I find the work satisfactory and the charges as agreed, and agree to pay the total amount due on presentation of this invoice without any deduction whatsoever. I further agree to pay reasonable charges for collection. Including attorney fees, in the event of my default, as well as penalty interest as allowed by law.</small>	
Leak Detect.	\$475.00
Other	
Subtotal	
Tax	
<b>Total Owed</b>	<b>\$475.00</b>

# Pool Surface

Staff report the 48-hour water loss with the pumps running goes from the middle of the blue tile to below the first step on stair entry. Since the pool did not lose as much water without the pumps running, there is a leak within the pool's recirculation system.

Staff have not observed the pool water leaking into the adjacent park, which likely means the leaking pool water is draining below the pool, which could be destabilizing the soil surrounding the pool structure. There are limited solutions to soil stabilization after the pool structures are in place.

Because of these cracks, coupled with the water loss and shifting deck, it is recommended that the pool shell not be reused if the facility undergoes a substantial renovation. It is possible to add a vinyl or fiberglass pool liner to the facility, purely as a band-aid approach, in order to get the facility 5 more years of operation.

And, while it is impossible to repair significant cracking in the pool and pool deck, they can be filled with an epoxy injection. However, with this type of movement, the cracking will reoccur.



AUDIT

STUDY

DESIGN

OPERATE

WEB-APPS

COUNSILMANHUNSAKER.COM





# Main Drains

There are two (2) 24" x 24" square, fiberglass main drain covers located in the deep end of the main pool. The main drain grates were broken and unsecured at the time of the site visit. The grates are suction and hair entrapment certified as required by the Virginia Graeme Baker Pool and Spa Safety Act (VGB), ASME/ANSI A112.19.81. All main drains with dimensions 18" x 23" or smaller are classified as "blockable" and must have a VGB stamped and certified "unblockable" grate cover with tamper proof screws.

The federal regulations of VGB were passed by Congress in 2008 and are designed to reduce the potential for suction and hair entrapment in commercial swimming pools at all suction outlets (e.g. main drains, skimmer equalizer lines, etc.). The Consumer Product Safety Commission (CPSC) is tasked with Federally enforcing all VGB regulations, but due to the vast number of commercial swimming pools in the United States, enforcement most commonly is the responsibility of the local governing agencies (e.g. public health departments, building departments, etc.).

Staff should confirm when the grates were last replaced to ensure it is still within the stipulated time frame. New grates will be necessary if the pool is brought back into operation.



AUDIT

STUDY

DESIGN

OPERATE

WEB-APPS

COUNSILMANHUNSAKER.COM



# Competition Pool ADA Accessibility

The ADA Act requires that a swimming pool with a perimeter that is less than 300' to have at least one accessible means of entry, provided that the primary accessible means of entry is an ADA compliant swimming pool lift or ADA compliant swimming pool ramp with handrails. The secondary means of access can be either a ramp, lift or compliant stair entry. The main pool's size necessitates one means of entry which is met with the ADA lift that is on-site. The lift will need to be installed adjacent to the pool if the pool is brought back into operation.



# Diving

According to Section 3313B: Diving Boards and Platforms, the following are required for diving boards.

- Diving boards shall be anchored to the pool deck, constructed of corrosion resistant material, designed and constructed to be easily cleanable and finished with a durable slip resistant material.
- Diving boards greater than 18 inches in height above the deck shall be provided with a ladder or stairs for access. Handrails shall be provided at all ladders and stairs leading to diving boards more than 1 meter above the water. Diving boards over 1 meter above the water shall have guard rails on both sides of the diving board that extend to a point director above the water's edge.
- Dimensions and clearances for the use of diving boards shall conform to those shown in Figures 31B-1 and 31B-2. Diving boards shall conform to the USA Diving Rules and Codes, Part 1, Subpart A and Appendix B.




FIGURE 31B-1  
DEPTHS AND CLEARANCES FOR POOLS WITH DIVING BOARDS GREATER THAN 30 INCHES (762 mm) ABOVE THE WATER LINE


TABLE 31B-1

BOARDS AND PLATFORMS	DIM	DEPTH OF WATER				LENGTH OF SECTION				
		D1	D2	D3	D4	L1	L2	L3	W1	W2
1-meter board	Min.	5'-6"	11'-6"	11'-2"	0'-0"	16'-5"	29'-7"	5'-11"	7'-11"	8'-3"
3-meter board	Min.	6'-6"	12'-6"	12'-2"	0'-0"	19'-9"	33'-8"	5'-11"	8'-7"	11'-6"

# Diving

Through Counsilman-Hunsaker's analysis of the existing deep end of the Beaumont Plunge Swimming Pool, the following has been determined:

- The depth of the diving well does not meet the minimum standards stipulated by the State Code. With a depth of 10 feet, the depth fails the standards by 18 inches.
- The existing slope of the pool floor does not meet the standards stipulated by the State Code. As shown in the picture to the right, the white line denotes the existing pool floor and slope while the red line represents the depth and slope required by the State Code. The pool does not meet the slope or the depth requirement.



AUDIT

STUDY

DESIGN

OPERATE

WEB-APPS

COUNSILMANHUNSAKER.COM



# Perimeter Overflow

The pool has a tiled, concrete gutter overflow system that allows for continuous surface skimming around the perimeter of the pool. The gutter system is in poor condition with noticeable cracks in the concrete and in the connecting coping stone.

The State Code and current industry standards stipulate that overflow gutters shall be capable of continuously removing no less than 100% of the recirculated water, which is not met with the current flow rate and gutter capacity.

A new perimeter overflow system would require a surge tank to be constructed equal to at least 1 gallon per square foot of pool surface area. Solutions exist to install a stainless-steel gutter system on this type of pool by cutting the top off the pool's perimeter and installing the gutter system. The installation of this gutter system would bring the pool's perimeter overflow system up to code.

Staff reported the perimeter return piping was replaced within the past 10 years by the City's grounds maintenance staff.

Based on the location of the scum line in the pictures to the right, it appears the gutters might not have been properly draining when the pool was last in operation. If the water level in the gutters is above the tile lip, then the gutters are not functioning properly.



# Pool Deck

Cracking is evident in the pool deck around the entire perimeter of the pool. Some of the cracks span 10 feet or longer. Staff reported that they have observed water bubbling under the cracks in the deck and when the pool is filled, there is often standing water behind the diving board.

While the facility does meet the California Building Code requirement of maintaining a minimum deck width of four (4) feet around the pool perimeter, due to the condition of the deck, a full replacement is recommended during a future renovation.



AUDIT

STUDY

DESIGN

OPERATE

WEB-APPS

COUNSILMANHUNSAKER.COM



# Mechanical System

AUDIT



STUDY



DESIGN



OPERATE



WEB-APPS



COUNSILMANHUNSAKER.COM



# Pool Mechanical

A single 10-horsepower Marathon pump is provided on the recirculation system that is under direct suction from the main drains. The pump and motor both display significant signs of corrosion. The GPM rating for the pump and the horsepower for the motor were not verified by nameplate during the site visit. A strainer is provided for the pump as required by the State Code.

The main drain and skimmer combine to a 6-inch PVC schedule 80 pipe in the mechanical room that is routed through the required skimmer basket (3125B.4) and to the high-rate sand filters. The filtered water is routed back to the pool via a single, 6-inch pipe (pressure). A flow meter was observed as required by 3125B.3.

The California Building Code, Chapter 3124B requires that public pools be turned over at a minimum rate of six hours. The pool was empty during the site visit, so the mechanical system was not observed as operational. Based on the size of the pool's suction piping at the current flow rate of 350GPM, the 160,000-gallon pool is turned over every 7.9 hours, which exceeds the current code requirement. The minimum flow rate for the swimming pool to achieve the required 6-hour turnover is 461 GPM.



AUDIT

STUDY

DESIGN

OPERATE

WEB-APPS

COUNSILMANHUNSAKER.COM





# Pool Mechanical

The pool contains two (2) Eko-3 Systems high-rate sand filters that were installed in 2014. With 16.5 square feet of filter area, the filters are each rated for a flow rate of 247 GPM, giving them an overall capacity for 494 GPM at 15 gallons per minute per square foot, which is the industry standard. The pool's flow rate of 350GPM is within this rating.

The horizontal filter tanks did not have any noticeable defects and staff reported they were functional during the 2019 summer season when the pool was last opened. Staff reported the gaskets and connectors behind the filter gauges are constantly leaking.

CH typically assigns a lifespan of 15-20 years to pool filters and related mechanical equipment. Since the pool filters are only 6 years old, CH would expect them to last another 10+ years for the operation of the pool.



AUDIT

STUDY

DESIGN

OPERATE

WEB-APPS

COUNSILMANHUNSAKER.COM



# Pool Mechanical

The pool is controlled by an BECSys 3 chemical controller. The chemical controller automatically adds sanitizer from the Pulsar 4 system, or muriatic acid as the pH buffer, as necessary to minimize the peaks and valleys common when the chemical feed is controlled manually. The controller was installed within the past few years and is in good working condition. It is appropriate for this type of usage and could be reused in a future renovation.



AUDIT

STUDY

DESIGN

OPERATE

WEB-APPS

COUNSILMANHUNSAKER.COM



# Pool Mechanical

The pools are sanitized with calcium hypochlorite (tablet chlorine) via a Pulsar erosion feeder system and use muriatic acid as a pH buffer. The sodium hypochlorite and muriatic acid for the swimming pool are located in the main pool mechanical room.

Corrosion was evident on several items within the mechanical space, including the following:

- Electrical panel
- Water heater
- Electrical conduit
- Electrical box for the Pulsar switch

This is most likely due to the presence of the muriatic acid feeder that is located within the mechanical room. A separate, dedicated and ventilated chemical storage room for both the sanitizer and pH buffer is recommended and is the current industry standard. During a future renovation, these separate mechanical rooms could be included. In an ideal setting these two would be in their own separate, ventilated spaces.



AUDIT

STUDY

DESIGN

OPERATE

WEB-APPS

COUNSILMANHUNSAKER.COM



# Pool Mechanical

A variable frequency drive is not installed on the circulation system. A variable-frequency drive (VFD) is a system for controlling the rotational speed of an alternating current (AC) electric motor by controlling the frequency of the electrical power supplied to the motor. VFDs should be considered on any future mechanical system upgrades.



AUDIT

STUDY

DESIGN

OPERATE

WEB-APPS

COUNSILMANHUNSAKER.COM



# Children's Pool

AUDIT



STUDY



DESIGN



OPERATE



WEB-APPS



COUNSILMANHUNSAKER.COM



# Children's Pool

- The children's pool is in fair condition overall but does not meet the current expectations for a children's area at an outdoor aquatic facility. The pool holds approximately 5,600 gallons which would necessitate a flow rate of 85 gallons per minute to reach a one-hour turnover rate as required by the State Code.
- Noticeable cracking is evident in the pool's coping stone and there are areas that do not contain any grout along the expansion joints. Missing tiles from the perimeter tile band were also observed.
- The pool is not compliant with the current ADA Standards for swimming pools (2010) and would need to add an entry ramp with compliant handrails in order to meet the current ADA requirements.
- The main drain grate is compliant with the Virginia Graeme Baker Pool and Spa Safety Act (VGB) but has a lifespan that is noted at 5 years. Staff should confirm when the grate was last replaced to ensure it is still within the stipulated time frame. Since the pool contains only one main drain, a Safety Vacuum Release System (SVRS) system is necessary to protect users against suction entrapment.



# Children's Pool

- The pool's mechanical system contains a Triton Sand Filter, BecSys 2 chemical controller and a Pulsar 1 unit for the calcium hypochlorite sanitizer. The muriatic acid and calcium hypochlorite feeders are both located in the mechanical shed and have caused corrosion on some of the surrounding equipment. This is especially noticeable on the pool pump motor and electrical outlet.
- The children's pool does not have a mechanical system that meets industry design standards since it does not contain an Ultraviolet Treatment (UV) System on the pool (picture – bottom right) to provide secondary sanitation. UV has been shown to be highly effective against chlorine resistant pathogens like Cryptosporidium and Giardia; as well as the vast majority of bacteria, viruses, yeast, and mold.
- According to the Model Aquatic Health Code, "Due to the risk of outbreaks of RWIs associated with the DISINFECTANT tolerant parasite Cryptosporidium, it is strongly recommended that all AQUATIC FACILITIES include SECONDARY DISINFECTION SYSTEMS to minimize the risk to the public associated with these outbreaks."



UV System Example

COUNSILMANHUNSAKER.COM

# Children's Pool

- The pool contains a single main drain with two (2) return inlets on the west side of the pool and a single skimmer box on the east side of the pool. With 2-inch schedule 40 pressure piping that is rated for 105 GPM at 10 feet per second, the piping can handle the flow rate necessary to meet the required one-hour turnover rate.
- The single skimmer suction piping cannot handle the full recirculation flow rate for the children's pool. Assuming the maximum flow rate of 63 GPM the pool would need a 3-inch pipe to handle this flow.
- The tot pool does not meet the modern definition of a children's pool because it lacks a zero-beach entry, children's play features, tot slides, etc. If the facility undergoes a future renovation, it is recommended that this area be replaced with a modern tot pool or interactive spraypad.



AUDIT

STUDY

DESIGN

OPERATE

WEB-APPS

COUNSILMANHUNSAKER.COM





# Assessment Summary

AUDIT



STUDY



DESIGN



OPERATE



WEB-APPS



COUNSILMANHUNSAKER.COM



# Assessment Summary

The Beaumont Plunge Swimming Pool has several physical and functional issues that are notated below. Due to these issues, it is the opinion of Counsilman-Hunsaker that the pool has exceeded its expected lifespan and the City should consider options for renovation or replacement.

- Three major leaks have been found in the swimming pool and mechanical system. CH observed numerous cracks in the pool shell and in the surrounding deck, which points to structural movement of the pool shell.
- The current perimeter overflow system and piping does not sufficiently meet modern industry standards, which is for the system to handle 100% of the recirculation rate as required by the current State Code (3136B).
- The pool's turnover rate exceeds the State Code requirement by 1.9 hours.
- The pool deck is shifting and has numerous cracks surrounding the pool necessitating a complete replacement.
- The depth and slope of the deep end of the pool does not meet the minimum requirement for the 1-meter diving board.
- The children's pool does not meet the current 2010 Americans with Disabilities Act standards or the Model Aquatic Health Code standards for secondary sanitation.
- An evaluation has determined that the in-pool lights are not grounded per NEC 680 requirements.
- Significant corrosion exists in the swimming pool's mechanical room necessitating separate chemical rooms for the pool's sanitizer (calcium hypochlorite) and the pH buffer (muriatic acid).

AUDIT

STUDY

DESIGN

OPERATE

WEB-APPS

COUNSILMANHUNSAKER.COM



# Assessment Summary

- The Beaumont Plunge Swimming pool has seen decreased attendance over the past several years with an increasing general fund subsidy for the summer pool operations.
- The shallow portion of the main pool is still too deep for young children, inhibiting the City's ability to teach swimming lessons.
- The pool does not contain easily accessible exits for pool users. Exit stairs are a key component of modern swimming pool design to ensure the ingress and egress to the pool is easily manageable for all pool users.
- Today's expectation for an outdoor aquatic facility has drastically changed from that of 1963.
- While most outdoor family aquatic centers will still incorporate lap lanes, a competition pool is not essential since the School District operates a competitive pool for their swimming programs. Likewise, there is not a large contention of competitive swimmers within the immediate area who have requested the City to build a competition pool.
- Children's areas are designed much larger than the existing one at the Beaumont Plunge Swimming Pool and incorporate perimeter seating for adults in order to enjoy the experience and to closely monitor their children.
- Recreational water has taken a more freeform shape as opposed to the traditional rectangular pools of the 1960s. It's common for these pools to have multiple zones that include a zero-beach entry, waterslide plunge areas, moving water such as a current channel or lazy river, inflatable crossing activities and deep-water amenities such as climbing walls, drop slides and diving boards or platforms.
- Mechanical systems have also been updated to address the requirements set forth in the Model Aquatic Health Code. These include increased turnover rates and secondary disinfection systems.

AUDIT

STUDY

DESIGN

OPERATE

WEB-APPS

COUNSILMANHUNSAKER.COM



# Market Overview

AUDIT



STUDY



DESIGN



OPERATE



WEB-APPS




COUNSILMANHUNSAKER.COM



# Beaumont Demographics

- Above average number of adults with ages ranging 30 to 39 and children 0 to 14 reside within the City of Beaumont.
- The local area to Stewart Park has below average household income (95%); areas 5 to 15 minutes away are slightly above the national average (106%).
- Both the City of Beaumont and the 30-minute drive time market have increasing population growth.



# Area Swimming Pools



Beaumont Plunge, Beaumont, CA



City of Banning Replier Park  
Aquatic Center; Banning, CA  
12 minutes, 5.8 miles from site



Yucaipa City Swimming Pool;  
Yucaipa, CA  
17 minutes, 10.6 miles from site



Riverside Aquatics Complex;  
Riverside, CA  
34 minutes, 27 miles from site



Arlington Park Pool; Riverside, CA  
37 minutes, 32.6 miles from site



Islander Park Pool; Riverside, CA  
26 minutes, 21.9 miles from site



Sippy Woodhead / Bobby Bonds  
Pool, Riverside, CA  
31 minutes, 24.2 miles from site



Lancer Aquatic Center CBU;  
Riverside, CA  
37 minutes, 31.3 miles from site

AUDIT

STUDY

DESIGN

OPERATE

WEB-APPS

COUNSILMANHUNSAKER.COM



# Area Swimming Pools



Shamel Park Pool, Riverside, CA  
33 minutes, 28.6 miles from site



Canyon Crest Country Club,  
Riverside, CA  
29 minutes, 22.7 miles from site



24 Hour Fitness, Riverside, CA  
34 minutes, 29.5 miles from site



Hunt Park Pool; Riverside, CA  
38 minutes, 32.1 miles from site



LA Fitness Arlington Ave, Riverside,  
CA  
34 minutes, 28.6 miles from site



UCR Student Recreation Center,  
Riverside, CA  
28 minutes, 23.4 miles from site



Riverside Community College,  
Riverside, CA  
32 minutes, 26.9 miles from site



The Cove Waterpark Camino Real,  
Riverside, CA  
35 minutes, 30.2 miles from site

AUDIT

STUDY

DESIGN

OPERATE

WEB-APPS

COUNSILMANHUNSAKER.COM



# Area Swimming Pools



Rialto Fitness and Aquatic Center,  
Rialto, CA  
30 minutes, 27.8 miles from site



24 Hour Fitness, Rialto, CA  
36 minutes, 34.1 miles from site



DVL Aquatic Center Valley-Wide  
Recreation, Hemet, CA  
30 minutes, 17.9 miles from site



LA Fitness, Hemet, CA  
22 minutes, 14.1 miles from site



DropZone Waterpark, Perris, CA  
36 minutes, 24.9 miles from site



Palm Springs Swim Center, Palm  
Springs, CA  
34 minutes, 30.8 miles from site



Crafton Hills College Aquatics  
Center, Yucaipa, CA  
18 minutes, 12.1 miles from site



Fifth Avenue Swim Club, Redlands, CA  
18 minutes, 14.5 miles from site

AUDIT


STUDY

DESIGN

OPERATE

WEB-APPS

COUNSILMANHUNSAKER.COM





# Area Swimming Pools



Yucaipa Regional Park Swim Complex,  
Yucaipa, CA  
22 minutes, 14.2 miles from site



University of Redlands, Thompson  
Aquatic Center, Redlands, CA  
20 minutes, 16.1 miles from site



Jerry Lewis Family Swim Center, San  
Bernardino, CA  
30 minutes, 27.4 miles from site



YMCA of the East Valley, Redlands, CA  
20 minutes, 15.9 miles from site



Tom Sawyer Swimming Pool, Rialto,  
CA  
30 minutes, 27.8 miles from site



Grand Terrace High School  
Swimming Pool, Grand Terrace, CA  
31 minutes, 27.8 miles from site



John W. North High School  
Swimming Pool, Riverside, CA  
28 minutes, 23.6 miles from site



UC Riverside - Glen Mor Pool,  
Riverside, CA  
28 minutes, 22.2 miles from site

AUDIT

STUDY

DESIGN


OPERATE

WEB-APPS

COUNSILMANHUNSAKER.COM



# Area Swimming Pools



Number	Facility
1	Beaumont Plunge
2	City of Banning Repplier Park Aquatic Center
3	Yucaipa City Swimming Pool
4	Riverside Aquatics Complex
5	Arlington Park Public Pool
6	Islander Park Pool
7	Sippy Woodhead / Bobby Bonds Pool
8	Lancer Aquatic Center – CBU
9	Shamel Park Pool
10	Canyon Crest Country Club
11	24 Hour Fitness Madison St.
12	Hunt Park
13	LA Fitness Arlington Ave.
14	UCR Student Recreation Center
15	Cesar E. Chavez Community Center
16	Riverside Community College
17	The Cove Waterpark Camino Real
18	Rialto Fitness and Aquatic Center
19	24 Hour Fitness Rialto
20	Diamond Valley Lake Aquatic Center
21	LA Fitness Hemet
22	DropZone Waterpark
23	Palm Springs Swim Center
24	Crafton Hills College Aquatics Center
25	Fifth Avenue Swim Club
26	Yucaipa Regional Park Swim Complex
27	University of Redlands Thompson Aquatic Center
28	Jerry Lewis Family Swim Center
29	YMCA of the East Valley
30	Tom Sawyer Swimming Pool
31	Grand Terrace High School Swimming Pool
32	John W. North High School Swimming Pool

<b>AUDIT</b>	<b>STUDY</b>	<b>DESIGN</b>	<b>OPERATE</b>	<b>WEB-APPS</b>	

# Options for Consideration

AUDIT



STUDY



DESIGN



OPERATE



WEB-APPS




COUNSILMANHUNSAKER.COM



# Options for Consideration

- The first option consists of a complete renovation of the existing Beaumont Plunge Pool. This would include modifications to the existing pool and pool structure, a new stainless steel gutter system, and removal of the 1-meter diving board. The existing children’s pool would be demolished and a new one built in its place. Mechanical system upgrades would be made to both pools, as well as a renovation to the existing bathhouse.
- The second option would entail a complete demolition of the existing Beaumont Plunge Pool and the construction of a new outdoor swimming pool in its place. The new pool would contain fitness lap lanes, waterslides, a zero-beach entry with a children’s area and an update to the existing bathhouse.
- The third option includes the demolition of the existing Beaumont Plunge Pool and replacing it with a spraypad.



# Beaumont Plunge Renovation

- Renovation of existing Beaumont Plunge Swimming Pool
  - Removal of diving board
  - Inclusion of shallow water floatables
- New children's pool
  - Spray features
  - ADA accessible
- Renovation of existing bathhouse and support spaces



AUDIT

STUDY

DESIGN

OPERATE


WEB-APPS

COUNSILMANHUNSAKER.COM



# Beaumont Plunge Renovation

- Renovation of existing Beaumont Plunge Swimming Pool
  - Removal of diving board
  - Inclusion of shallow water floatables
  
- New children's pool
  - Spray features
  - ADA accessible
  
- Renovation of existing bathhouse and support spaces

 <b>Counsilman - Hunsaker</b> AQUATICS FOR LIFE	
Beaumont, California	
*PRELIMINARY Opinion of Probable Construction Cost	
11/17/2020	
ITEM	COST
Beaumont Plunge Swimming Pool	\$655,631.05
Deck Equipment	\$32,833.33
Loose Equipment	\$555.56
Maintenance Equipment	\$7,694.44
Safety Equipment	\$3,450.00
Existing Bathhouse Renovation	\$898,937.50
Children's Pool	\$320,617.46
Contingency (Design / Construction)	\$70,016.44
Project Fees (Design, Surveys, Permitting)	\$77,018.08
<b>Project Total</b>	<b>\$2,066,753.87</b>

# Beaumont Plunge Replacement

- Demolition of existing swimming pool and children's pool
- New 5,000 SF outdoor aquatic center
  - Zero depth entry with spray features
  - Fitness lap lanes
  - Waterslide
- Renovation of existing support spaces
  - Mechanical room
  - Locker rooms
  - Office
  - Storage



AUDIT


STUDY

DESIGN

OPERATE

WEB-APPS

COUNSILMANHUNSAKER.COM



# Beaumont Plunge Replacement

- Demolition of existing swimming pool and children’s pool
- New 5,000 SF outdoor aquatic center
  - Zero depth entry with spray features
  - Fitness lap lanes
  - Waterslide
- Renovation of existing support spaces
  - Mechanical room
  - Locker rooms
  - Office
  - Storage

OPINION OF PROJECT COST: Option 2					
Description	Unit	Amount	Cost per Unit	Opinion of Cost	Opinion of Cost
Support Spaces		3,785	238	\$898,938	\$898,938
Existing Building Renovation	Sq. Ft.	3,785	238	\$898,938	
Outdoor Aquatic Center		15,286	165	\$2,524,101	\$2,524,101
<b>Outdoor Leisure Pool</b>	Sq. Ft.	5,091	333	\$1,695,303	
Spray Features	Allowance	2	50,000	\$100,000	
Crossing Activity	Allowance	1	50,000	\$50,000	
Climbing Wall	Allowance	1	50,000	\$50,000	
Waterslide Tower	Allowance	1	200,000	\$200,000	
Waterslide Mechanical	Allowance	1	50,000	\$50,000	
Shade Structures	Qty.	4	10,000	\$40,000	
Shade Pavillion	Qty.	1	20,000	\$20,000	
Outdoor Deck	Sq. Ft.	10,184	15	\$152,760	
Overhead Lighting	Sq. Ft.	15,286	8	\$122,288	
Fencing	Linear Ft.	500	88	\$43,750	
Unit	Sq. Ft.		Cost	Opinion of Cost	Opinion of Cost
<b>Total Building Construction Costs</b>		<b>19,371</b>	<b>\$180</b>	<b>3,479,289</b>	<b>3,479,289</b>
Demolition Allowance		<b>1</b>	<b>\$200,000</b>	\$200,000	\$200,000
Site Construction Costs (demolition, parking, landscaping, utilities, walks)				\$484,275	\$484,275
Furniture, Fixtures, Equipment				\$117,000	\$117,000
Subtotal				\$4,280,564	\$4,280,564
Escalation Allowance (1 year)	5.0%			\$214,028	\$214,028
Contingency (Design / Construction)	10.0%			\$449,459	\$449,459
Design Fees, Surveys, Permitting	10.0%			\$494,405	\$494,405
<b>Opinion of Probable Cost</b>				<b>\$5,438,456</b>	<b>\$5,438,456</b>
<b>Total Estimated Project Costs:</b>			<b>\$281</b>	<b>\$5,438,456</b>	<b>\$5,500,000</b>
<b>Estimate Current as of:</b>			<b>11/17/2020</b>		
			<b>Source: Counsilman-Hunsaker</b>		



# Beaumont Plunge Replacement



AUDIT	STUDY	DESIGN	OPERATE	WEB-APPS	<a href="http://COUNSILMANHUNSAKER.COM">COUNSILMANHUNSAKER.COM</a>
					

# New Spraypad

- New 2,100 SF spraypad with sequencing features and lighting
- Perimeter concrete deck
- Shade Pavilions
- Access walkways from sidewalks and streets



AUDIT

STUDY

DESIGN

OPERATE

WEB-APPS

COUNSILMANHUNSAKER.COM



# New Spraypad

- New 2,100 SF spraypad with sequencing features and lighting
- Perimeter concrete deck
- Shade Pavilions
- Access walkways from sidewalks and streets

OPINION OF PROJECT COST: Option 3					
Description	Unit	Amount	Cost per Unit	Opinion of Cost	Opinion of Cost
Outdoor Aquatic Center		6,905	88	\$608,775	\$608,775
<b>Spraypad</b>	Sq. Ft.	2,100	163	\$341,250	
Features	Allowance	1	100,000	\$100,000	
Outdoor Pool Mechanical Enclosure	Sq. Ft.	600	50	\$30,000	
Shade Structures	Qty.	4	10,000	\$40,000	
Outdoor Deck	Sq. Ft.	4,200	15	\$63,000	
Overhead Lighting	Sq. Ft.	6,905	5	\$34,525	
Unit		Sq. Ft.	Cost	Opinion of Cost	Opinion of Cost
<b>Total Building Construction Costs</b>		<b>6,905</b>	<b>\$88</b>	<b>608,775</b>	<b>608,775</b>
Demolition Allowance				\$0	\$0
Site Construction Costs (parking, landscaping, utilities, walks)				\$172,625	\$172,625
Furniture, Fixtures, Equipment				\$21,000	\$21,000
Subtotal				\$802,400	\$802,400
Escalation Allowance (1 year)	5.0%			\$40,120	\$40,120
Contingency (Design / Construction)	10.0%			\$84,252	\$84,252
Design Fees, Surveys, Permitting	10.0%			\$92,677	\$92,677
<b>Opinion of Probable Cost</b>				<b>\$1,019,449</b>	<b>\$1,019,449</b>
<b>Total Estimated Project Costs:</b>			<b>\$148</b>	<b>\$1,019,449</b>	<b>\$1,100,000</b>
<b>Estimate Current as of:</b>	<b>11/17/2020</b>				
	<b>Source: Counsilman-Hunsaker</b>				

# New Spraypad



AUDIT

STUDY

DESIGN

OPERATE

WEB-APPS

COUNSILMANHUNSAKER.COM



# New Spraypad



AUDIT

STUDY

DESIGN

OPERATE

WEB-APPS

COUNSILMANHUNSAKER.COM



# Operational Analysis

AUDIT



STUDY



DESIGN



OPERATE



WEB-APPS



COUNSILMANHUNSAKER.COM



# Operational Analysis Overview

The revenue analysis for the swimming pool and spraypad options include special user group usage and facility per capita spending trends, developing an opinion of revenue for the first five years of operation. Programming revenue is based on user groups and local programming fees. The fee structure is based on fees from season passes and other users to project a per capita income. Revenue is estimated, taking recommended fee schedules into account and current market rates and utilization figures.

The expense analysis includes a detailed budget model for estimating probable expenses for major areas of labor, contractual services, commodities, and utilities. User projections are made based on programming. Expenses are estimated taking into account hours of operation, attendance projections, local weather patterns, local utility rates, and other key items.

AUDIT



STUDY



DESIGN




OPERATE



WEB-APPS



COUNSILMANHUNSAKER.COM



# Expense Budget

Direct Facility Expense Budget			
	Existing Pool	New Outdoor Pool	Spraypad
<b>Facility Staff</b>			
Full Time Employment		Not Included	Not Included
Part-Time Management		\$15,120	\$0
Lifeguard Personnel		\$120,960	\$0
Front Desk Personnel		\$7,140	\$0
Personnel Equipment Cost		\$1,333	\$0
Training		\$5,000	\$0
<b>Total Labor</b>		<b>\$149,553</b>	<b>\$0</b>
<b>Direct Facility Expenses</b>			
Insurance		Not Included	Not Included
Repair and Maintenance		\$13,600	\$2,600
Credit Card Fees		\$2,444	\$0
Operating Supplies		\$8,160	\$1,560
Chemicals		\$7,020	\$2,468
Advertising		\$3,500	\$0
<b>Direct Expenses</b>		<b>\$34,724</b>	<b>\$6,628</b>
<b>Utilities</b>			
HVAC		\$9,970	\$0
Electricity		\$35,290	\$13,886
Pool Heating		\$11,895	\$2,063
Data/Communications		\$0	\$0
Trash Service		\$0	\$0
Water & Sewer		\$11,982	\$8,598
<b>Total Utilities</b>		<b>\$69,136</b>	<b>\$24,548</b>
<b>Programs</b>			
Program Supplies		\$5,419	\$0
LG Class Materials		\$666	\$0
Food and Beverage		\$4,744	\$0
Part-Time Program Staff		\$10,711	\$0
<b>Total Programs</b>		<b>\$21,540</b>	<b>\$0</b>
<b>Total Operating Expenses</b>	<b>\$0</b>	<b>\$274,952</b>	<b>\$31,176</b>
Capital Replacement Fund	\$0	\$27,200	\$5,100
<b>Total Expense</b>	<b>\$0</b>	<b>\$302,152</b>	<b>\$36,276</b>

**Existing Budget**






# New Aquatic Facility Revenue (Option 2)

- Daily admissions / memberships
- Swim team revenue
- Program revenue
- Food and beverage
- Rentals

Revenue Streams



- Daily Admissions / Memberships
- Swim Team Revenue
- Aquatics Instruction Revenue
- Food and Beverage
- Rentals

AUDIT

STUDY

DESIGN

OPERATE

WEB-APPS

COUNSILMANHUNSAKER.COM



# Aquatic Facility Financial Dashboard (Option 2)

Total Capital Cost

**\$5,500,000**

Total Attendance

**35,940**


Operating Cashflow

**(\$139,485)**



Cost Recovery

**49%**

Annual Revenue



Expense Budget Breakdown



AUDIT

STUDY

DESIGN

OPERATE

WEB-APPS

COUNSILMANHUNSAKER.COM



# Aquatic Facility Financial Dashboard (Option 3)

Total Capital Cost

**\$1,100,000**

Total Attendance

**29,856**


Operating Cashflow

**(\$31,176)**


Cost Recovery

**0%**

Annual Revenue



Expense Budget Breakdown



- Total Labor
- Direct Expenses
- Total Utilities



AUDIT

STUDY

DESIGN

OPERATE

WEB-APPS

COUNSILMANHUNSAKER.COM



# Options Summary

Summary Dashboard				
<b>Existing Pool</b>	Total Capital Cost	Total Revenue	Total Expense	Cost Recovery
	<b>\$2,066,754</b>	<b>\$10,403</b>	<b>\$61,150</b>	<b>17%</b>
<b>New Outdoor Pool</b>	Total Capital Cost	Total Revenue	Total Expense	Cost Recovery
	<b>\$5,500,000</b>	<b>\$135,467</b>	<b>\$274,952</b>	<b>49%</b>
<b>Spraypad</b>	Total Capital Cost	Total Revenue	Total Expense	Cost Recovery
	<b>\$1,100,000</b>	<b>\$0</b>	<b>\$31,176</b>	<b>0%</b>

AUDIT

STUDY

DESIGN

OPERATE

WEB-APPS

COUNSILMANHUNSAKER.COM



# General Limiting Conditions

This study is based on information that was current as of January 2021. Every reasonable effort has been made in order that the data reflects the most timely and current information possible and is believed to be reliable. This study is based on estimates, assumptions, and other information developed by the consultant from independent research.

No warranty or representation is made by the consultant that any of the projected values or results contained in this study will actually be achieved. No responsibility is assumed for inaccuracies in reporting by the client, its agents, and representatives or any other data source used in preparing or presenting this study.

This entire report is qualified and should be considered in light of the above conditions and limitations.

AUDIT



STUDY



DESIGN




OPERATE



WEB-APPS



COUNSILMANHUNSAKER.COM



City of Beaumont, California

Beaumont Plunge Pool Study

January 2021



AUDIT

STUDY

DESIGN

OPERATE

WEB-APPS

COUNSILMANHUNSAKER.COM

