


# Albion, NE

Fin Folk Underwater Services

## Diagram legend

|                |                                                                                   |
|----------------|-----------------------------------------------------------------------------------|
| Overflow       |  |
| Entry hatch    |  |
| Inlet/Outlet   |  |
| Vent           |  |
| Safety railing |  |
| Center Tube    |  |
| Tower Door     |  |



# Tank information

- Year built 2000
- Max capacity- 300,000 gallons
- Type- pedosphere
- Height-80ft



# Tower entry door

- Location- 12
- Rust grade- 8
- The door appears to be in good condition with little to no rusting or coating failures.



# Exterior base

- Location- 12
- Rust grade- 9
- Base appears to be in very good condition with little to no rust, pitting, or coating failures.



# Exterior wall

- Location- 3
- Rust grade- 9
- Wall appears to be in very good condition with little to no rust, pitting, or coating failures.



# Exterior base

- Location- 3
- Rust grade- 9
- Base appears to be in very good condition with little to no rust, pitting, or coating failures.



# Exterior wall

- Location- 6
- Rust grade- 9
- Wall appears to be in very good condition with little to no rusting, pitting, or coating failures.



# Exterior base

- Location- 6
- Rust grade- 9
- Base appears to be in good condition with little to no rust, pitting, or coating failures.



# Overflow

- Location- 8
- Rust grade- 8
- Overflow appears to be in good condition with some minor surface rust, no pitting.
- Has fine mesh covering opening to keep bugs and animals out.



# Exterior wall

- Location- 9
- Rust grade- 9
- Wall appears to be in good condition with little to no rust, pitting, or coating failures.



# Exterior base

- Location- 9
- Rust grade- 9
- Base appears to be in very good condition with little to no rust, pitting, or coating failures.



# Common inlet/outlet pipe

- Location- center
- Rust grade-8
- Inlet/outlet pipe appears to be in good condition from what I could see.
- Has heat shield that is properly assembled.



# Center Tube Hatch

- Location- Center
- Rust grade- 8
- Center tube appears to be in good condition with little to no rust, pitting or coating failures.
- Has fine mesh.




# Center tube ladder

- Location- Center
- Rust Grade- 9
- Center tube ladder appears to be in very good condition with little to no rust, pitting, or coating failures.



# Entry Hatch

- Location- center
- Rust grade- 8
- Entry hatch appears to be in good condition with little to no rust, pitting, or coating failures.
- Has minor staining.
- Has fine mesh.



# VENT

- Location-9
- Rust grade- 9
- Vent appears to be in very good condition with little to no rust, pitting, or coating failures.
- Has fine mesh to prevent bugs form entering water.



# Light post

- Location- center
- Rust grade- 9
- Light appears to be in very good condition with everything properly put together.



# Tower ceiling

- Location- 12
- Rust grade- 9
- Ceiling appears to be in very good condition with little to no rust, pitting, coating failures, or deformities.




# Tower ceiling

- Location- 3
- Rust grade- 9
- Ceiling appears to be in very good condition with little to no rust, pitting, coating failures, or deformities.



# Tower ceiling

- Location- 6
- Rust grade- 9
- Ceiling appears to be in very good condition with little to no rust, pitting, coating failures, or deformities.




# Tower ceiling

- Location- 9
- Rust grade- 9
- Ceiling appears to be in very good condition with little to no rust, pitting, coating failures, or deformities.



# Interior ladder

- Location- Center
- Rust Grade- 9
- Interior ladder appears to be in very good condition with little to no rust, pitting, or coating failures.



# Floor

- Location- 12
- Rust grade- 9
- Floor appears to be in very good condition with little to no rust or deformities.



# Common inlet/outlet

- Location- 11
- Rust grade- 9
- Common inlet/outlet appears to be in very good condition with little to no rust or deformities.



# Floor

- Location- 3
- Rust grade- 9
- Floor appears to be in very good condition with little to no rust or deformities.



# Manway

- Location- 6
- Rust grade- 9
- Manway appears to be in very good condition with little to no rust or deformities.



# Wall

- Location- 12
- Rust grade- 9
- Wall appears to be in very good condition with little to no rust or deformities.



# Wall

- Location- 3
- Rust grade- 9
- Wall appears to be in very good condition with little to no rust or deformities.



# Wall

- Location- 6
- Rust grade- 9
- Wall appears to be in very good condition with little to no rust or deformities.




# Wall

- Location- 9
- Rust grade- 9
- Wall appears to be in very good condition with little to no rust or deformities.



# Center Tube

- Location- Center
- Rust Grade- 9
- Center Tube appears to be in very good condition with little to no rust, pitting, or coating failures.



# Recommendations

- Maintain a regular cleaning cycle of 3-5 years.
- There are quite a few fly's on the inside of the center tube.
- On behalf of Fin Folk we would like to thank the city of Albion for choosing us for all your underwater needs.
- If you have any questions feel free to call 760-224-8232.