

Notice of Hazards & Employer Action Taken

Company: Town of Alpine

Location: 291 Buffalo Drive Afton WY 83128- 2 shops

WC Policy #: 000156321
10/14/2025

Visit Date: _____

Abatement Due Date: 11/26/2025

Employer Signature & Date: _____

(Please sign when all abatements are completed)


Hazard #1	Hazard Location:	Waste water shed (not in service)		
Hazard Description:	Walking surface with no leading-edge protection, greater than 4 ft	Picture:		
Hazards Reference:	1910.28(b)(1)(i) Except as provided elsewhere in this section, the employer must ensure that each employee on a walking-working surface with an unprotected side or edge that is 4 feet (1.2 m) or more above a lower level is protected from falling by one or more of the following: 1910.28(b)(1)(i)(A) Guardrail systems			
Corrective Action Taken:				
Action Taken to Prevent Recurrence:				
Date Corrected		Abated on Site		

Hazard #2	Hazard Location:	Waste water shed (not in service)		
Hazard Description:	Open grating on vessel deeper than 4ft.	Picture:		
Hazards Reference:	<u>1910.22(d)(2)</u> Hazardous conditions on walking-working surfaces are corrected or repaired before an employee uses the walking-working surface again. If the correction or repair cannot be made immediately, the hazard must be guarded to prevent employees from using the walking-working surface until the hazard is corrected or repaired			
Corrective Action Taken:				
Action Taken to Prevent Recurrence:				
Date Corrected		Abated on Site		

Hazard #3	Hazard Location:	Waste water shed (not in service)		
Hazard Description:	Missing handrail for stairs leading to the underground vessel	Picture:		
Hazards Reference:	<u>1910.28(b)(11)(ii)</u> Each flight of stairs having at least 3 treads and at least 4 risers is equipped with stair rail systems and handrails.			
Corrective Action Taken:				
Action Taken to Prevent Recurrence:				
Date Corrected		Abated on Site		

Hazard #4	Hazard Location:	Waste Water building		
Hazard Description:	Missing eye wash inspections-weekly		Picture:	
Hazards Reference:	<u>1910.151(c)</u> Where the eyes or body of any person may be exposed to injurious corrosive materials, suitable facilities for quick drenching or flushing of the eyes and body shall be provided within the work area for immediate emergency use.			
Corrective Action Taken:				
Action Taken to Prevent Recurrence:				
Date Corrected		Abated on Site		

Hazard #5	Hazard Location:	Waste Water building		
Hazard Description:	Missing load limits om ladders		Picture:	
Hazards Reference:	1910.23(c)(3) Ladders are not loaded beyond the maximum intended load; Note to paragraph (c)(3): The maximum intended load, as defined in § 1910.21(b), includes the total load (weight and force) of the employee and all tools, equipment, and materials being carried.			
Corrective Action Taken:				
Action Taken to Prevent Recurrence:				
Date Corrected		Abated on Site		

Hazard #6	Hazard Location:	Waste Water building		
Hazard Description:	No annual inspection on overhead crane/hoist lift	Picture:		
Hazards Reference:	1910.179(j)(1)(ii) Inspection procedure for cranes in regular service is divided into two general classifications based upon the intervals at which inspection should be performed. The intervals in turn are dependent upon the nature of the critical components of the crane and the degree of their exposure to wear, deterioration, or malfunction. The two general classifications are herein designated as "frequent" and "periodic" with respective intervals between inspections as defined below: - Frequent inspection - Daily to monthly intervals - Periodic inspection - 1 to 12-month intervals.			
Corrective Action Taken:				
Action Taken to Prevent Recurrence:				
Date Corrected		Abated on Site		

Hazard #7	Hazard Location:	Waste Water building		
Hazard Description:	No known SDS sheets for chemicals on site		Picture:	N/A
Hazards Reference:	1910.1200(b)(3)(ii) Employers shall maintain any safety data sheets that are received with incoming shipments of hazardous chemicals, and ensure that they are readily accessible during each work shift to employees when they are in their work areas			
Corrective Action Taken:				
Action Taken to Prevent Recurrence:				
Date Corrected		Abated on Site		

Hazard #8	Hazard Location:	Waste Water building			
Hazard Description:	Missing EXIT signs		Picture:		
Hazards Reference:	1910.37(b)(2) Each exit must be clearly visible and marked by a sign reading "Exit."				
Corrective Action Taken:					
Action Taken to Prevent Recurrence:					
Date Corrected		Abated on Site			

Hazard #9	Hazard Location:	Waste Water building		
Hazard Description:	Lock-Out/Tag-Out program controls for energy isolation need to be in place prior to any work taking place on electrical equipment	Picture:		
Hazards Reference:	<u>1910.147(a)(3)(i)</u> This section requires employers to establish a program and utilize procedures for affixing appropriate lockout devices or tagout devices to energy isolating devices, and to otherwise disable machines or equipment to prevent unexpected energization, start-up or release of stored energy in order to prevent injury to employees.			
Corrective Action Taken:				
Action Taken to Prevent Recurrence:				
Date Corrected		Abated on Site		