

Front of building showing gable end view. Previous owner had replaced with vinyl sliding windows. Looking to replace with Pella wood clad 6/6 double hung windows to look more to the original windows.



Left side view along driveway, windows are in poor condition, many rotted and/or inoperable. Looking to replace with Pella wood clad 6/6 double hung windows.



View of one of many rotted windows in poor condition.



Close up view of existing vinyl windows.



Rear of house.



474 and 484 Thames St Bristol RI Page 5



Existing rear sliding door. Looking to replace with 36" French door 9 lite.



Evidence of original windows along the right side of the house that were previously boarded up. 6 on 1st floor, 6 on second floor. Proposing to reinstall with matching Pella wood clad 6/6 double hung windows. Same size and style windows as the left and rear sides.



Another view of previously boarded up window.



Interior view of existing windows. These windows are not original to the house.



Interior view of existing vinyl sliders. Proposed to replace with Pella wood clad 6/6 double hung windows.

Window count and sizes:

1st floor:

11 windows 30"x55"

1 exterior door 36"x80" 9 lite fiberglass door

2nd floor:

11 windows 30"x55"

2 windows 72"x 55"

1 exterior door 36"x80" 9 lite fiberglass door

3rd floor:

2 41"x60"

1 36"x41"

1 exterior door 36"x80" 9 lite fiberglass door