

EXTERIOR VIEWS



View from the North (across Constitution St.)



View from the Northwest (near intersection of Constitution and Thames)

EXTERIOR VIEWS



View from the Southwest (Thames St.)



View from the South

EXTERIOR VIEWS



West Elevation



Side Door



Box Bay

EXTERIOR DETAILS



Front Porch



Front Entry



Decking/Columns



Exposed Rafter Tails & Tripled Shingles over window



Garage/Driveway

WINDOWS

- Predominantly single hung, single pane wood windows with diamond light pattern in top sash and aluminum frame storm windows.
- East elevation = 2-over-1 divided light pattern (bathroom, kitchen, stair, living room)
- Many are inoperable due to misalignment in frames and/or broken sash weight cords. Some have broken/chipped muntins; cracked/loose/missing glazing compound; and broken glass.



Missing sash cords



Broken muntin



Cracked/missing glazing compound



2-over-1 window (east elevation)



Exterior trim(split)/Storm Window