



## 2.8 PORCHES

## ₾ POOR

Item 1-3 (Picture) Moisture intrusion into rear porch floor with decay. Rear porch is not structurally safe. Recommend having evaluated and repaired by a licensed construction company.



