

## EXTERIOR VIEWS



View from the North (across Constitution St.)



View from the Northwest (near intersection of Constitution and Thames)



## EXTERIOR VIEWS



View from the Southwest (Thames St.)



View from the South



## EXTERIOR VIEWS



West Elevation



Side Door



Box Bay



## EXTERIOR DETAILS



Front Porch



Front Entry



Decking/Columns



Exposed Rafter Tails & Tripled Shingles over window



Garage/Driveway



## WINDOWS

- Predominantly single hung, single pane wood windows with diamond light pattern in top sash and aluminum frame storm windows.
- East elevation = 2-over-1 divided light pattern (bathroom, kitchen, stair, living room)
- Many are inoperable due to misalignment in frames and/or broken sash weight cords. Some have broken/chipped muntins; cracked/loose/missing glazing compound; and broken glass.



Missing sash cords



Broken muntin





Cracked/missing glazing compound



2-over-1 window (east elevation)



Exterior trim(split)/Storm Window