

Caseday Services, LLC

21212 NE 72nd AVE
 Battle Ground, WA 98604

360-931-0859

PROPERTY INFORMATION

Dale E Anderson
 Location: 4550 SW 5th AV
 CAMAS
 Tax ID: 127155000 Lot:
 Use: Residential, Single Family

ON ID: ON0008701

Mail To: Dale E Anderson
 14707 SE Rivershore Dr
 Vancouver, WA
 98684

ON-SITE WASTEWATER TREATMENT SYSTEM INSPECTION REPORT

Inspected: 11/01/2019 - Inspection Type: ROUTINE - Correction Status: All corrections made

Company: Certification - Level 2
 Caseday Services, LLC

Work Performed By:
 Justin Caseday

Submitted 11/01/2019 by:
 Justin Caseday

COMMENTS & GENERAL INSPECTION NOTES

Deficiencies Were Noted: Corrections were made to resolve the deficiencies.

Tanks pumped same day. Found check valve on pump was cracked and leaking, replaced with new check valve.

All accessible components were inspected, secure and in good condition at time of inspection.

Caseday Services, LLC DBA Caseday Septic Services assumes no liability for future performance or problems with system .

GENERAL SITE & SYSTEM CONDITIONS

The General Site and System Conditions were:	Fully Inspected
All Components accessible for maintenance, secure and in good condition:	YES
Surfacing effluent from any component (including mound seepage):	NO
Components appear to be watertight - no visual leaks:	YES
Improper encroachment (roads, buildings, etc.) onto component(s):	NO
Component settling problems observed:	NO
Abnormal ponding present for one or more of the disposal components:	N/A
Subsurface components adequately covered	YES
Site maintenance required (e.g. Landscape maintenance) If yes, describe in comments:	NO

ONSITE SEWAGE SYSTEM INSPECTION DETAIL

TANK: Septic Tank - 2 Compartment D&K 5 lid, Risers about 8" below grade

This component was:	Fully Inspected	
Component appears to be functioning as intended:	YES	
Effluent level within operational limits (if NO explain in comments):	YES	
All required baffles in place (N/A = No baffles required):	YES	
Effluent Filter Cleaned (N/A = Not Present):	N/A	
Compartment 1 Scum accumulation (Inches, if other specify):	14	
Compartment 1 Sludge accumulation (Inches, if other specify):	10	
Compartment 2 Scum accumulation (Inches, if other specify):	0	
Compartment 2 Sludge accumulation (Inches, if other specify):	8	
Pumping needed:	YES	Corrected
Approximate Gallons to be pumped (if needed) by Certified Pumper:		

TANK: Pump Basin Riser to grade

This component was:	Fully Inspected	
Component appears to be functioning as intended:	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	0	
Compartment 1 Sludge accumulation (Inches, if other specify):	6	
Pumping needed:	YES	Corrected
Approximate Gallons to be pumped (if needed) by Certified Pumper:		

Pump: Effluent Pump		
This component was:	Fully Inspected	
Component appears to be functioning as intended:	NO	Corrected
Controls functioning:	YES	
Pump Vault Filter cleaned (N/A = not present):	N/A	
One-minute draw down test result (inches):	6	
Distribution: D-Box no access		
This component was:	Not Inspected	
D-Box in good condition:		
D-Box outlets set to allow equal effluent distribution:		
Drainfield (disposal): Gravity		
This component was:	Fully Inspected	
Component appears to be functioning as intended:	YES	
Ponding present? If YES explain in comments:	N/A	

Caseday Services, LLC

21212 NE 72nd AVE
Battle Ground, WA 98604

360-931-0859

PROPERTY INFORMATION

Location: 4420 SW 5th AV
CAMAS
Tax ID: 127155005 Lot:

Use:

ON ID: ON0000855

Mail To:

Fold Here

Fold Here

ON-SITE WASTEWATER TREATMENT SYSTEM INSPECTION REPORT

Inspected: 11/01/2019 - Inspection Type: ROUTINE - Correction Status: All corrections made

Company: Certification - Level 2
Caseday Services, LLC

Work Performed By:
Justin Caseday

Submitted 11/01/2019 by:
Justin Caseday

COMMENTS & GENERAL INSPECTION NOTES

Deficiencies Were Noted: Corrections were made to resolve the deficiencies.

Pumped tanks same day.

All accessible components were inspected, secure and in good condition at time of inspection.

Caseday Services, LLC DBA Caseday Septic Services assumes no liability for future performance or problems with system .

GENERAL SITE & SYSTEM CONDITIONS

The General Site and System Conditions were:	Fully Inspected
All Components accessible for maintenance, secure and in good condition:	YES
Surfacing effluent from any component (including mound seepage):	NO
Components appear to be watertight - no visual leaks:	YES
Improper encroachment (roads, buildings, etc.) onto component(s):	NO
Component settling problems observed:	NO
Abnormal ponding present for one or more of the disposal components:	N/A
Subsurface components adequately covered	YES
Site maintenance required (e.g. Landscape maintenance) If yes, describe in comments:	NO

ONSITE SEWAGE SYSTEM INSPECTION DETAIL

TANK: Septic Tank - 2 Compartment Risers to grade		
This component was:	Fully Inspected	
Component appears to be functioning as intended:	YES	
Effluent level within operational limits (if NO explain in comments):	YES	
All required baffles in place (N/A = No baffles required):	YES	
Effluent Filter Cleaned (N/A = Not Present):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	14	
Compartment 1 Sludge accumulation (Inches, if other specify):	10	
Compartment 2 Scum accumulation (Inches, if other specify):	0	
Compartment 2 Sludge accumulation (Inches, if other specify):	8	
Pumping needed:	YES	Corrected
Approximate Gallons to be pumped (if needed) by Certified Pumper:		
TANK: Pump Tank Riser to grade		
This component was:	Fully Inspected	
Component appears to be functioning as intended:	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	0	
Compartment 1 Sludge accumulation (Inches, if other specify):	4	
Pumping needed:	YES	Corrected
Approximate Gallons to be pumped (if needed) by Certified Pumper:		

Pump: Effluent Pump		
This component was:	Fully Inspected	
Component appears to be functioning as intended:	YES	
Controls functioning:	YES	
Pump Vault Filter cleaned (N/A = not present):	N/A	
One-minute draw down test result (inches):	3	
Drainfield (disposal): Gravity		
This component was:	Fully Inspected	
Component appears to be functioning as intended:	YES	
Ponding present? If YES explain in comments:	N/A	