



**EASTSIDE @ Left**  
Foundation, mud sill, rim joist,  
and bottom wall plate damage



EASTSIDE @ Right  
Foundation, mud sill, rim joist, bottom  
wall plate and wall stud damage



**SOUTHSIDE @ (E) CHIMNEY**  
Foundation, mud sill, rim joist and  
bottom wall plate damage




**SOUTHSIDE @ FRONT OF BUILDING**  
Foundation, mudsill, some floor joists, rim joist, bottom wall plate and stud damage.



**NORTHSIDE**  
Foundation, mud sill, some floor joists, rim joist, bottom wall plates and stud damage.



**NORTHSIDE @ BACK OF BUILDING**  
Foundation, mud sill, rim joist, bottom  
wall plate and stud damage



WESTSIDE ON LEFT  
Foundation, mud sill,  
and rim joist repair

WEST  
ELEVATION

WESTSIDE ON RIGHT  
Foundation , mud sill, rim joist damage







**INTERIOR EASTEND  
STRUCTURE DAMAGE**  
sub floor, mud sill, and stud  
damage



**SOUTHSIDE MIDDLE OF BUILDING  
STRUCTURE DAMAGE**  
Stud damage around the (E) Window,  
(E) Vapor barrier damage



**NORTHSIDE MIDDLE BUILDING  
STRUCTURE DAMAGE**  
Damaged sub floor, vapor barrier  
and studs



**NORTHSIDE MIDDLE OF BUILDING  
STRUCTURE DAMAGE**  
Damaged Subfloor, vapor barrier, bottom  
plate and studs



INTERIOR EASTEND OF  
BUILDING LEFT  
Deteriorated vapor barrier,  
damaged studs



INTERIOR EASTEND OF  
BUILDING RIGHTSIDE  
Vapor Barrier Deteriorated



INTERIOR SOUTH SIDE OF BUILDING  
Vapor Barrier Deterioration, Stud  
Replacement



**SOUTHSIDE OF BUILDING**  
Vapor Barrier Deteriorated,  
Studs replacement around window.





**SOUTHSIDE OF BUILDING**  
Window trim replacement,  
siding replacement



**SOUTHSIDE OF BUILDING**  
Window trim & siding damage




**(E) SOUTHSIDE SIDING**  
Damage to siding and eve tails



SOUTHSIDE EVE  
Example of damaged eave tails  
and roof boards



(E) CHIMNEY DAMAGE WESTSIDE  
Separation of mortar from lower brick.  
This is on three sides.



(E) CHIMNEY ON SOUTHSIDE  
Separation of mortar from lower brick



(E) CHIMNEY EASTSIDE  
Separation of mortar from lower brick



(E) CHIMNEY  
(E) Mortar is failing and  
crumbling