



Elevated deck
boards create a
potential hazard
for guests



Wood treads
contain
exposed nails
and splintered
areas



Tread wear
observed near
the top of both
staircases





Areas of wood decay identified, though the structure is still sound