COLUMBUS WATER & LIGHT CUSTOMER OUTAGE REPORT SUBSTATION CIRCUIT #		
	CAUSE	TRANSFORMER FAILURE
PART THAT FAILED	0 Unknown	INAMSPORIVER PAILURE
(O None	1 Loss of supply	CWL# KVA
1 Numerous	2 Operating error	CVISII RVII
2 Other-note in remarks	3 Circuit overload	MFG AGE (est)
3 Transmission equipment	4 Mis-coordination	102 (031)
4 Substation equipment	5 Faulty installation	Serial #
O.H. DISTRIBUTION	6 Lightning	John III
10 Anchor or guy	7 Wind	Arrester ON / OFF Tank (circle one)
11 Arrester	8 Ice	imester of the office one)
12 Conductor – Primary	9 Cold weather	ARRESTOR FAILURE
13 " - Secondary	10 Hot Weather	
14 Connector	11 Moisture	MFR Porc Polymer
21 Insulator	12 Contamination	MFR Porc Polymer Riser Line Transformer
24 Metering equipment	13 Fire	(circle all that apply)
25 Pole	14 Extreme storm	(care and anim expers)
26 Recloser		DEVICE THAT OPENED
27 Riser or Jumper	FOREIGN OBJECTS	Distribution
28 Splice	20 Vehicles	Main Feeder
29 Switch - GOAB	22 Trees – tore down	· ·
30 " - Disc.	23 Trees – shorted	Breaker Counter
(31) Cutout - Fused	24 Animals	
32 Transformer – Line	25 Birds	Targets
33 Transformer – Potential	26 Underground dig in	1
<u>U.G. DISTRIBUTION</u>	27 Vandalism	Branch Line
50 Arrester	28 Other	O.C.R. Size Size Size
51 Conductor – Primary		Fuse 50/ Size
52 " - Secondary	EQUIPMENT	
53 Connector – Bolted	30 Manufacturing defect	Transformer
54 " - Comp.	31 Equipment overload	Fuse Transf. Size
55 " - Elbow	32 Electrical failure	
56 " - Splice	33 Worn out	ROUTING (initial)
59 Terminator		
60 Transformer – Pad Mount	(use 24 hour time)	Responded By
61 Transformer – Bayonet Fuse	620	Responded By Line Assisted By Mason Made 19
62 Metering Equipment	TIME OFF STON 520	Line Assisted By Mason Mashle
WEATHER	Number of Calls 1	Assisted By
Normal	rumber of cans <u>1</u>	
2 Wind	Number of Minutes	Manager
3 Thunderstorm	Customers Duration	
4 Rain		Outage File
5 Rain and wind	1 / 9 39	
6 Fog		
7 Ice		
8 Ice and wind		
9 Snow		
10 Extreme cold		
11 Extreme heat		

12 Extreme storm