



Elevated deck boards create a potential hazard for guests



Wood treads contain exposed nails and splintered areas



Tread wear
observed near
the top of both
staircases





Areas of wood decay
identified, though the
structure is still sound