

501 Vienna



- 1.
2. South Elevation



East Elevation



West Elevation



North Elevation



3)Explanation of Work:

Replace the two 1970's era aluminum windows with a more period correct set of casement windows. Add back door with period correct door – original if possible, or quality wood/steel door - as original door was eliminated with this more recent addition of the house.

4)Diagram of work:





5) Material Information / Window/Door Detail



Doors, though most likely this will be a single door, not double:



6)Rational: These changes will eliminate 1970's aluminum windows and add back much nicer, more expensive, period correct windows. While the house originally had two back doors, they have both been eliminated by the latest addition – which appears to be from the 70's. We would like to add back the function of the original house – access to the back yard.