

**BLACK HILLS COLLISION PROS**

Workfile ID:

066c45b7

209 W HUDSON AVE, SPEARFISH, SD 57783

Phone: (605) 642-2020

FAX: (605) 642-3420

**Preliminary Estimate****Customer: Police Department, Deadwood****Job Number:**

Written By: Beau Hamilton

Insured: Police Department, Deadwood Policy #: Claim #:

Type of Loss: Date of Loss: Days to Repair: 0

Point of Impact: 12 Front

**Owner:**

Police Department, Deadwood  
100 Sherman St  
Deadwood, SD 57732  
(605) 578-2623 Business

BLACK HILLS COLLISION PROS  
209 W HUDSON AVE  
SPEARFISH, SD 57783  
Repair Facility  
(605) 642-2020 Business

**Insurance Company:****VEHICLE**

2021 DODG Durango Pursuit AWD (Fleet) 4D UTV 8-5.7L Gasoline Sequential MPI

|                        |                  |              |              |
|------------------------|------------------|--------------|--------------|
| VIN: 1C4SDJFT3MC695602 | Interior Color:  | Mileage In:  | Vehicle Out: |
| License:               | Exterior Color:  | Mileage Out: |              |
| State:                 | Production Date: | Condition:   | Job #:       |

**TRANSMISSION**

Automatic Transmission

4 Wheel Drive

**POWER**

Power Steering

Power Brakes

Power Windows

Power Locks

Power Mirrors

Heated Mirrors

Power Driver Seat

**DECOR**

Dual Mirrors

Privacy Glass

Console/Storage

Overhead Console

**CONVENIENCE**

Air Conditioning

Intermittent Wipers

Tilt Wheel

Cruise Control

Rear Defogger

Keyless Entry

Message Center

Steering Wheel Touch Controls

Rear Window Wiper

Telescopic Wheel

Climate Control

Dual Air Condition

Backup Camera

Parking Sensors

**RADIO**

AM Radio

FM Radio

Stereo

Search/Seek

Auxiliary Audio Connection

Satellite Radio

**SAFETY**

Drivers Side Air Bag

Passenger Air Bag

Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Traction Control

Stability Control

Front Side Impact Air Bags

Head/Curtain Air Bags

Hands Free Device

Xenon or L.E.D. Headlamps

**SEATS**

Cloth Seats

Bucket Seats

Reclining/Lounge Seats

**WHEELS**

Styled Steel Wheels

**PAINT**

Clear Coat Paint

**OTHER**

Rear Spoiler

California Emissions

**TRUCK**

Rear Step Bumper

**Preliminary Estimate**

**Customer: Police Department, Deadwood**

**Job Number:**

2021 DODG Durango Pursuit AWD (Fleet) 4D UTV 8-5.7L Gasoline Sequential MPI

| Line                  | Oper | Description                      | Part Number | Qty             | Extended Price \$ | Labor       | Paint |
|-----------------------|------|----------------------------------|-------------|-----------------|-------------------|-------------|-------|
| <b>1 FRONT BUMPER</b> |      |                                  |             |                 |                   |             |       |
| 2                     |      | O/H front bumper                 |             |                 |                   | 3.1         |       |
| 3                     | Repl | Lower grille w/pursuit           | 7EJ44RXFAA  | 1               | 99.70             | Incl.       |       |
| 4                     | Repl | Bumper cover w/o prk aid         | 68510292AD  | 1               | 684.00            | Incl.       | 3.0   |
| 5                     |      | Add for Clear Coat               |             |                 |                   |             | 1.2   |
| <b>6 GRILLE</b>       |      |                                  |             |                 |                   |             |       |
| 7                     | Repl | Grille SXT, CITADEL, PURSUIT     | 6UZ19MALAA  | 1               | 445.00            | Incl.       |       |
| 8                     | #    | Subl Hazardous waste removal     |             | 1               | 7.00 T            |             |       |
| 9                     | #    | Repl Flex additive               |             | 1               | 5.00 T            |             |       |
| 10                    | #    | Repl Corrosion protection primer |             | 1               | 7.00 T            | 0.3         |       |
| <b>11 HOOD</b>        |      |                                  |             |                 |                   |             |       |
| 12                    | **   | Repl A/M CAPA Hood (ALU)         | 55369453AF  | 1               | 793.00            | 1.9         | 3.0   |
| 13                    |      | Add for Clear Coat               |             |                 |                   |             | 1.2   |
| 14                    |      | Add for Underside(Complete)      |             |                 |                   |             | 1.5   |
| 15                    |      | Add for Clear Coat               |             |                 |                   |             | 0.3   |
| <b>SUBTOTALS</b>      |      |                                  |             | <b>2,040.70</b> | <b>5.3</b>        | <b>10.2</b> |       |

**ESTIMATE TOTALS**

| Category           | Basis      | Rate         | Cost \$         |
|--------------------|------------|--------------|-----------------|
| Parts              |            |              | 2,021.70        |
| Body Labor         | 5.3 hrs @  | \$ 78.00 /hr | 413.40          |
| Paint Labor        | 10.2 hrs @ | \$ 78.00 /hr | 795.60          |
| Paint Supplies     | 10.2 hrs @ | \$ 60.00 /hr | 612.00          |
| Miscellaneous      |            |              | 19.00           |
| <b>Subtotal</b>    |            |              | <b>3,861.70</b> |
| <b>Grand Total</b> |            |              | <b>3,861.70</b> |

THIS ESTIMATE MAY BE BASED IN WHOLE OR IN PART UPON THE PAINTLESS DENT REPAIR METHOD. EACH ITEM OF DAMAGE ADJUSTED USING THAT METHOD IS IDENTIFIED ON THE ESTIMATE. THE PAINTLESS DENT REPAIR METHOD MAY NOT BE THE APPROPRIATE REPAIR METHOD FOR ALL TYPES OF DAMAGE. IF AN INSURER IS LIABLE FOR THE DAMAGE LISTED ON THE ESTIMATE, THE INSURER SHALL PROVIDE SUFFICIENT COMPENSATION TO RESTORE THE VEHICLE TO SUBSTANTIALLY THE SAME PHYSICAL CONDITION. FOR ANY DAMAGE WHERE IT IS APPROPRIATE TO REPAIR THE VEHICLE USING THE PAINTLESS DENT REPAIR METHOD, THE INSURED MAY CHOOSE NOT TO REPAIR THE VEHICLE OR CHOOSE TO HAVE THE VEHICLE REPAIRED USING A DIFFERENT METHOD OF REPAIR. IF THE INSURED CHOOSES EITHER OF THESE OPTIONS, THE INSURER IS LIABLE ONLY FOR THE COST OF THE PAINTLESS DENT REPAIR METHOD.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THESE PARTS RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.

**Customer: Police Department, Deadwood****Job Number:**

2021 DODG Durango Pursuit AWD (Fleet) 4D UTV 8-5.7L Gasoline Sequential MPI

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR3TG11, CCC Data Date 01/16/2026, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (\*) or Double Asterisk (\*\*) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

**SYMBOLS FOLLOWING PART PRICE:**

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category.

X=Miscellaneous Non-Taxed charge category.

**SYMBOLS FOLLOWING LABOR:**

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category.

M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

**OTHER SYMBOLS AND ABBREVIATIONS:**

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel.

CAPA=Certified Automotive Parts Association. CFC=Carbon Fiber.

D&amp;R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part.

O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&amp;I=Remove and Install. R&amp;R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. STS=Stainless Steel. Subl=Sublet.

UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Solutions Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

**Preliminary Estimate****Customer: Police Department, Deadwood****Job Number:**

2021 DODG Durango Pursuit AWD (Fleet) 4D UTV 8-5.7L Gasoline Sequential MPI

**PARTS SUPPLIER LIST**

| <b>Line</b> | <b>Supplier</b>   | <b>Description</b>  | <b>Price</b> |
|-------------|---|---|--------------|
| 12          | Sturdevant's Refinish Supply<br>2601 S Shirley Ave.<br>Sioux Falls SD 57106<br>(605) 362-6950 | #CH1230286C<br>A/M CAPA Hood (ALU)<br>Quote: 18206758008<br>Expires: 12/19/25 | \$ 793.00    |