# Mack's Auto Body LLC

3120 4th Ave Spearfish, SD 57783

605-642-4143 Phone 605-644-1343 Fax

## **Invoice**

Date	Invoice #
9/17/2024	2024-062

Bill To ATTN ACCOUNTS PAYABLE CITY OF DEADWOOD 102 SHERMAN DEADWOOD SD 57732

Description		Amount
Auto Body Parts, Materials & Labor - Lornie Stalder authorized repairs 2020 RAM ProMaster Cargo Van VIN 3C6TRVNG5LE146211 Final Bill \$12953.65 Vehicle released to Lornie Stalder on Sept 6, 2024		12,953.65
Initial repair estimate \$6680.20 (First ins payment mailed to the City less \$2500 deductible =\$4180.20) Supplement \$6273.45 (City should have supplement check by now)  Any questions for Claims Associates, please call Ethan Kellett, Adjuster @ Claims Assoc (605) 275-528	1	
Municipality/Sales Tax Exempt		0.00
Please pay from this invoice.		0.00
If you have any questions, please call. Sincerely, Jeneen Mack (605) 642-4143		
Submitted by Jerewmack		
Submitted by Greenmack Mack's auto Body LLC		
Thank you!		
	Total	\$12,953.65



#### **MACK'S AUTO BODY LLC**

Workfile ID: PartsShare: 1d74b669 7SvN9W

Federal ID: Resale Number:

27-1557205 1022-2799-ST

Where Quality & Craftsmanship Come Together 3120 4TH AVE, SPEARFISH, SD 57783 Phone: (605) 642-4143

FAX: (605) 644-1343

**Customer: CITY OF DEADWOOD** 

Job Number:

Written By: Eugene Mack

Insured:

CITY OF DEADWOOD

Policy #:

Claim #:

GC2024119068

Type of Loss:

Point of Impact:

Date of Loss:

Days to Repair: 0

Owner:

CITY OF DEADWOOD 102 SHERMAN STREET DEADWOOD, SD 57732 (605) 641-7745 Cell

**Inspection Location:** 

MACK'S AUTO BODY LLC

3120 4TH AVE

SPEARFISH, SD 57783

Repair Facility

(605) 642-4143 Business

**Insurance Company:** 

**VEHICLE** 

2020 RAM ProMaster Cargo Van 1500 Low Roof 118" WB 3D VAN 6-3.6L Gasoline Sequential MPI SILVER

VIN:

3C6TRVNG5LE146211

Interior Color:

Mileage In:

Vehicle Out:

License: CTY0623

Exterior Color:

**SILVER** 

Mileage Out:

State:

SD

Production Date:

Condition:

Job #:

**TRANSMISSION** 

**Automatic Transmission** 

**POWER** 

Power Steering Power Brakes **Power Windows** 

Power Locks

**Power Mirrors DECOR** 

**Dual Mirrors** 

**Body Side Moldings** Tinted Glass

**CONVENIENCE** 

Air Conditioning Intermittent Wipers

Tilt Wheel

Keyless Entry Message Center

Steering Wheel Touch Controls

Telescopic Wheel Backup Camera

**RADIO** 

AM Radio FM Radio

Stereo

Search/Seek

**Auxiliary Audio Connection** 

**SAFETY** 

Drivers Side Air Bag Passenger Air Bag Anti-Lock Brakes (4) 4 Wheel Disc Brakes

Traction Control Stability Control

Front Side Impact Air Bags

Head/Curtain Air Bags

Hands Free Device

**SEATS** Cloth Seats

**Bucket Seats** 

Reclining/Lounge Seats

WHEELS

Styled Steel Wheels

PAINT

Clear Coat Paint

**OTHER** 

Signal Integrated Mirrors

California Emissions

### **Customer: CITY OF DEADWOOD**

Job Number:

2020 RAM ProMaster Cargo Van 1500 Low Roof 118" WB 3D VAN 6-3.6L Gasoline Sequential MPI SILVER

Line		Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	FRONT BUMPE	R&G	RILLE			rice \$		
2		R&I	R&I bumper cover as an assy				2.2	
3	FRONT LAMPS				***************************************	The same of the sa	E,E	
4		R&I	RT Headlamp assy w/o daytime run lamp				Incl.	
5		R&I	RT Headlamp bezel lower				Incl.	
6	FENDER			1.00	The state of the s	A Marie	IIICI.	
7	*	Blnd	RT Fender (HSS)					0.0
8	RESTRAINT SY	STEMS	S	The second secon				0.8
9		Repl	RT Pressure sensor	68170696AA	1	67.45 m	0.2 M	
			Note: Part # changes to 68304326AA		_	57115 III	0.2 14	
10			Air bag system diagnosis			m	0.5 M	
11	PILLARS, ROCK	(ER &	FLOOR	A STATE OF THE STA			0.5 14	
12		Repl	RT Body side mldg	1ZT47LAHAA	1	131.00	0.2	
13	*		RT Center pillar right	68100631AB	1	454.00	5.0	2.5
14			RT Aperture panel	68167373AA	1	<del>131.00</del> 544.00		2.5
15			Add for Clear Coat	0010/0/0/0/	_	311.00	17.0	3.9
16	FRONT DOOR				**************************************			1.6
17	*	Repl	RT Door shell	68465073AC	1	<u>722.00</u>		4.5
18			Overlap Major Adj. Panel	00 10307 JAC	•	722.00	5.5	4.5
19			Add for Clear Coat					-0.4
20			Add for trnsfr glass				0.5	8.0
21			RT Nameplate "RAM 1500"	68210902AA	1	99.50	0.3	
22			RT Nameplate "ProMaster"	68211249AB	1	87.20	0.2	
23	*		RT Body side mldg	1ZT58JXWAB	1	186.00	Incl.	
24			RT Flare	IL I DOSKII I D	-	100.00	Incl.	
25	SIDE LOADING	DOOR		A consideration of the second		Acceptance of the second secon	IIICI.	
26	*		RT Door shell standard roof 118" WB w/o glass	68249804AB	1	2,365.00	3.2	6.6
27			Overlap Major Adj. Panel					-0.4
28	*		Add for Clear Coat					1.2
29			Add for trnsfr glass				0.7	-112
30		Repl	RT Body side mldg 118" WB	1ZT42LAHAA	1	306.00	Incl.	
31	#	Subl	Hazardous waste removal		1	5.00 T		
32	#	Repl	Cover Car		1	3.00 T		
33	#	Repl (	Corrosion protection primer		1	10.00 T		
34	SIDE PANEL		Accessed	end continuendado como por sur \$ acres (\$ collectivo co	and the second s		The state of the s	
35	*	Repl <u>I</u>	RT Outer rocker	68167513AA	1	224.00 s	8.5 S	1.4
36		(	Overlap Major Non-Adj. Panel				5.5 5	-0.2
37	*	,	Add for Clear Coat					0.2
38	1	Repl I	RT Body side mldg front	1ZT43LAHAA	1	328.00	0.3	0.2
39	#		RT "B" Pillar inner Panel		_		4.0	
40	* ,	Blnd F	RT Side panel				1.0	

	omer: CITY C					Job No	umber:
2020 F	RAM ProMaster Car	go Var	1500 Low Roof 118" WB 3D VAN 6-3.6L G	asoline Sequential MPI SILVER	Ł	20211	
41		R&I	RT Flare			0.0	
42		R&I	RT Body side mldg front			0.3	
43		R&I	RT Sill molding			0.2	
44	BACK DOOR				The second continues of the se	0.2	
45		R&I	RT R&I door assy				
46		R&I	RT Upper hinge body side			0.8	
			Note: LABOR: Time is after door is remove	/ed		0.3	
47	REAR LAMPS						
48		R&I	RT Tail lamp assy				
49	REAR BUMPER					0.3	
50			O/H rear bumper				
51		R&I	Bumper cover w/o reverse sensor	•		0.5	
			w/o receiver hitch			Incl.	
52		R&I	RT End cap			0.3	
53	VEHICLE DIAG	NOST	ICS	The second secon		0.5	
54	*	Rpr	Pre-repair scan		m	<u>1.0</u> M	
55	*	Rpr	Post-repair scan		m	1.0 M	
			SUB	TOTALS	5,532.15	53.1	24.3

#### **ESTIMATE TOTALS**

Category	Basis	Basis		Cost \$	
Parts	Dusis		Rate		
Body Labor				5,514.15	
10.10.00 • DOM/90044	41.9 hrs	@	\$ 75.00 /hr	3,142.50	
Paint Labor	24.3 hrs	@	\$ 75.00 /hr	1,822.50	
Mechanical Labor	2.7 hrs	@	\$ 100.00 /hr	270.00	
Structural Labor	8.5 hrs	@	\$ 100.00 /hr	850.00	
Paint Supplies	24.3 hrs	@	\$ 55.00 /hr	1,336.50	
Miscellaneous		6	Ψ 55.00 /111	•	
Subtotal				18.00	
Grand Total				12,953.65	
Grand Total				12,953.65	

THIS ESTIMATE MAY BE BASED IN WHOLE OR IN PART UPON THE PAINTLESS DENT REPAIR METHOD. EACH ITEM OF DAMAGE ADJUSTED USING THAT METHOD IS IDENTIFIED ON THE ESTIMATE. THE PAINTLESS DENT REPAIR METHOD MAY NOT BE THE APPROPRIATE REPAIR METHOD FOR ALL TYPES OF DAMAGE. IF AN INSURER IS LIABLE FOR THE DAMAGE LISTED ON THE ESTIMATE, THE INSURER SHALL PROVIDE SUFFICIENT COMPENSATION TO RESTORE THE VEHICLE TO SUBSTANTIALLY THE SAME PHYSICAL CONDITION. FOR ANY DAMAGE WHERE IT IS APPROPRIATE TO REPAIR THE VEHICLE USING THE PAINTLESS DENT REPAIR METHOD, THE INSURED MAY CHOOSE NOT TO REPAIR THE VEHICLE OR CHOOSE TO HAVE THE VEHICLE REPAIRED USING A DIFFERENT METHOD OF REPAIR. IF THE INSURED CHOOSES EITHER OF THESE OPTIONS, THE INSURER IS LIABLE ONLY FOR THE COST OF THE PAINTLESS DENT REPAIR METHOD.

Submitted by Repair Done 09/5/2024

Geneen mack

Mack's auto Body LC

Mack's auto Body LC

To Jorine Staider

AM Themk you!

436794

Page 3