








































**SUITE 440**  
**Created an indoor**  
**gutter system to divert**  
**water back outside.**













**Exposed electrical panels  
and wiring throughout  
property**



**More open electrical panels  
and unlicensed  
work**







**Rusted roof and noticeable sag**




**Southeast building  
Peeling roof insulation  
reveals roof completely  
rusted and light shining  
through.**







**Tires  
improperly  
stored.**



**Water damaged  
ceilings through out  
buildings.**