# Homer Public Safety Building

Grubstake Avenue Homer, Alaska 99603



**Date** Fri 12/06/2019

**Job** # 1809-2

Prepared By Carl Brinkerhoff





#### Weather

12:00 PM

6:00 AM

27° 🍊

30°

34°

Overcast

Wind: 8 MPH | Precipitation: .0" | Humidity: 75%

**Mostly Cloudy** 

Wind: 9 MPH | Precipitation: .01" | Humidity: 77%

Wind: 10 MPH | Precipitation: .01" | Humidity: 79%

4:00 PM

| Work Logs  |   |          |       |               |  |
|--|---|----------|-------|---------------|--|
| Name   | Description   | Quantity | Hours | Hours To Date |  |
| Consolidated Roofing   |   | 0        | 0     | 477           |  |
| Duct or Sheet Metal  |   | 0        | 0     | 12            |  |
| East Road Services   |   | 0        | 0     | 944           |  |
| Eayrs Plumbing   | Onsite continuing domestic water rough in. Carl Brinkerhoff   12/06/19   03:17PM  | 2        | 8     | 520           |  |
| Matt Hanson, Ron<br>Frazier, Tanner<br>Stengel, Chad<br>Albertsons, Ryan Fox,<br>Jim | Supervision, coordination and documentation. Crew continued setting upper level interior door frames. Continued blocking at walls for bath accessories and other devices. Continued framing at dented on area. Misc. framing for electrical panel in dispatch, fur out walls at rain leaders in dispatch and polygraph. Grinding fins and imperfections at lower level exposed concrete walls.  Carl Brinkerhoff   12/06/19   03:22PM | 7        | 8     | 5235.5        |  |
| Puffin Electric  | 2 journeyman and an apprentice onsite continuing electrical rough in mainly upper level. Roughed in power to door frames as required.  Carl Brinkerhoff   12/06/19   03:24PM  | 3        | 0     | 905.5         |  |
| Total  |   | 12       | 72    | 10737         |  |

**Time Cards** 

No entry

**Materials** No entry

#### **General Notes**

No entry


## Site Safety Observations

1. Site safety protocols were observed onsite today.  $_{\text{Carl Brinkerhoff}\,|\,12/06/19\,|\,03:26\text{PM}}$ 

#### **Quality Control Observations**

1. All materials and workmanship performed onsite today met or exceeded project specifications.

| Survey                                  |  |   |  |  |  |  |
|---|--|---|--|--|--|--|
| Questions                               | N/A No Yes Description   |   |  |  |  |  |
| 1. Any accidents on site today?         |  |   |  |  |  |  |
| 2. Any schedule delays occur?           |  |   |  |  |  |  |
| 3. Did weather cause any delays?        |  |   |  |  |  |  |
| 4. Any visitors on site?                | Pat McNary was onsite to layout control room. Person from dispatch and officer Brown were onsite to coordinate control room layout. Gentleman from ProCom was onsite this afternoon. Carl Brinkerhoff   12/06/19   03:29PM | ÷ |  |  |  |  |
| 5. Any areas that can't be worked on?   | No exterior door frames onsite yet.  Carl Brinkerhoff   12/06/19   03:29PM   |   |  |  |  |  |
| <b>6.</b> Any equipment rented on site? | All terrain scissor lift. Carl Brinkerhoff   12/06/19   03:29PM  |   |  |  |  |  |



I, Carl Brinkerhoff, have reviewed and completed this report.

Carl Brinkerhoff | 12/06/19 | 03:29PM

## SUBCONTRACTOR REPORTS

## Fri 12/06/2019



Homer Public Safety Building: Grubstake Avenue Homer, Alaska 99603

| Name                                    | Description                              | Quantity | Hours | <b>Hours To Date</b> |
|---|--|----------|-------|----------------------|
| 1. Puffin Electric                      | No Entry                                 | 0        | 0.0   | 0.0                  |
| <b>2.</b> Eayrs Plumbing and Mechanical | No Entry                                 | 0        | 0.0   | 0.0                  |
| <b>3</b> . PEI                          | No Entry                                 | 0        | 0.0   | 32.0                 |
| Subtotal                                |  | 0        | 0     | 32.0                 |
| Grand Total (Includes<br>Total)         | Cornerstone General Contractors Work Log | 12       | 72    | 10769.0              |