



Photo 61: Structural damage (crack in pipe) (Basin E4).



Photo 62: Structural damage (pipe deterioration) (Basin E4).



Photo 63: Protruding lateral (Basin E4).




Photo 64: Structural damage (exposed gasket) (Basin E4).



Photo 65: Structural damage (hole in pipe) (Basin E4).




Photo 66: Structural damage (hole in pipe) (Basin E4).