



Front view of subject property. The right side of the structure is encroaching into the setback by two feet. Provided by staff.



View of front corner of building to property line stake. Provided by staff.





Before image of subject property. Provided by applicant.



View of subject property in progress. Roof extended forward from original footprint of subject property. Provided by applicant.