



# Public Works

## Road Inventory Report

### Road Rating:

1 – Very Poor, 2 – Poor, 3 – Fair, 4 – Good, 5 – Excellent/New

Road Name	Length	Rating	Notes
E. Holly Street	752 LF	1	Lateral cracking, tree roots, base failure, Radius at SR 19
E. Gardenia Street	826 LF	1	Lateral cracking, base failure, drop-offs, tree roots, Radius at SR 19
N. Citrus Ave	1,116 LF	1	Bad Lateral Cracking, Broken edges, Narrow curved intersection at Camellia Way, Radius at SR 19
N. Tangerine Ave	1,400 LF	1	Bad Lateral & Horizontal cracking, Delamination of asphalt layers, Bad Radius at Camellia Way
N. Valencia Ave	1,121 LF	1	Lateral cracking, Lifting, Bad radius at E. Magnolia, Bad radius at E. Croton Way
N. Georgia Ave	656 LF	1	Bad Lateral Cracking, Bad Intersection/Radius at W. Cypress Ave
E. Myrtle Street	815 LF	2	Cracking, small potholes, Radius at SR 19
E. Oak Street	652 LF	2	Lateral cracking, Radius at N. Lakeshore Blvd, Radius at SR 19
E. Pine Street	967 LF	2	Lateral & Horizontal cracking, Radius at N. Lakeshore Blvd, Radius at SR 19
E. Cedar Street	1,066 LF	2	Lateral cracking, Northside Radius at SR 19
E. Palmetto Ave	1,275 LF	2	Lateral cracking, small potholes, Radius at N. Lakeshore Blvd, Radius at SR 19
E. Cypress Ave	1,069 LF	2	Lateral cracking, Radius at SR 19
E. Magnolia Ave	1,527 LF	2	Lateral cracking, Radius at SR 19
E. Laurel Ave	1,646 LF	2	Lateral cracking, Radius at SR 19
E. Croton Way	1,663 LF	2	Lateral cracking, narrow Radius at N. Temple, Bad radius at N. Valencia, Bad Radius at N. Lakeshore Blvd
Mission Lane	1,335 LF	2	Some cracking, potholes, tree roots
N. Lakeshore Blvd. (Red Road)	370 LF	2	Some Lateral Cracking, Potholes

E. Camellia Way	1,682 LF	2	Lateral cracking, Broken edges, Narrow Intersection at N. Temple
N. Temple Ave	2,185 LF	2	Lateral Cracking, Narrow Intersection at Orchid, Bad Radius at Camellia Way, Bad Radius at E. Croton, Bad Radius at E. Laurel
W. Cypress Ave	1,185 LF	2	Lateral Cracking, Bad Narrow radius at SR 19
W. Dupont Circle	1,200 LF	2	Lateral Cracking, Potholes
W. Oak Street	750 LF	2	Lateral Cracking, Narrow Radius at SR 19
W. Pine Street	370 LF	2	Lateral Cracking, Narrow Radius at SR 19
W. Palmetto Street	347 LF	2	Lateral Cracking, Narrow Radius at SR 19
W. Myrtle Street	706 LF	3	Some cracking, Radius at SR 19, Radius at S. Dixie Drive
W. Holly Street	704 LF	3	Some cracking, Radius at SR 19, Radius at S. Dixie Drive
W. Lakeview Ave	709 LF	3	Some cracking, Radius at S. Dixie Drive, Radius at SR 19
W. Oleander Ave	685 LF	3	Some cracking, Radius at S. Dixie Drive
S. Dixie Drive	2,603 LF	3	Some cracking, Radius at SR 19, Radius at W. Oleander Ave, Radius at W. Myrtle, Radius at W. Lakeview, Radius at W. Holly St
E. Lakeview Ave	783 LF	3	Some cracking, Radius at SR 19
E. Orchid Way	1,544 LF	3	Some cracking, Narrow Intersections at N. Valencia & N. Temple
W. Magnolia Ave	1,172 LF	3	Some Lateral Cracking, Narrow Radius at SR 19
N. Dixie Drive (W. Pine St – W. Central Ave)	614 LF	3	Some Cracking
N. Florida Ave (W. Cypress Ave - W. Dupont Cir	833 LF	3	Potholes, Bad Radius at W. Cypress Ave, Bad Radius at W. Dupont
N. Florida Ave (W. Oak St – W. Central Ave)	320 LF	3	Some Lateral Cracking
E. Central Ave	700 LF	4	Some Lateral Cracking, Some Small Potholes
N. Lakeshore Blvd. (E. Central – N. Tangerine)	2,790 LF	4	Some Lateral Cracking
N. Lakeshore Blvd (N. Tangerine – Red Road)	1,150 LF	4	Some Lateral Cracking, Some Small Potholes
S. Lakeshore Blvd. (E. Central – E. Revels Rd.)	5,150 LF	4	Some Lateral Cracking, Some Small Potholes, Broken Edges

E. Revels Road	5,050 LF	4	Some Lateral Cracking, Broken Edges
S. Florida Ave	2,760 LF	4	Some Lateral Cracking, Broken Edges
Venezia Blvd	1,740 LF	4	Some Minor Cracking, Oil Stains
Messina Place	1,790 LF	4	Some Minor Cracking, Oil Stains
Terracotta Terrace	1,375 LF	4	Some Minor Cracking, Oil Stains
Napoli Way	250 LF	4	Some Minor Cracking, Oil Stains
Bellissimo Place	3,415 LF	4	Some Minor Cracking, Oil Stains
Calabria Way	1,100 LF	4	Some Minor Cracking, Oil Stains
Avila Place	4,500 LF	4	Some Small Patched Areas
Amola Way	300 LF	5	Excellent Condition
Via Bella Court	675 LF	5	Excellent Condition
Lido Drive	2,330 LF	5	Excellent Condition
Palazzo Avenue	170 LF	5	Excellent Condition
Marilyn Ave	735 LF	5	Excellent Condition, Reconstructed in 2022
N. Dixie Drive	1,450 LF	5	Excellent Condition, Reconstructed and Widened in 2023