

# LIFT STATION CLEANING COMPLETION REPORT

---

**PREPARED FOR:**

**Village of Kronenwetter**

2025 Spring Lift Station Cleaning

03.20.2025

**AQUALIS**<sup>®</sup>  
Formerly Northern Pipe, Inc.

[aqualisco.com](https://aqualisco.com) | 920.754.3216



Formerly Northern Pipe, Inc.  
2094 COUNTY ROAD QQ  
GREEN BAY, WISCONSIN 54311  
920.754.3216 | AQUALISCO.COM

## Lift Station Inspection Form

Village of Kronenwetter

W/O 2579

Lift Station Number: L/S 1 Lift Station Location: 2201 Tower Rd

### Pre-Cleaning Description:

Heavy Grease

### Condition:

- ☒ Good  
☐ Fair  
☐ Poor

Construction Type: Precast

Depth: 34.0'

Width: 10.0'

Evidence of Infiltration: ☐ YES ☒ NO

GPM of Leak: \_\_\_\_\_

### Issues Needing Repair:

N/A

### Other Comments:

Pump retrieval cable is hung up poorly.







Formerly Northern Pipe, Inc.  
2094 COUNTY ROAD QQ  
GREEN BAY, WISCONSIN 54311  
920.754.3216 | AQUALISCO.COM

## Lift Station Inspection Form

Village of Kronenwetter

W/O 2579

Lift Station Number: L/S 2 Lift Station Location: 1929 Kimberly Rd

Pre-Cleaning Description:

Heavy Grease

Condition:

- ☒ Good  
☐ Fair  
☐ Poor

Construction Type: Precast

Depth: 32.0'

Width: 6.0'

Evidence of Infiltration: ☐ YES ☒ NO


GPM of Leak: \_\_\_\_\_

Issues Needing Repair:

N/A

Other Comments:

N/A







Formerly Northern Pipe, Inc.  
2094 COUNTY ROAD QQ  
GREEN BAY, WISCONSIN 54311  
920.754.3216 | AQUALISCO.COM

## Lift Station Inspection Form

Village of Kronenwetter

W/O 2579

Lift Station Number: L/S 3 Lift Station Location: 2361 Tower Rd

Pre-Cleaning Description:

Heavy Grease

Condition:

- ☒ Good  
☐ Fair  
☐ Poor

Construction Type: Precast

Depth: 26.0'

Width: 6.0'

Evidence of Infiltration: ☐ YES ☒ NO

GPM of Leak: \_\_\_\_\_

Issues Needing Repair:

N/A

Other Comments:

N/A







Formerly Northern Pipe, Inc.  
2094 COUNTY ROAD QQ  
GREEN BAY, WISCONSIN 54311  
920.754.3216 | AQUALISCO.COM

## Lift Station Inspection Form

Village of Kronenwetter

W/O 2579

Lift Station Number: L/S 9 Lift Station Location: 2099 West Rd

### Pre-Cleaning Description:

Very Heavy Grease

### Condition:

- ☒ Good  
☐ Fair  
☐ Poor

Construction Type: Precast

Depth: 30.0'

Width: 8.0'

Evidence of Infiltration: ☐ YES ☒ NO

GPM of Leak: \_\_\_\_\_

### Issues Needing Repair:

N/A

### Other Comments:

N/A







Formerly Northern Pipe, Inc.  
2094 COUNTY ROAD QQ  
GREEN BAY, WISCONSIN 54311  
920.754.3216 | AQUALISCO.COM

## Lift Station Inspection Form

Village of Kronenwetter

W/O 2579

Lift Station Number: L/S 10 Lift Station Location: 2505 Sussex Pl

Pre-Cleaning Description:

Light Grease

Condition:

☒ Good

☐ Fair

☐ Poor

Construction Type: Precast

Depth: 26.0'

Width: 72"

Evidence of Infiltration: ☐ YES ☒ NO


GPM of Leak: \_\_\_\_\_

Issues Needing Repair:

N/A

Other Comments:

N/A







Formerly Northern Pipe, Inc.  
2094 COUNTY ROAD QQ  
GREEN BAY, WISCONSIN 54311  
920.754.3216 | AQUALISCO.COM

## Lift Station Inspection Form

Village of Kronenwetter

W/O 2579

Lift Station Number: L/S 11 Lift Station Location: 805 Glade Ct (back of subdivision)

Pre-Cleaning Description:

Heavy Grease

Condition:

- ☒ Good  
☐ Fair  
☐ Poor

Construction Type: Precast

Depth: 18.0'

Width: 6.0'

Evidence of Infiltration: ☐ YES ☒ NO

GPM of Leak: \_\_\_\_\_

Issues Needing Repair:

N/A

Other Comments:

N/A

