



EXISTING PICTURE P1



EXISTING PICTURE P2



EXISTING PICTURE P3



EXISTING PICTURE P4



EXISTING PICTURE P5



EXISTING PICTURE P6



EXISTING PICTURE P7



EXISTING PICTURE P8



EXISTING PICTURE P9



EXISTING PICTURE P10

GENERAL NOTES. TYP.

AS SHOWN INTERIOR PICTURES: WOOD ROD AND TERMITE DAMAGED, INCLUDING BUT NOT LIMITED TO:

WINDOWS AND WINDOWS WOOD FRAMING, WOOD DOOR AND DOORS WOOD FRAMING, CASING, WOOD STUDS/ WOOD FRAMING, EXTERIOR WOOD SIDING AND SOME ROOF RAFTERS. STRUCTURAL ENGINEER VISITED THE SITE AND RECOMMENDED SHORING THE ROOF STRUCTURE.

CONTRACTOR AND ALL SUBCONTRACTORS PERFORMING ANY WORK ON THIS PROJECT ARE TO VISIT THE SITE AND VERIFY ALL MEASUREMENTS INCLUDING BUT NOT LIMITED TO BUILDING HEIGHTS, ROOF SLOPES, ROOM DIMENSIONS ETC. TO CONFIRM ALL EXISTING CONDITIONS BEFORE ORDERING OR FABRICATING ANY MATERIALS. CONTRACTOR SHALL REPORT ANY INCONSISTENCIES WITH THE CONSTRUCTION DOCUMENTS TO THE ARCHITECT BEFORE CONTINUING WORK.

REV # DATE DESCRIPTION

SEAL

ROGER HANSROTE, ARCHITECT
FLAR # 14300

REVISION

JOB NUMBER: 2022-53
DATE: 07-22-2022
DRAWN BY: AL/MG
APPROVED BY: RH

SHEET TITLE

EXISTING
INTERIOR
PHOTOGRAPHS

SHEET NUMBER