



















#### Scope of Work

- Remove and Replace Concrete Curb.
- 2. Remove and Replace Aluminum Railing.
- 3. Perform Wall and Cap Concrete Restoration.
- 4. Perform Tunnel Entrance Concrete Restoration.
- 5. Out flush and plus Steel Pipe Penetrations thru wall.
- Provide FDXIT Class 5 Finish on Curb, Cup and Wall. See FDXIT Standard Specifications Section 400-15.2.6. Provide City with 5 gallons for touch up.

#### General Notes

- Photos do not represent every occurrence for repairs. Photos are provided to demonstrate typical examples of each repair procedure type.
- Concrete Restoration shall be provided on a Lump Sum Basis. The Contractor shall survey the wall and concrete conditions to develop the quantities required for each repair toxes.
- Aluminum Railing shall be per FDVIT Standard Index 860. Note the following modification: SS 31.6 Fasteners shall be used in lieu of Galivanized Steel Anchors indicated in the Index 860.
- 4. No digging on the Seward Side of the wall shall occur during Turtle Nexting Season.

#### Legend

A Photo Numbers



Repair Location Map

| į.       |   |     |      | BOX STOR SECURITY AND ADDRESS OF THE PERSON | THE C. PROCEST<br>PLANES FE NO. 20191 | Artis Ct. et. et | MOCK - ROOS                       | FLORESTA NO. 16 PER CONTRACTOR OF THE PER CO | WANTER COOK PETANG WALL REPAIR<br>DOCUMENTO DEARNES | (VE 384 201)<br>F4 40 810010 |
|----------|---|-----|------|---|---------------------------------------|------------------|-----------------------------------|--|---|------------------------------|
| CASE MAD | - | 142 | 1000 | 12-500  | 7,75                                  | 100 Carren Str.  | The late hand from 1987 1981 1984 | DITE OF CONTROL COME AS A SECTION  | OTY OF LAKE WORTH PAIN MODE COURTS MODES            | HEET                         |





Photo 9 North Corner



Photo 10 North Corner



Photo 11



Photo 12 Repair Procedure No. 3. Cut Back Steel.



Photo 13 Repair Procedure No. 3 and No. 4



Photo 14 Repair Procedure No. 2



Photo 15 Repair Procedure No. 2



Repair Procedure No. 2. Replace 1/2" Expansion Soint Material.

|    | H   | $\overline{}$ |      | RIDE ULIDA ADDICAL AC | 164.                  | 8,00 |
|----|-----|---------------|------|-----------------------|-----------------------|------|
|    |     |               |      |                       | PERSON FILL NO. SECUL | 1    |
| ME | 10. | 0E 0          | 4.00 | 12-500                | 140                   | 919  |

OFF OF LAKE WORTH
MINISTPAL READ RETAINING AND SEPARE
CONCRETEDING DIMMINIST
OFF OF LAKE WORTH
PROFITABLE COUNTY FLORIS



















