

Quote No: 129123 - 1

# LEVY COUNTY BOCC SOLID WASTE

SOLID WASTE PO BOX 1734 BRONSON FL 32621-1734

PER YOUR REQUEST, WE HAVE ESTIMATED REPAIRS ON THE MACHINE LISTED BELOW. A REPAIR DESCRIPTION WITH LABOR AND/OR PARTS IS ATTACHED. UPON DISASSEMBLY OF THE COMPONENT(S) TO BE REPAIRED, ADDITIONAL PARTS AND LABOR MAY BE NECESSARY. IF SO, A QUOTE FOR ADDITIONAL REPAIRS WILL BE FORWARDED TO YOU FOR APPROVAL. NOTE: AN AUTHORIZED REPRESENTATIVE OF YOUR COMPANY SHOULD SIGN AND RETURN THIS REPAIR ESTIMATE. ONLY UPON RECEIPT OF THE SIGNED ESTIMATE WILL REPAIRS BE PERFORMED. A PURCHASE ORDER NUMBER SHOULD BE SUPPLIED IF REQUIRED BY YOUR COMPANY.

CUSTOMER NO.	QUOTE NO.	DATE	CONTACT
027077	129123	12/3/2024	BENNY
PHONE NO.	FAX NO.	EMAIL	
3522215186			LIMAIL
MODEL	MAKE		SERIAL NO.
D6NLGP	CATERPILLAR		0MG501057
UNIT NO.	HOURS	WO NO.	P.O. NO.
	7753		F.O. NO.

## STEAM CLEAN MACHINE

NOTES

MULTI-STAGE CLEANING PROCESS INCLUDING RINSING OF HEAVY DIRT WITH HIGH POWER CANNON AND SOAP STEAM CLEAN FOR REMOVAL OF GREASE AND OIL BUILD-UP. A CLEAN MACHINE WILL PROVIDE MANY BENEFITS INCLUDING ACCESS TO TIGHT AREAS TO PROFORM A MORE THOROUGH VISUAL EVALUATION, IT WILL REDUCE THE LIKELIHOOD O CONTAMINANTS ENTERING MACHINE SYSTEMS DURING DISASSEMBLY. INCREASE EFFICIENCY DURING THE REPAIR PROCESS AND HELP TO EXTEND UNDERCARRIAGE LIFE. SYSTEM CONTAMINATION IS THE LEADING CAUSE OF MORE THAN 70 PERCENT OF HYDRAULIC SYSTEM AND OTHER MAJO COMPONENT FAILURES.

	Total Flat Rate Labor:	287.50
₽	Segment 01 Total:	287.50
REMOVE & INSTALL CARRIER ROLLER	CAT ABRASION BOTH SIDES	
	The second Bottl OldE3	
	Total Estimated Parts:	529.42
		529.42 296.00

#### **REMOVE & INSTALL SPROCKET SEGMENT BOTH SIDES**

Total Estimated Parts:1,283.80Total Flat Rate Labor:814.00

**Segment 03 Total:** 2,097.80

#### REPLACE GASKET/RESEAL TRACK ADJUSTER BOTH SIDES

Total Estimated Parts: 176.86
Total Flat Rate Labor: 1,073.00

**Segment 04 Total:** 1,249.86

## REMOVE & INSTALL IDLER/IDLER WHEEL CAT ABRASION BOTH SIDES

Total Estimated Parts: 9,083.24
Total Flat Rate Labor: 740.00

**Segment 05 Total:** 9,823.24

### REMOVE & INSTALL IDLER GUIDE WEAR STRIP BOTH SIDES

Total Estimated Parts: 113.56
Total Flat Rate Labor: 592.00

Segment 06 Total: 705.56

## REMOVE & INSTALL TRACK ASSEMBLY CAT ABRASION BOTH SIDES

Total Estimated Parts: 798.95
Total Flat Rate Labor: 1,036.00

**Segment 07 Total:** 1,834.95

# REMOVE & INSTALL TRACK SHOE CAT ABRASION BOTH SIDES

NOTES:

THE REPLACEMENT LINK ASSEMBLIES HAVE BEEN ENROLLED IN CATERPILLARS UNDERCARRIAGE ASSURANCE PROGRAM. THEY ARE COVERED PER THE PROGRAMS STANDARD TERMS STARTING WITH THE INSTALLATION DATE OR 100% WEAR, WHICHEVER COMES FIRST FOR LEAKS AND/OR BREAKAGE. WHEN A COMPONENT REPLACEMENT IS MORE ECONOMICAL, CATERPILLAR WILL COVER THE PRORATED COST OF PARTS, BASED ON THE PERCENTAGE OF WEAR ON THE REPLACED COMPONENT. LEFT LINK ASSEMBLY SERIAL #: RIGHT LINK ASSEMBLY SERIAL #:

Total Estimated Parts: 20,505.28
Total Flat Rate Labor: 1,332.00

	Segment 08 Total:	21,837.28
REMOVE & INSTALL TRACK ROLLER CAT ABRAS	ION BOTH SIDES	
	<b>Total Estimated Parts:</b>	7,398.24
	Total Flat Rate Labor:	1,776.00
	Segment 09 Total:	9,174.24
CREDIT TO CUSTOMER	Total Estimated Misc:	
	Segment 10 Total:	-5,900.00
	Total Segments:	41,935.85
ENVIRONMENTAL/MISCELLANEOUS		300.00
SUB TOTAL (BEFORE TAXES)		42,235.85
TOTAL ESTIMATE		42,235.85
		# 70. 1-