

PROJECT SIDING REQUEST

TO: LOS GATOS HPC

RE: REQUEST TO REMOVE AND REPLACE SIDING

THE HOME'S EXISTING SIDING CONSISTS OF THREE DIFFERING PROFILES. REFER TO PHOTOS 1, 2, 3.

DURING PRIOR REMODELS, THE FRONT OF THE HOME HAS BEEN PATCHED WITH NON-MATCHING SIDING APPLIED WITHOUT CARE TO BLEND IT IN WITH EXISTING SIDING - REFER TO PHOTOS 4, 5, 6, 7.


IT APPEARS DUE TO NEGLECT, THE ROOF'S GUTTER SYSTEM AND DOWNSPOUTS UNDERWENT A PERIOD OF YEARS LEAKING ONTO THE SIDING AND COMPLETELY ROTTING IT OUT. THE SIDING WAS BONDO-ED AND PUTTY-ED OVER IN A VERY UNSIGHTLY WAY TO TRY AND STOP THE ROT, WHICH WILL NOT BE EFFECTIVE - THE SIDING IS IRREPAIRABLE. REFER TO PHOTOS 8.

THE ADDITION TO REAR OF THE HOME WILL BE SIDED WITH THE PROPER HISTORIC 3 LAP SIDING.

WE WOULD LIKE TO REPLACE THE EXISTING SIDING OF THE HOME WITH NEW SIDING TO MATCH THE PROFILE OF THE NEW SIDING TO BE APPLIED TO THE ADDITION.


THIS WILL RESULT IN AN ATTRACTIVE COHESIVE RESTORATION OF THE ORIGINAL HOUSE THAT WILL LAST FOR MANY MORE YEARS GOING FORWARD.

THANK YOU FOR YOUR CONSIDERATION.



2


1



3




4






5



A photograph of a wall with horizontal white siding. A window opening is visible at the top, showing a wooden frame and dark interior. The siding is in poor condition, with several horizontal cracks and areas where the paint has chipped away, revealing the underlying wood. A red square with a white border and the number '7' is overlaid on the wall, centered horizontally and slightly below the middle vertically. In the bottom left corner, there is a wooden post and some red wires.

7



8



8

***This Page
Intentionally
Left Blank***