

Luther Burbank Pier Renovation and Upgrade Grant



Figure 1: Profile view of pier showing concrete panel and wood cap beam construction



Figure 2: Detail of cap beam illustrating typical rot condition