



## PUBLIC WORKS FACILITY SEISMIC RETROFITS PROJECT CLOSEOUT CONSTRUCTION PHOTOS



**AB6901 | EXHIBIT 2 | GRADE BEAM INSTALLATION AT MECHANIC GARAGE DOORS**



**PUBLIC WORKS FACILITY SEISMIC RETROFITS PROJECT  
CLOSEOUT CONSTRUCTION PHOTOS**



**AB6901 | EXHIBIT 2 | GRADE BEAM COMPLETE AT MECHANIC GARAGE DOORS**



## PUBLIC WORKS FACILITY SEISMIC RETROFITS PROJECT CLOSEOUT CONSTRUCTION PHOTOS



**AB6901 | EXHIBIT 2 | UPPER ROOF REINFORCEMENT**



**PUBLIC WORKS FACILITY SEISMIC RETROFITS PROJECT  
CLOSEOUT CONSTRUCTION PHOTOS**



**AB6901 | EXHIBIT 2 | FALL PROTECTION**



## PUBLIC WORKS FACILITY SEISMIC RETROFITS PROJECT CLOSEOUT CONSTRUCTION PHOTOS



**AB6901 | EXHIBIT 2 | EXISTING OVERBURDENED GREEN ROOF**



## PUBLIC WORKS FACILITY SEISMIC RETROFITS PROJECT CLOSEOUT CONSTRUCTION PHOTOS



**AB6901 | EXHIBIT 2 | GREEN ROOF ASSEMBLY REMOVAL**



## PUBLIC WORKS FACILITY SEISMIC RETROFITS PROJECT CLOSEOUT CONSTRUCTION PHOTOS



**AB6901 | EXHIBIT 2 | SINGLE PLY ROOFING MEMBRANE, DRAINAGE SWALE AND FALL PREVENTION**



## PUBLIC WORKS FACILITY SEISMIC RETROFITS PROJECT CLOSEOUT CONSTRUCTION PHOTOS



**AB6901 | EXHIBIT 2 | STORM DRAINAGE INSTALLATION**



**PUBLIC WORKS FACILITY SEISMIC RETROFITS PROJECT  
CLOSEOUT CONSTRUCTION PHOTOS**



**AB6901 | EXHIBIT 2 | BRACING AT INTERIOR CONCRETE MASONRY UNIT WALL**