



Remove rear wing
of house; salvage
materials as
practical



Material to be repurposed:

Original Siding, Windows, Doors, Interior Trim, Casings, Plumbing Fixtures



1st Addition to the original structure. This picture shows the condition of the framing.



This is another example of the 1st failed addition to the home. Along with extensive frame damage, there are multiple areas where the subfloor is rotting.



The 2nd addition to the original home. The ceiling has fallen due to water intrusion, massive frame and subfloor damage.



This is also located in the 2nd addition.



Additional Examples

