

HISTORIC PRESERVATION SURVEY INVENTORY FORM

----- TYPE ALL ENTRIES.

1. PROPERTY NAME: NORMAN, OKLAHOMA
 2. RESOURCE NAME: _____
 3. ADDRESS: 904 S. Classen Avenue
 4. CITY: NORMAN
 5. VICINITY: YES (yes or no)
 6. COUNTY: CLEVELAND
 7. BLOCK: 14
 8. LOT: 10-12
 9. PLAT NAME: Classen-Miller Addition
 10. SECTION: N/A
 11. TOWNSHIP: N/A
 12. RANGE: N/A
-
13. RESOURCE TYPE: B Building
 14. HISTORIC FUNCTION: 01A Single dwelling
 15. CURRENT FUNCTION: Same
 16. AREA(S) OF SIGNIFICANCE: 030 Architecture
 17. SIGNIFICANCE: Contributing to the Classen-Miller District
 - _____
 - _____
 18. DOCUMENTATION SOURCES: Sanborn Insurance Maps, 1944, 1925
 - _____
 - _____
-
19. NAME OF PREPARER: MEACHAM WEISIGER ASSOCIATES
709 Chautauqua, Norman, Ok. 73069
405 - 321 - 6221
 20. SURVEY PROJECT: CITY OF NORMAN, OKLAHOMA
 21. DATE OF PREPARATION: AUGUST, 1988
 22. PHOTOGRAPHS: YES YEAR 1988

BUILDING CONSTRUCTION DESCRIPTION:

23. ARCHITECT/BUILDER: _____
24. YEAR BUILT: Ca. 1922
25. ORIGINAL SITE? Yes DATE MOVED _____ FROM WHERE _____
26. ACCESSIBLE? Yes
27. ARCHITECTURAL STYLE: 65 Bungalow/Craftsman
28. FOUNDATION MATERIAL: 65 Quarried concrete
29. ROOF MATERIAL: 63 Asphalt
30. WALL MATERIAL: 55 Aluminum
31. WINDOW TYPE: Double hung, 1/1, 12/1
32. WINDOW MATERIAL: 20 Wood
33. DOOR TYPE: Panel/lites/side
34. DOOR MATERIAL: 20 Wood
35. EXTERIOR FEATURES: Bay window; recessed porch
36. INTERIOR FEATURES: N/A
37. DECORATIVE DETAILS: QA window dormer
38. CONDITION OF RESOURCE: Fair
39. DESCRIPTION OF RESOURCE: Present and historic: Gabled roof,
hipped above front porch; one story with one-half basement;
chimney center; quarried concrete block porch; original
square columns covered with siding
- Alterations: Covered with siding Post 1980's
40. COMMENTS: _____
42. PLACEMENT: _____

