



Begin Complete Street corridor

Existing deteriorating RR viaduct. Floods due to Dry Run Creek channel overtopping

Restore stream corridor

Match existing Complete Street corridor

W Charles St

W Charles St

B & L Body Repair, Inc

C50

W Charles St

Garbage Guru Custom Replicas

Structure over Dry Run Creek, in deteriorating condition

Existing deteriorating RR viaduct. Creates barrier due to height and width restrictions. Evaluate replacement with shorter structure possible due to modified rail operations.

Identify if structure is needed

Beautify stream corridor

existing structure under 2nd Ave SW, Railroad museum, and active RR tracks

Park Rd

SW

5th Ave SW

2nd Ave SW

1st Ave SW

1st St SW

1st St SW

Railroad Museum

1st Ave SW

Ma &