

The current failing section of 170 feet of force main piping.



Deformed clamps around piping showing loss of structural integrity of piping which has been accelerated by the tightening of compression bolts on the clamp.



The position and entirety of the 170-foot section of force main piping proposed for replacement.



