

December 2020

Water Report

WATER PLANT

During this last month, we have experienced heavy rains in which caused slides in many parts of southeast Alaska. These heavy rains have increased the need for flushing the reservoir and also caused modifications to the SOP. Ditches, one by one are getting cleared out by hand to increase flow and keep water off the roads which in turn will be less ice. Shut offs have been found that were not previously documented and future curb stops will be found and documented as well and plans made to document corporate stops and upgrade to curb stops.

SEAPORT

Seaport organization is slowly taking shape, few projects pending. Have identified some leaks in the main warehouse in the rafters and will make corrective action.

MISC.

Continued drain and ditch clearing and continued pmcs of the city and other areas under saxman control.

Water Operator


Josh Tyler