

ADMINISTRATIVE COMMENT

The following recommendations for the below listed Performance and/or Warranty Obligations are as follows:

- 1. Dove Park Estates Subdivision Extended Warranty Obligation - \$66,616.00 - Extend
- Hunter's Haven Subdivision, Phase 1
 Extended Warranty Obligation \$44,000.00 Release

 Lakeshore Villages Subdivision, Phase 10
- Warranty Obligation \$104,896.00 Release upon expiration
- 4. Money Hill Plantation Subdivision, Phase 7B-1 Extended Warranty - \$57,100.00 - Extend
- 5. River Club Subdivision, Phase 2A Extended Warranty - \$35,900.00 - Extend
- 6. Tchefuncta Club Estates Subdivision, Phase 3A Warranty Obligation - \$153,780.00 - Release upon expiration



ST. TAMMANY PARISH MICHAEL B. COOPER PARISH PRESIDENT

September 21, 2023

St. Tammany Parish Council P.O. Box 628 Covington, LA 70434

Re: Dove Park Estates Subdivision Extended Warranty Obligation - \$66,616.00 - Letter of Credit #679

Honorable Council Members,

The extended Warranty Obligation in the amount of \$66,616.00 expires November 23, 2023 and is scheduled for review by the Parish Council at the October 5, 2023 meeting.

The developer was notified on July 24, 2023 by the Department of Engineering of the punch list items required. The developer's engineer shall certify to this office at least sixty (60) days prior to the expiration of the obligation, that the punch list has been completed.

The following punch list items remain:

- 1. Replace/Repair all damaged and broken concrete curbing throughout the development (See picture #1 Typical Comment);
- 2. Replace the broken and damaged sidewalk sections within the Dove Park Road Right-of-Way leading to the Tammany Trace (See pictures #2 & #3);
- 3. Replace/repair all broken and damaged sidewalk sections within the Dove Park Estates Subdivision (See pictures #4 #6 Typical Comment);
- 4. Replace/Repair all damaged pavement sections throughout the development (See picture #7 Typical Comment);
- 5. Repair the damaged curbing, pavement and drop inlet in front of Lot #36 along Skyler Dove Drive (See picture #8);
- 6. Repair the damaged curbing, pavement and drop inlet in front of Lot #33 & Lot #52 along Skyler Dove Drive (See pictures #9 & #10);
- 7. Repair the damaged curbing, pavement and drop inlet in front of Lot #26 along Ring Neck Dove Drive (See picture #11);
- 8. Repair the damaged curbing, pavement and drop inlet in front of Lot #23 along Ring Neck Dove Drive (See picture #12);
- 9. Repair the damaged curbing, pavement and drop inlet in front of Lot #48 along White Wing Dove Drive (See picture #13);
- 10. Repair the damaged curbing, pavement and drop inlet in between Lots #5 & #7 along White Wing Dove Drive (See picture #14);
- 11. Repair the damaged curbing, pavement and drop inlet in front of Lot #3 along Brook Dove Drive (See picture #15);
- 12. Repair the damaged curbing, pavement and drop inlet in front of Lot #2 and next to Lot #38 along Brook Dove Drive (See pictures #16 & #17);
- 13. Repair the damaged curbing, pavement and drop inlet in front of Lot #76 along Emerald Dove Drive (See pictures #18);
- 14. Repair the damaged curbing, pavement and drop inlet in front of Lot #72 along Emerald Dove Drive (See pictures #19);
- 15. The pavement has failed in front of Lot #66 on Emerald Dove Drive and needs to be replaced (See picture #20);
- 16. The drainage and access servitude behind Lots #45 #49 is encumbered by fences which is in violation of Restrictive Covenant #3 and needs to be corrected (See picture #21);
- 17. The eroding land into Pond #1 needs to be corrected, stabilized and vegetated. Pond #1 needs to have all siltation from this erosion removed (See pictures #22 #24);
- 18. The eroding land into Pond #2 needs to be corrected, stabilized and vegetated, Pond #2 needs to have all siltation and have all construction debris removed from the Pond. (See pictures #25 #26);
- 19. Pond #3's shoulders and banks were eroding and needs to be re-established and vegetated and have all construction debris removed (See pictures #27 & #28);
- 20. Pond #5's shoulders and banks were eroding and needs to be re-established and vegetated (See picture #29);
- 21. Correct the low areas associated with the new sidewalk construction around Pond #5 (See picture #30);
- 22. The Emerald Dove Drive roadway culvert at the intersection of Dove Park Road appears to be obstructed due to the roadside repairs and needs to be corrected (See picture #31);
- 23. Replace/Repair all leaning signage within this development (See picture #32 Typical Comment);



Re: Dove Park Estates Subdivision

Warranty Obligation - \$66,616.00 - Letter of Credit #679 (continued)

- 24. Numerous of the required plantings along Dove Park Lane are missing or have died. The missing/dead plantings need to be replanted in accordance with the approved Landscape Plan (Rev. date 3.4.2020) (See pictures #33 & #34);
- Install all required trees on Lots #31 #38 in accordance with the General Notes on Page 2 of the Recorded Plat;
- 26. Clean siltation from all subsurface pipes within this development (Typical Comment);
- 27. The Walking Trail Site Work Permit (#2022-3761) needs to be completed and closed out.
- 28. An appropriate ADA access to the cluster mailbox area on Skyler Dove Drive needs to be provided for this development in accordance with the previous STP email issued on 9/7/2022.
- 29. The side walk on the west side of Emerald Dove Drive should be connected to the existing sidewalks within this development and utility valve concrete collars located on the west side of Emerald Dove Drive place at grade (See picture #35).

This office is working with the developer and the developer's engineer to satisfactorily accomplish the outstanding punch list items. This obligation must be extended for one (1) year or until the work is satisfactorily accomplished.

Sincerely, Daniel P TIL P.E.

Director, Department of Engineering

Attachment: Representative photos from site inspection performed on July 24, 2023

- xc: Honorable Michael Cooper
 - Honorable Rykert Toledano
 - Mr. Ross Liner, AICP, PTP, CFM
 - Mr. Jay Watson, P.E.
 - Ms. Leslie Long Mr. Tim Brown
 - Mr. Theodore Reynolds, P.E.
 - Ms. Maria Robert, P.E.
 - Mr. Chris Cloutet, P.E.
 - Mr. Joey Lobrano
 - Ms. Jan Pavur
 - Mr. Corie Herberger, Dove Park Estates, LLC
 - Mr. Thomas Buckel, P.E., Duplantis Design Group, PC
 - Mr. Paul Mayronne, Jones Fussell, LLP





Picture #3

THE THE CANCERNESS OF





























Aug Trank

STOP



. All











11 71

























10

14

.....

100



St. Tammany Parish Council P.O. Box 628 Covington, LA 70434

Re: Hunter's Haven Subdivision, Phase 1 Extended Warranty Obligation - \$44,000.00 - Cash in Escrow

Honorable Council Members,

The extended Warranty Obligation in the amount of \$44,000.00 expires December 28, 2023 and is scheduled for review by the Parish Council at the October 5, 2023 meeting.

This office has inspected the site. All work covered by this Warranty Obligation is satisfactory.


Therefore, it is recommended that the Warranty Obligation be released. This is a private subdivision and the Parish is not responsible for any maintenance in accordance Recorded Plat File #6002A.

Sincerely, Daniel P. Mill, P.F.

Director, Department of Engineering

Attachment: Hunter's Haven Subdivision, Phase 1 Recorded Plat File #6002A

Honorable Michael Cooper xc: Honorable Michael Lorino, Jr. Mr. Cary Menard Mr. Ross Liner, AICP, PTP, CFM Mr. Jay Watson, P.E. Ms. Leslie Long Mr. Tim Brown Mr. Theodore Reynolds, P.E. Ms. Maria Robert, P.E. Mr. Chris Cloutet, P.E. Mr. Joey Lobrano Ms. Jan Pavur Mr. Uncas Favret, Favret Investments, LLC Mr. Kelly McHugh, P.E., P.L.S., Kelly McHugh & Associates, Inc. Mr. Paul Mayronne, Jones Fussell, LLP





St. Tammany Parish Council P.O. Box 628 Covington, LA 70434

Re: Lakeshore Villages Subdivision, Phase 10 Warranty Obligation - \$104,896.00 - Bond #SU1178581

Honorable Council Members,

The Warranty Obligation in the amount of \$104,896.00 expires November 30, 2023 and is scheduled for review by the Parish Council at the October 5, 2023 meeting.

This office has inspected the site. All work covered by this Warranty Obligation is satisfactory.

Therefore, it is recommended that the Warranty Obligation be released upon expiration. This subdivision is within a Community Development District and the Parish is not responsible for any maintenance.

Sincerely, Daniel P. Hill, P.E.

Director, Department of Engineering

xc: Honorable Michael Cooper Honorable Jake A. Airey Mr. Cary Menard Mr. Ross Liner, AICP, PTP, CFM Mr. Jay Watson, P.E. Ms. Leslie Long Mr. Tim Brown Mr. Theodore Reynolds, P.E. Ms. Maria Robert, P.E. Mr. Chris Cloutet, P.E. Mr. Joey Lobrano Ms. Jan Pavur Mr. Adam Kurz, D.R. Horton, Inc. - Gulf Coast Mr. Tommy Buckel, P.E., Duplantis Design Group, PC Ms. Elizabeth Songy, P.E., Duplantis Design Group, PC Mr. Jeff Schoen, Jones Fussell, LLP



St. Tammany Parish Council P.O. Box 628 Covington, LA 70434

Re: Money Hill Plantation Subdivision, Phase 7B-1 Extended Warranty Obligation - \$57,100.00 - Letter of Credit

Honorable Council Members,

The extended Warranty Obligation in the amount of \$57,100.00 expires November 21, 2023 and is scheduled for review by the Parish Council at the October 5, 2023 meeting.

The developer was notified on July 14, 2023 by the Department of Engineering of the punch list items required. The developer's engineer shall certify to this office at least sixty (60) days prior to the expiration of the obligation, that the punch list has been completed.

The following punch list items remain:

- The roadside ditches located in the vicinity of Lot #423 through #425 are silted in and the side slopes are eroding. Roadside ditches need to be regraded to provide positive flow and should be properly vegetated once regraded and proper erosion control measures installed and maintained until vegetation is established (See pictures #1 - #3);
- 2. The cross culvert under Hidden Lake Lane is silted in and needs to be corrected (See picture #4);
- 3. The pond inflow pipe located in the vicinity of Lot #413 is holding water due to erosion and needs regrading and rip rap at the downstream side to provide positive flow and prevent erosion (See pictures #5);
- 4. The roadside shoulders in this phase of Money Hill Plantation need to be reestablished and vegetated in several locations (See pictures #6 #9, Typical Comment);
- 5. Replace blue reflectors in the vicinity of fire hydrants where missing (Typical Comment);
- 6. Replace/Repair the end of roadway signage located in the vicinity of Lot #407 (See picture #10);
- 7. The "As-Built Signage Plan" needs to be resubmitted with the speed limit signs corrected to show 25 MPH as installed in this phase of Money Hill;

This office is working with the developer and the developer's engineer to satisfactorily accomplish the outstanding punch list items. This obligation must be extended for one (1) year or until the work is satisfactorily accomplished.

Sincerely 🗐, P.E. 🧹 Dagiel P

Director, Department of Engineering

Attachment: Representative photos from site inspection performed on July 13, 2023

xc: Honorable Michael Cooper Honorable Cheryl Tanner
Mr. Ross Liner, AICP, PTP, CFM
Mr. Jay Watson, P.E.
Ms. Leslie Long
Mr. Tim Brown
Mr. Theodore Reynolds, P.E.
Ms. Maria Robert, P.E.
Mr. Chris Cloutet, P.E.
Mr. Joey Lobrano
Ms. Jan Pavur
Ms. Mimi Dossett, Money Hill Plantation, LLC
Mr. Sean Burkes, P.E., P.L.S., J.V. Burkes & Associates, Inc.























St. Tammany Parish Council P.O. Box 628 Covington, LA 70434

Re: River Club Subdivision, Phase 2A Extended Warranty Obligation - \$35,900.00 - Letter of Credit #703

Honorable Council Members,

The Warranty Obligation in the amount of \$35,900.00 expires November 23, 2023 and is scheduled for review by the Parish Council at the October 5, 2023 meeting.

The developer was notified on July 14, 2023 by the Department of Engineering of the punch list items required. The developer's engineer shall certify to this office at least sixty (60) days prior to the expiration of the obligation, that the punch list has been completed.

The following punch list items remain:

- 1. The concrete panel in front of Lot #180 is broken and needs to be replaced (See picture #1);
- 2. Concrete joints need to be cleaned and repaired throughout this phase of River Club Estates (See picture #2 Typical Comment);
- 3. Most of the roadways were covered with dirt and a meaningful inspection of the concrete panels could not be performed during the site visit (See pictures #3 #5);
- 4. Roadside shoulders need to be reestablished, brought to grade, and vegetated throughout this phase of River Club Estates (See pictures #6 & #7, Typical Comment);
- The roadside ditches throughout this phase of River Club Estates should be properly vegetated and proper erosion control measures installed and maintained until vegetation is established (See pictures #6 & #7, Typical Comment);
- 6. The temporary ditch located between Lots #123 & #124 should be properly vegetated and proper erosion control measures installed and maintained until vegetation is established (See picture #8);
- The side slopes of the ditch located within Parcel B needs to be re-established and should be properly vegetated and proper erosion control measures installed and maintained until vegetation is established. (See picture #9);
- 8. The soil adjacent to the pipe ends located in the drainage servitude on Parcel B is scouring and needs to be stabilized by installing additional rip rap (See pictures #10 & #11);
- 9. Drainage catch basins throughout this phase of River Club Estates needs to be cleared and cleaned so a meaningful inspection of the subsurface system can be made (See Picture #12 & #13);
- 10. Install missing blue reflectors in the vicinity of all fire hydrants within this Subdivision (Typical Comment);
- 11. The wooden bridge and walking trail need to be completed in accordance with the previously approved plans.

This office has not received notification from the developer's engineer. Therefore, this obligation must be extended for one (1) year or until the work is satisfactorily accomplished.

Sincerely, E. Daniel

Director, Department of Engineering

Attachment: Representative photos from site inspection performed on July 13, 2023

xc: Honorable Michael Cooper Honorable Marty Dean Mr. Ross Liner, AICP, PTP, CFM Mr. Jay Watson, P.E. Ms. Leslie Long Mr. Tim Brown Mr. Theodore Reynolds, P.E. Ms. Maria Robert, P.E. Ms. Maria Robert, P.E. Mr. Chris Cloutet, P.E. Mr. Joey Lobrano Ms. Jan Pavur Mr. Matthew Bennett Mr. Kelly McHugh, P.E., P.L.S., Kelly McHugh & Associates, Inc.





























St. Tammany Parish Council P.O. Box 628 Covington, LA 70434

Re: Tchefuncta Club Estates Subdivision, Phase 3A Warranty Obligation - \$153,780.00 - Letter of Credit #689

Honorable Council Members,

The Warranty Obligation in the amount of \$153,780.00 expires November 9, 2023 and is scheduled for review by the Parish Council at the October 5, 2023 meeting.

This office has inspected the site. All work covered by this Warranty Obligation is satisfactory.

Therefore, it is recommended that the Warranty Obligation be released upon expiration. This is a private subdivision and the Parish is not responsible for any maintenance in accordance with Recorded Plat File #6079.

Sincerel R Hill, P.E Daniel

Director, Department of Engineering

Attachment: Tchefuncta Club Estates Subdivision, Phase 3A Recorded Plat File #6079

xc: Honorable Michael Cooper Honorable Marty Dean Mr. Cary Menard Mr. Ross Liner, AICP, PTP, CFM Mr. Jay Watson, P.E. Ms. Leslie Long Mr. Tim Brown Mr. Theodore Reynolds, P.E. Ms. Maria Robert, P.E. Mr. Chris Cloutet, P.E. Mr. Joey Lobrano Ms. Jan Pavur Mr. Charlie Barnett, TCE Properties, LLC Mr. William L. Taylor, P.E., McLin Taylor, Inc. Mr. Paul J. Mayronne, Jones Fussell, L.L.P.

| BASE BEARING: GPS - CAGNET - RTN (LOUISIANA SOUTH ZONE - NAD 83) | REFERENCE BENCHMARK: | REFERENC |
|--|---|--|
| FLOOD ZONE: "A13", "B" & "C" BASE FLOOD ELEVATION: 9.0' & N/A | GPS-C4GNET-RTN (NAVD 88) SITE BENCHMARK: | 1. PLAT PREPARE A PARCEL OF L/ |
| DRAWN BY: KAS RESTRICTIVE COVEN | ANTS | SECTION 52, T- BY JOHN C. CUM |
| CREW CHIEF: BAS TECHNICIAN: PLV 1.) EACH NUMBERED LOT SHALL NOT HAVE MORE THAN ONE (1) SINGLE-FAMILY DWE 2.) NO CERTIFICATE OF OCCUPANCY SHALL BE ISSUED REFORE THE SEMERACE AND A | LILEVATION. 17.57 (NAVD 1986) | $\left(\begin{array}{c} \end{array} \right)$ |
| CHECKED BY: CHECKED BY: CHECK | PROVED BY DEPARTMENT OF ENVIRONMENTAL SERVICES OF ST. TAMMANY ER SYSTEM (SUPPLY). NO PRIVATE WATER SUPPLY MAY BE DRILLED OR ILE WATER TO ANY BUILDING OR STRUCTURE, EXCEPT FOR THE PURPOSE TWEEN ANY SUCH SOURCE AND ANY FLEMENT OF THE COMMUNIC | $\frac{1}{\sqrt{2}}$ |
| (CENTRAL) WATER SYSTEM (SUPPLY). 3.) MINIMUM BUILDING SETBACKS SHALL AS NOTED ON FINAL PLAT OR WITHIN THE RI THE CLERK OF COURT FOR ST. TAMMANY PARISH. | | Y / A |
| LOTS 815–844, 848, 40, FRONT 855–869, 871 35' REAR (SEE TYP. LAYOUT 1) 25' SIDE | 1 | 11A |
| LOTS 845-847, 849-854, 35' FRONT 870, 872-878 25' REAR (SEE TYP. LAYOUT 2) 15' SIDE | ÍT | |
| 4.) CONSTRUCTION OF ANY NATURE, INCLUDING FENCES, IS PROHIBITED IN PRIVATE D OR STREET RIGHTS-OF-WAY. | | 1112 |
| 5.) NO NOXIOUS OR OFFENSIVE ACTIVITY SHALL BE CARRIED ON UPON ANY LOT, NOR ANNOYANCE OR NUISANCE TO THE NEIGHBORHOOD, PARTICULARLY THE USE OF L 6.) THE MINIMUM ELEVATION FOR THE LOWEST FLOOR OF ALL RESIDENCES SHALL BE MAPS. THE MINIMUM ELEVATION FOR THE LOWEST FLOOR OF ALL RESIDENCES SH | DETERMINED FROM THE LATEST REVISED FEMA FLOOD INSURANCE RATE | V / / 1/ 13 |
| LOT OR 1' ABOVE THE EFFECTIVE BFE, WHICHEVER IS HIGHER. 7.) THIS SUBDIVISION IS IN F.I.R.M. COMMUNITY PANEL 225205 0220 C AND IS CLASS | | $\langle / / / /$ |
| 8.) NO MOBILE HOMES WILL BE PERMITTED IN THIS SUBDIVISION. 9.) NO LOT WILL BE FURTHER RESUBDIVIDED WITHOUT THE PRIOR APPROVAL OF THE | PLANNING COMMISSION OF ST. TAMMANY PARISH. | 18/1 |
| 10.) THE HOMEOWNERS' ASSOCIATION SHALL BE RESPONSIBLE FOR THE MAINTENANCE 11.) THE FRONT OF EACH LOT SHALL BE SUBJECT TO A 10' UTILITY EASEMENT ALONG | | VE US ASS |
| 12.) DRIVEWAYS ON CORNER LOTS SHALL NOT BE LOCATED ANY CLOSER THAN SIXTY INTERSECTION AS MEASURED FROM THE PROPERTY LINES ON THE CORNER OF TH 13.) IN ADDITION TO THE FOREGOING MINIMUM RESTRICTIVE COVENANT. THE DEVELOPE | | |
| 13.) IN ADDITION TO THE FOREGOING MINIMUM RESTRICTIVE COVENANT, THE DEVELOPE NOADDITIONAL RESTRICTIVE COVENANTS WHICH ARE APPLICABLE TO RUNNING WITH EACH TITLE AND REFERENCE SHALL BE MADE THERETO IN EACH T 14.) BUILDING CONTRACTOR SHALL CONSTRUCT SHALLOW SWALES IN ACCORDANCE WITH | IIILE. | |
| LOT LINES AND SHARED BY THE TWO ADJACENT PROPERTIES. 15.) EACH RESIDENCE OR ESTABLISHMENT WITHIN THE SUBDIVISION SHALL SUBSCRIBE AND REFUSE DISPOSAL) SERVICES PROVIDED. | | |
| P\L | P\L | |
| | IZE & SEED | |
| VARIES VARIES VARIES VARIES | SEE PLAN VARIES GRADE | |
| $\begin{array}{c ccccccccccccccccccccccccccccccccccc$ | TO DRAIN R20 | (1) |
| 3 2 5 | MAX | < V |
| * TYPICAL ASPHALTIC ROADWAY/ENTRAN | TYPICAL CUL-DE-SAC | 2 1 |
| LEGEND: FOR ASPHALT PAVING BASE PREPARATION AN ① 4" (MIN.) ASPHALT PAVEMENT 1. ALL WORK AND MATERIAL | NT.S. | · ~ / / |
| ② 8" (MIN.) CLASS II BASE COURSE COMPLIANCE WITH LOUISIA ③ 12" (MIN.) A-4 OR BETTER SUB-BASE STRUCTURAL FILL SPECIFICATIONS FOR ROAL ③ 12" (MIN.) A-4 OR BETTER SUB-BASE STRUCTURAL FILL SPECIFICATIONS FOR ROAL | ANA DEPARTMENT NDARD DS AND BRIDGES, | * /) |
| (4) NATIVE SOLL SHOULDER SURFACE (5) 6" MIN. SHOULDER BACKFILL MATERIAL, COMPACTED TO 92% OF ITS STANDARD PROCTOR DENSITY. MATERIAL TO BE IN COMPLIANCE WITH THE APPLICABLE SECTION OF THE BED TO BE EXCAVATED | ROPOSED ROAD | ',-', |
| BE IN COMPLIANCE WITH THE APPLICABLE SECTION OF THE LOUISIANA DEPARTMENT OF TRANSPORTATION STANDARD SPECIFICATIONS FOR ROADS AND BRIDGES, AND LATEST REVISIONS THERETO. 3. PROOFROLL AND STABILIZE | L GRADE. | 1.111 |
| * THIS TYPICAL SECTION REPRESENTS THE MINIMUM: HOWEVER UPON APPRO OF PRELIMINARY PLANS A GEOTECHNICAL INVESTIGATION, INCLUDING A PAY DESIGN, SHALL BE CONDUCTED. | | 11/1 |
| CURVE TABLE | LINE TABLE | //// |
| LUT RADIUS ARC LEN. CH. DIST. CH. BRG LUT RADIUS ARC LEN. CH. DIST. CH. BRG C1 305.00' 455.75' 414.52' S68*52'44*W C51 330.00' 79.92' 79.73' N57*50'24*W C2 305.00' 58.58' 58.49' N73*48'57*W C52 330.00' 20.36' 20.36' N66*32'46*W | LINE LENGTH BEARING L1 91.85 \$63*10'17*V L2 79.17 N43*58'49*E | 611 |
| C3 305.00' 262.80' 254.75' \$75*59'53'W C53 365.00' 221.39' 218.01' N85*41'25'W C4 305.00' 134.37' 133.29' \$38*41'34'W C54 365.00' 92.90' 92.65' \$84*13'26'W C5 190.00' 26.12' 26.10' N30*00'36'E C55 365.00' 128.50' 127.83' N78*23'57'W | L3 37.78 N70*32'39'E L4 122.32 \$86*13'46'E L5 62.45 \$68*25'24'E | End Store |
| C6 30.00' 25.23' 24.49' S71*03'42*E C56 365.00' 252.95' 247.92' S45*55'29*W C7 60.00' 289.42' 80.00' N43*01'59*E C57 365.00' 246.90' 242.22' S46*23'58*W C8 60.00' 61.72' 59.03' N65*41'15*W C58 365.00' 6.05' 6.05' S26*32'46*W | L6 115.34 \$60*36'23*E L7 148.63 \$85*47*18*E L8 128.06 N73*15'41*E | 1-1 |
| C9 60.00' 68.69' 65.00' N03*25'17'W C59 130.00' 116.65' 112.78' N51*46'39*E C10 60.00' 68.69' 65.00' N62*10'22'E C60 270.00' 67.44' 67.27' S70*19'38*W C11 60.00' 68.69' 65.00' S52*13'58*E C61 230.00' 148.93' 146.34' N44*37'17*E C12 60.00' 21.63' 21.52' S09*06'23*E C62 270.00' 82.05' 81.74' N59*36'29*W | L9 167.47 N31*14'33*E L10 72.08 S08*58*51*W L11 109.44 N14*31*08*W L12 95.23 N37*13*14*W | 11/1/ |
| C12 C000 E1.65 E1.65 S19 V0 C3 E C06E E7.60 SE.05 G1.74 N93 SE E7 C13 30.00' 25.23' 24.49' N22*52'19*W C63 170.00' 143.62' 139.39' N87*22'26'E C14 190.00' 84.12' 83.43' N64*48'02*E C64 170.00' 124.40' 121.65' S42*12'26'W C15 210.00' 52.46' 52.32' S70*19'38*W C65 230.00' 40.63' 40.58' N31*53'23*W | L13 107.24 N17'18'16'E L14 79.13 N26'04'17'E L15 51.11 \$22'53'02'E | 14/14 |
| C16 230.00' 194.31' 188.58' N87*22'26'E C66 170.00' 111.18' 109.21' S18*12'57'E C17 230.00' 89.97' 89.40' N74*22'38'E C67 230.00' 93.95' 93.30' N11*10'56'W C18 230.00' 104.34' 103.45' S81*25'12'E C68 170.00' 132.24' 128.93' S89*24'04'W | L16 104.12 N68'18'41'W L17 72.23 N26'04'17'E L18 18.40 \$26'04'17'V | |
| C19 170.00' 143.62' 139.39' S87*22'26'W C69 230.00' 194.75' 188.98' S02*34'17'E C20 170.00' 84.69' 83.82' N82*41'45'W C70 230.00' 48.88' 48.78' S15*35'54'W C21 170.00' 58.93' 58.63' S73*06'06'W C71 230.00' 98.62' 97.87' S02*46'23*E | L19 61.21 \$35*00*51*W | 1.1/1 |
| C22 35.00' 28.60' 27.82' S39*45'29*W C72 230.00' 47.25' 47.17' S20*56'34'E C23 60.00' 286.57' 82.11' S26*49'43'E C73 390.00' 68.90' 68.81' N31*53'23*W C24 60.00' 93.96' 84.65' N61*12'34'E C74 390.00' 114.04' 113.63' N07*51'26'W | 11/1/1/1 | ×, / / / |
| C25 60.00' 62.83' 60.00' S43*55'34*E C75 390.00' 23.45' 23.44' N01*12'11'W C26 60.00' 62.83' 60.00' S16*04'26*W C76 390.00' 90.59' 90.39' N09*34'47'W C27 60.00' 66.94' 63.52' S78*02'09*W C77 390.00' 330.23' 320.45' S02*34'17*E C28 35.00' 28.60' 27.82' N86*35'04*E C78 390.00' 83.06' 82.91' S15*35'04*W | VIIIII | AIN. |
| C28 35.00' 28.60' 27.82' N86*35'04*E C78 390.00' 83.06' 82.91' S15*35'04*W C29 230.00' 186.75' 181.66' S86*25'54*W C79 390.00' 167.14' 165.86' S02*47'39*E C30 230.00' 93.37' 92.73' S74*48'05*W C80 390.00' 80.03' 79.89' S20*57'00*E C31 230.00' 93.37' 92.73' N81*56'18*W C81 170.00' 143.95' 139.68' S02*34'17*E | VIXIIII | ×// 18 |
| C32 C33.00' 168.31' 164.58' S42*12'26'W C82 170.00' 143.55' 139.56' S02 34 17'E' C32 230.00' 168.31' 164.58' S42*12'26'W' C82 170.00' 110.08' 108.16' N44*37'17'E' C33 230.00' 125.71' 124.15' S36*54'01'W' C83 10.00' 6.48' 6.36' N44*37'17'E' C34 230.00' 42.61' 42.55' S57*51'52*V' C84 115.00' 171.84' 156.29' S68*52'44'W' | | NTE |
| C35 170.00' 30.03' 29.99' N31*53'23'W C85 115.00' 39.09' 38.90' N78*03'04'W C36 230.00' 150.42' 147.75' S18*12'57'E C86 115.00' 78.08' 76.59' S72*45'39'W C37 230.00' 21.87' 21.86' S34*13'35'E C87 115.00' 54.67' 54.16' S39*41'27'W | | V/A |
| C38 230.00' 105.08' 104.17' S18*24'48*E C88 440.00' 246.64' 243.43' N79*13'48*E C39 230.00' 23.46' 23.45' S02*24'10*E C89 440.00' 30.44' 30.44' N65*09*12*E C40 170.00' 69.44' 68.96' N11*10'56*V C90 440.00' 216.20' 214.03' N81*12'43*E | ZONE B JARLEN | |
| C41 60.00' 260.10' 99.26' N78*41'35*V C91 420.00' 120.58' 120.17' S76*38'54*E C42 60.00' 46.26' 45.12' S00*47'50*E C92 250.00' 953.12' 472.13' S17*41'24*E C43 60.00' 62.83' 60.00' S51*17'22*V C93 250.00' 231.18' 223.03' N79*34'57*E | - + - ZONE ALBA | N/ / X |
| C44 60.00' 66.91' 63.50' N66*45'41'\v C94 250.00' 261.80' 250.00' \$43*55'34'E C45 60.00' 84.10' 77.38' N05*20'34'E C95 250.00' 261.80' 250.00' \$16*04'26'\v C46 35.00' 41.77' 39.34' \$11*18'25'\v C96 250.00' 183.62' 179.52' \$67*06'55'\v C47 230.00' 178.92' 174.44' \$89*24'04'\v C97 250.00' 14.71' 14.71' \$89*50'34'\v | No Ville X X X X | */ X / / / |
| C47 230.00' 178.92' 174.44' S89*24'04*W C97 250.00' 14.71' 14.71' S89*50'34*W C48 230.00' 81.92' 81.49' S77*19'11*W C98 420.00' 346.16' 336.44' S86*46'57*W C49 230.00' 96.99' 96.28' N80*23'42*W C99 420.00' 170.51' 169.34' S74*48'05*W C50 330.00' 100.29' 99.90' N59*36'29*W C100 420.00' 175.65' 174.37' N81*35'14*W | SO NO CUT BUFFER | |
| SEWAGE DISPOSAL: | | |
| NO PERSON SHALL PROVIDE A METHOD OF SEWAGE DISPOSAL, EXCEPT CONNECTION TO AN APPROVED SANITARY SEWER SYSTEM, UNTIL THE | KELLY DEAN MOTICHEK (NOW OR FORMERLY) | DEDICATIO |
| METHOD OF SEWAGE TREATMENT AND DISPOSAL HAS BEEN APPROVED BY THE STATE BOARD OF HEALTH. | USE: A-1 SUBURBAN | AND DESCRIBED HER AND ACCURATE PLA |
| | GENERAL NOTES 1.) AT&T AND OTHER UTILITY PROVIDERS MAY PLACE | EASEMENTS SHALL BE |
| THIS SURVEY WAS PREPARED AT THE REQUEST AND FOR THE EXCLUSIVE USE OF: | THEIR INFRASTRUCTURE WITHIN THE GREENSPACE. 2.) WETLAND INFORMATION PROVIDED BY BIOLOGICAL SURVEYS, INC. | BEING USED FOR THEIL THE DRAINAGE SERVITI |
| THIS FIRM WAS NOT CONTRACTED TO PERFORM A COMPLETE TITLE | 3.) MAX. HEIGHT OF BLDG.: 40'4.) ACTIVE AMENITIES: WOODEN BARN/OUTDOOR EVENT AREA | HOMEOWNERS ASSOCIA MAINTENANCE THEREOR |
| ABSTRACT OF THE PROPERTY SHOWN HEREON. BE AWARE THAT SERVITUDES SHOWN HEREON WERE TAKEN FROM REFERENCE DATA AND | 5.) FLOODPLAIN REQUIRES FILL MITIGATION CONSISTENT WITH NO NET FILL.6.) SEWER AND WATER SERVICE ARE AVAILABLE AT THIS SITE. | COMMON AREAS ARE A ASSOCIATION. ST. TAI THEREOF. |
| THAT OTHER SERVITUDES, ENCUMBRANCES OR RESTRICTIONS, EITHER VISIBLE OR NOT VISIBLE, MAY AFFECT THE SUBJECT PROPERTY. | 7.) THE MINIMUM CULVERT SIZES TO BE USED FOR DRIVEWAYS ARE LABELED ON THE DRAINAGE PLAN. | STREETS ARE NOT DEL STREETS ARE TO BE M |
| CERTIFICATION: THIS IS TO CERTIFY THAT THIS MAP IS MADE IN ACCORDANCE WITH | 8.) ALL LOT CORNERS ARE SET 1/2" RON RODS UNLESS OTHERWISE NOTED. | ASSOCIATION OR ITS S |
| LOUISIANA REVISED STATUTES 33:5051 AND CONFORMS TO ALL PARISH ORDINANCES GOVERNING THE SUBDIVISION OF LAND. THIS MAP IS MADE IN ACCORDANCE WITH THE STANDARDS OF PRACTICE FOR BOUNDARY SURVEYS | | DEVELOPMENT MANUAL STREET NAME SIGNS A |
| FOR CLASS "C" SURVEYS AND IT WAS THE INTENT TO SUBDIVIDE THE TRACT INTO THE PLATTED SUBDIVISION. THIS CERTIFICATION IS SPECIFICALLY | OF LOUISIA | MAINTAINED BY THE H |
| RESTRICTED TO THE CLIENT FOR THE REQUIRED SUBDIVISION OF PROPERTY ONLY, AND DOES NOT EXTEND TO THIRD PARTIES UNLESS THE PLAT IS PROPERLY REVISED BY THE CERTIFIER TO REFLECT SAME. | ison with the second state | TCE PROPE |
| Set a the 22 | LESTER A. McLIN, JR. = License No. 4470 REGISTERED | 2 PINECREST DR COVINGTON, LA (985) 351-4814 |
| LESTER A. McLIN, JR. DATE | PROFESSIONAL PROFESSIONAL | Clust |
| PROFESSIONAL LAND SURVEYOR LICENSE #4470 | SURVE IN SURVE | 2 PINECREST DR |
| McLIN TAYLOR, INC. | | COVINGTON, LA (985) 351-4814 |

