### HAZARDOUS MATERIALS SURVEY

### ASBESTOS LEAD-BASED PAINT

for

Residential Structure 220 W. 1st Ave. Toppenish, WA 98948

Project #A2024/1004

08/25/2024

prepared for:

City of Toppenish
Dan Ford, PE
21 W 1st Ave
Toppenish, WA 98948
Dan.Ford@cityoftoppenish.us

prepared by:

Richard Cersome

Blue Mountain Environmental & Consulting Co., Inc.

PO Box 545/125 Main Street Waitsburg, WA 99361 (509) 337-6403

### TABLE OF CONTENTS

1		Introduction	2
2		Scope of Work	3
	Asbe	estos Survey	3
	Lead	l in Construction Assessment	3
3		General Site Conditions	4
	3.1	General Property and Building Information	4
	3.2	Exterior Finish Descriptions	4
	3.3	Interior Finish Descriptions	4
4		Asbestos Containing Materials	5
	4.1	Homogeneous Areas	5
	4.2	Laboratory Analytical Methodology	5
	4.3	Sampling Results	5
5		Lead Containing Paint	7
	5.3	Paint Chip Sample Collection for Laboratory Analysis	8
	5.4	Components Identified During the Inspection	8
6		Findings and Recommendations	9
	Asbe	estos-Containing Materials	9
	Lead	I	9
7		Limitations	10
Asbe	stos Lal	b Data	
Asbe	stos Saı	mple Photos	
		1	
		1 0	
	-		
	-	•	
Profe	essional	Certifications	
	3  4  5  6  7  Asbe Asbe Asbe Lead Paint Lab (	Asbestos La Asbestos Sar Asbestos Sar Asbestos Sar Lead Sample Paint Chip S Lab Certifications Lead Sample Paint Chip S Lab Certifications Lab Cer	2 Scope of Work  Asbestos Survey

i

### **EXECUTIVE SUMMARY**

City of Toppenish retained Blue Mountain Environmental & Consulting Co., Inc. (BMEC) to perform a pre renovation HazMat assessment specific to asbestos and lead based paint at 220 W. 1<sup>st</sup>. Ave. Toppenish, WA 98948.

On October 17, 2024, Richard DeLorme with BMEC completed the hazardous building materials inspection. The survey was conducted in accordance with Blue Mountain Environmental & Consulting Company, Inc.'s written proposal dated October 9, 2024.

### **Asbestos-Containing Materials**

Thirty-Five (35) bulk samples were collected for analysis. The results of laboratory testing confirm zero (0) homogeneous materials sampled from the Subject Property were found to contain asbestos >1%.

### Lead

The Washington State Department of Labor and Industries (L&I) Lead in Construction Standard (WAC 296-155-1760) applies to demolition-related tasks that impact materials with detectable level of lead. One of six samples collected for lead have detectable levels of lead, specifically the white concrete exterior wall located in the former "apartment".

Demolition/Renovation Contractor(s) must be notified by the Owner, prior to the start of demolition/renovation activities that detectable levels of lead were identified in some of the painted surfaces sampled, and that all work must be completed in accordance with the United States, Occupational Safety and Health Administration's (OSHA) Lead Standard for the Construction Industry, Title 29 Code of Federal Regulations 1926.62, as amended on March 26, 2012, and Washington State Department of Labor and Industries, Division of Occupational Safety and Health WAC 296-62-07521.

1

### 1 Introduction

City of Toppenish retained Blue Mountain Environmental & Consulting Co., Inc. (BMEC) to perform a pre renovation HazMat assessment specific to asbestos and lead based paint at 220 W. 1st. Ave. Toppenish, WA 98948.

On October 17, 2024, Richard DeLorme with BMEC completed the hazardous building materials inspection. See Appendix G for applicable certifications.

### 2 SCOPE OF WORK

BMEC's scope of work consisted of site inspections, material sampling, sample analysis, and reporting. All inspection tasks were completed by accredited, certified, or qualified professionals.

### **ASBESTOS SURVEY**

The scope of the asbestos survey encompassed the Subject Property included the following:

- 1. Reviewing existing asbestos reports for the Subject Property, if available.
- 2. Identification of accessible suspect asbestos-containing materials (ACMs) that may be disturbed during renovations.
- 3. Collection of bulk samples for PLM analysis of suspect friable and non-friable materials.
- 4. Describing types, locations, and estimated quantities of identified ACM and PACM.

### LEAD IN CONSTRUCTION ASSESSMENT

1. Collect paint chip samples for lead based paint to comply with OSHA's Lead Standard for the Construction Industry, Title 29 Code of Federal Regulations 1926.62. applies to demolition/renovation-related tasks that impact materials with detectable level of lead.

### **3** GENERAL SITE CONDITIONS

### 3.1 GENERAL PROPERTY AND BUILDING INFORMATION

General property and building information are partly extrapolated from the Yakima County Assessors website, site reconnaissance, prior assessments or presented by the site official and are presented in the following table:

Table 2-1
General Property Information

Date of Inspection:	October 17, 2024
	Richard DeLorme
	Asbestos Building Inspector
Inspectors:	Certification Number ASI-BIR-24-059
	Department of Commerce Lead Risk Assessor
	Cert#6085
Property Address:	220 W. 1 <sup>st</sup> Ave.
Property Address.	Toppenish, WA 98948
Parcel Number(s):	201010-22426
Property Owner	Jon Alke LLC
Property Owner Address	Unknown
Property Owner Telephone No.	Unknown
Building Construction Date:	1935
Date(s) of Significant	Unknown
Renovations:	Unknown
Building Description:	Subject property is a single-level, commercial
Building Description.	structure.
Building Square Footage (Approximate):	Subject property encompasses approximately 5,192 sf.

### 3.2 EXTERIOR FINISH DESCRIPTIONS

The Subject Property is currently unoccupied. The Subject Property is wood framed with hardwood siding construction finished with flat built-up roofing.

### 3.3 Interior Finish Descriptions

The former office/medical structure is finished with gypsum wallboard sheathed walls and ceilings. The flooring is finished with ceramic tiles and carpet.

### 4 ASBESTOS CONTAINING MATERIALS

Blue Mountain Environmental & Consulting Company, Inc. representatives Richard DeLorme conducted the asbestos inspection of the Subject Property on October 17, 2024. The Subject Property was visually inspected for the presence of building materials that are suspected to contain asbestos. Bulk samples of suspect asbestos containing materials (ACM) were collected and placed into individual containers for transport under Chain of Custody protocol, to a National Voluntary Lab Accreditation Program (NVLAP) accredited laboratory for polarized-light microscopy analysis. Materials typically known as non-asbestos items, i.e., wood, glass or metal were not sampled. The asbestos inspection consisted of the following three basic procedures:

- 1. Conducting a visual inspection of the structure(s).
- 2. Identifying homogeneous areas of suspect surfacing, thermal system insulation, and miscellaneous materials.
- 3. Sampling accessible, friable, and non-friable suspect materials.

### 4.1 HOMOGENEOUS AREAS

Prior to collecting any samples, homogenous areas were identified. A homogeneous sampling area can be described as one or more areas of material that are similar in appearance and texture and that have the same apparent installation date, appearance, and function. The actual number of samples collected from each homogeneous sampling area may vary, based on the type of material and professional opinion of the inspector.

### 4.2 LABORATORY ANALYTICAL METHODOLOGY

Bulk samples were analyzed by EMC Labs Inc. 9830 S. 51st St., Ste B-109 Phoenix, AZ 85044, using polarized-light microscopy (PLM) and dispersion staining (Method Reference: 40 CFR Part 763, Volume 47, No. 103, May 27, 1982, pg. 23376). This laboratory participates in the National Voluntary Laboratory Accreditation Program (NVLAP #101926-0), a quality assurance program for PLM analysis, and is accredited by the National Institute of Standards and Technology (NIST) as well as accreditation requirements under 15 CFR Part 25.

### 4.3 SAMPLING RESULTS

Bulk samples were collected from the Subject Property and analyzed by PLM utilizing EPA Method 600/R-93/116.

• Thirty-Five (35) samples were collected for analysis. The results of laboratory analysis confirm zero (0) homogeneous materials sampled from the Subject Property were found to contain asbestos >1%. Identified ACM, Non-ACM and PACM are summarized in Table 3-4 below.

Table 3-4 Summary Table

### 220 W. 1st Ave., Toppenish, WA 98948

Material Sample #	Description	Asbestos	Approximate Square Feet
400	Gray Floor Leveler w/Tan Mastic	N/D	-
401	Brown Carpet Tan Mastic	N/D	-
500	Gypsum Wallboard w/Orange Peel Texture/Joint Compound	N/D	-
501	Gypsum Wallboard w/Heavy Orange Peel Texture w/Joint Comp.	N/D	-
502	4" Gray Covebase w/Mastic	N/D	-
503	FRP w/Mastic	N/D	-
600	2x4 Suspended Ceiling Tile	N/D	-
601	2X2 Suspended Ceiling Tiles	N/D	-
900	Stainless Steel Sink White Undercoat	N/D	-

N/D-Non-Detect for asbestos.

Laboratory results of the asbestos sampling are included in Appendix A, Asbestos Sample Photos Appendix B and Sample Drawing Appendix C.

### 5 LEAD CONTAINING PAINT

### 5.1 Regulatory Basis

The purpose of the LBP investigation is to facilitate pending demolition activities in compliance with pertinent regulations while protecting workers, the public, and the environment. For purposes of this investigation, LBP are being evaluated under or based upon the following regulations:

- WAC 296-155-176, Lead
- OSHA 29 CFR 1910.1025(a)(2) Lead

The most stringent lead regulations are found in the lead in construction regulations administered by the Occupational Safety and Health Administration (OSHA), in federally managed areas, and the Department of Occupational Safety and Health (DOSH) in Washington State. Under these worker protection regulations any material containing a detectable concentration of lead is LBP. Lead in construction regulations apply to all work environments during many types of tasks including, but not limited to, the following:

- Demolition or salvage of structures where lead or materials containing lead are present.
- Removal or encapsulation of materials containing lead.
- New construction, alteration, repair, or renovation of structures, substrates, or portions thereof, that contain LBP or materials containing lead.
- Transportation, disposal, storage, or containment of LBP or materials containing lead on the site or location at which construction activities are performed; and
- Maintenance operations associated with the construction activities described in this section.

### 5.2 Inspection and Sampling Methodology

A visual inspection of accessible portions of the investigation area was conducted. The inspection was conducted in substantial conformance with applicable regulatory and industry standards. Relevant regulatory and industry standards include Washington State lead-based paint regulations. The LCM inspection consists of the following basic steps:

- Identification of homogenous areas and components
- Paint Chip sample collection for laboratory analysis

Characteristic painted surfaces were classified as homogeneous areas based on color of surface paint, substrate, construction era, and in some cases, color of sublayers. Homogeneous materials are one of the key elements for referencing both lead and non-lead materials identified during the inspection and used within this report. Sample locations in the facility were selected to be representative of the various homogeneous areas. Full-layer thicknesses of existing paint were evaluated to obtain a historical representation of all paints applied to the tested component.

For this inspection report, homogeneous areas/materials were developed using surface color, and component composition as primary considerations, supported by visual observations made in the painted surfaces were then sampled to determine if they contain lead or are non-lead containing based on laboratory results.

### 5.3 PAINT CHIP SAMPLE COLLECTION FOR LABORATORY ANALYSIS

BMEC's certified Lead Inspector or Risk Assessor collected paint chip samples of select building materials where homogenous materials were visually identified. Paint chip sample analytical results are used to determine if the lead concentrations in the paint are appropriate for disclosure to the project contractor for worker protection purposes.

Paint chip samples were submitted to EMC Labs accredited laboratory (102063-0) located in Phoenix, Arizona, an Environmental Lead Proficiency Analytical Testing (ELPAT) Program certified laboratory. Submitted samples are analyzed by EPA SW-846 METHOD 7420 for total lead. See Appendix E for complete Lead Analytical Results.

### 5.4 COMPONENTS IDENTIFIED DURING THE INSPECTION

During this inspection Six (6) paint chip samples were taken. The results from the paint chip samples are summarized below and laboratory results in Appendix E and paint chip sample photos Appendix F.

Material Sample #	Color Substrate Component	Location Sample Collected	Analysis Results (PPM)
Pb-1	Yellow-GWB-Wall	Interior	BRL
Pb-2	Yellow-GWB-Wall	Interior	BRL
Pb-3	Brown-GWB-Wall	Interior	BRL
Pb-4	Brown-GWB-Wall	Interior	BRL
Pb-5	White-Wood-Door Casing	Interior	BRL
Pb-6 See Photo#6	White-Concrete-Wall	Interior	5350

<sup>\*</sup>BRL-Below Reportable Limit

### **6** FINDINGS AND RECOMMENDATIONS

### ASBESTOS-CONTAINING MATERIALS

Thirty-Five (35) bulk samples were collected for analysis. The results of laboratory testing confirm zero (0) homogeneous materials sampled from the Subject Property were found to contain asbestos >1% and one (1) homogeneous sample <1% asbestos.

### **LEAD**

The Washington State Department of Labor and Industries (L&I) Lead in Construction Standard (WAC 296-155-1760) applies to demolition-related tasks that impact materials with detectable level of lead. One of six samples collected for lead have detectable levels of lead, specifically the white concrete exterior wall located in the former "apartment".

Demolition Contractor(s) must be notified by the Owner, prior to the start of demolition activities that detectable levels of lead were identified in some of the painted surfaces sampled, and that all work must be completed in accordance with the United States, Occupational Safety and Health Administration's (OSHA) Lead Standard for the Construction Industry, Title 29 Code of Federal Regulations 1926.62, as amended on March 26, 2012, and Washington State Department of Labor and Industries, Division of Occupational Safety and Health WAC 296-62-07521.

### 7 LIMITATIONS

BMEC Environmental Consulting, Inc.'s scope of services for this project was limited to a Hazardous Building Materials inspection of the building located at 220 W. 1st Ave., Toppenish, WA 98948 as outlined in the preceding sections. Results are specific to the time and day of inspection and may not reflect conditions at other times.

This document does not contain the elements necessary for an Abatement Workplan, and this document does not contain, nor should it take the place of technical specifications for ACM or LBP removal.

If the scope of work should change, including impact to materials not tested during this inspection or if new suspect materials are identified, the contractor(s) should stop work and contact BMEC to conduct additional sampling and analysis.

### APPENDIX A ASBESTOS LAB DATA

Laboratory Report 0321072

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044 Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

### **Bulk Asbestos Analysis by Polarized Light Microscopy**

NVLAP# 101926-0

Client: BLUE MOUNTAIN ENV. CONSULTING

125 MAIN STREET

WAITSBURG,, WA 99361

Collected: 10/17/2024

Project Name: DEMOLITION ASBESTOS SURVEY-220

W. 1ST AVE., TOPPENISH, WA

Address:

Address:

Job# / P.O. #: A2024 1003

Date Received: 10/21/2024

Date Analyzed: 10/24/2024

Date Reported: 10/24/2024

Submitted By: RICHARD DeLORME

Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbesto Detected	s Asbestos Type d (%)	Non-Asbestos Constituents	
0321072-001 400.1		LAYER 1 Leveling Compound, Gray	No	None Detected	Carbonates Quartz Gypsum Non-Fibrous Binder/Filler	100%
		LAYER 2 Mastic, Brown	No	None Detected	Cellulose Fiber Synthetic Fiber Carbonates Gypsum Quartz Non-Fibrous Binder/Filler	1% <1%
0321072-002 400.2		LAYER 1 Leveling Compound, Gray	No	None Detected	Carbonates Quartz Gypsum Non-Fibrous Binder/Filler	100%
		LAYER 2 Mastic, Brown Note: Difficult to separate adjacent layers	No	None Detected	Carbonates Gypsum Quartz Non-Fibrous Binder/Filler	100%
0321072-003 400.3		LAYER 1 Leveling Compound, Gray	No	None Detected	Carbonates Quartz Gypsum Non-Fibrous Binder/Filler	100%
		LAYER 2 Mastic, Brown	No	None Detected	Cellulose Fiber Synthetic Fiber Carbonates Gypsum Quartz	1% <1%
					Non-Fibrous Binder/Filler	98%

**Laboratory Report** 0321072

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044 Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

### **Bulk Asbestos Analysis by Polarized Light Microscopy**

NVLAP# 101926-0

Client: BLUE MOUNTAIN ENV. CONSULTING Address:

125 MAIN STREET

WAITSBURG,, WA 99361

Collected: 10/17/2024

Project Name: DEMOLITION ASBESTOS SURVEY-220

W. 1ST AVE., TOPPENISH, WA

Address:

Job# / P.O. #: A2024 1003

Date Received: 10/21/2024

Date Analyzed: 10/24/2024

Date Reported: 10/24/2024

Submitted By: RICHARD DeLORME

Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbesto Detected	s Asbestos Type	Non-Asbestos Constituents	
0321072-004		LAYER 1	No	None Detected	Synthetic Fiber	85%
401.1		Carpet, Brown			Carbonates Non-Fibrous Binder/Filler	15%
		LAYER 2 Mastic, Tan/ Yellow	No	None Detected	Carbonates Quartz Non-Fibrous Binder/Filler	100%
0321072-005		LAYER 1	No	None Detected	Synthetic Fiber	85%
401.2		Carpet, Brown			Carbonates Non-Fibrous Binder/Filler	15%
		LAYER 2	No	None Detected	Cellulose Fiber	<1%
		Mastic, Tan/ Yellow			Carbonates Quartz Non-Fibrous Binder/Filler	99%
0321072-006		LAYER 1	No	None Detected	Synthetic Fiber	85%
401.3		Carpet, Brown			Carbonates Non-Fibrous Binder/Filler	15%
		LAYER 2	No	None Detected		
		Mastic, Tan/ Yellow			Carbonates Quartz Non-Fibrous Binder/Filler	100%
0321072-007		LAYER 1	No	None Detected		
500.1		Joint Compound, White Note: No Gypsum Wallboard Present			Carbonates Perlite Non-Fibrous Binder/Filler	100%
		LAYER 2	No	None Detected	143H-1 IDIOUS DINUEI/I IIIEI	10070
		Orange Peel Texture/ Paint, Whit		<b>25.63.63</b>	Carbonates Perlite	
					Non-Fibrous Binder/Filler	100%

**Laboratory Report** 0321072

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044 Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

### **Bulk Asbestos Analysis by Polarized Light Microscopy**

NVLAP# 101926-0

Client: BLUE MOUNTAIN ENV. CONSULTING Address:

125 MAIN STREET

WAITSBURG,, WA 99361

Collected: 10/17/2024

Project Name: DEMOLITION ASBESTOS SURVEY-220

W. 1ST AVE., TOPPENISH, WA

Address:

Job# / P.O. #: A2024 1003

Date Received: 10/21/2024

Date Analyzed: 10/24/2024

Date Reported: 10/24/2024

Submitted By: RICHARD DeLORME

Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbesto Detected	s Asbestos Type d (%)	Non-Asbestos Constituents	
0321072-008 500.2		LAYER 1 Joint Compound, White Note: No Gypsum Wallboard Present	No	None Detected	Carbonates Perlite Non-Fibrous Binder/Filler	100%
		LAYER 2 Orange Peel Texture/ Paint, Whi	No ite	None Detected	Carbonates Perlite Non-Fibrous Binder/Filler	100%
0321072-009 500.3		LAYER 1 Drywall, White/ Beige	No	None Detected	Cellulose Fiber Gypsum Carbonates Non-Fibrous Binder/Filler	10%
		LAYER 2 Joint Compound, White	No	None Detected	Carbonates Perlite Non-Fibrous Binder/Filler	100%
		LAYER 3 Orange Peel Texture/ Paint, Whi	No te	None Detected	Carbonates Perlite Non-Fibrous Binder/Filler	100%
0321072-010 500.4		LAYER 1 Joint Compound, White Note: No Gypsum Wallboard Present	No	None Detected	Carbonates Perlite Non-Fibrous Binder/Filler	100%
		LAYER 2 Orange Peel Texture/ Paint, Whi	No te	None Detected	Carbonates Perlite Non-Fibrous Binder/Filler	100%

**Laboratory Report** 0321072

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044 Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

### **Bulk Asbestos Analysis by Polarized Light Microscopy**

NVLAP# 101926-0

Client: BLUE MOUNTAIN ENV. CONSULTING Address:

125 MAIN STREET

WAITSBURG,, WA 99361

Collected: 10/17/2024

Project Name: DEMOLITION ASBESTOS SURVEY-220

W. 1ST AVE., TOPPENISH, WA

Address:

Job# / P.O. #: A2024 1003

Date Received: 10/21/2024

Date Analyzed: 10/24/2024

Date Reported: 10/24/2024

Submitted By: RICHARD DeLORME

Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbesto Detected	s Asbestos Type i (%)	Non-Asbestos Constituents	
0321072-011 500.5		LAYER 1 Joint Compound, White Note: No Gypsum Wallboard Present	No	None Detected	Carbonates Perlite Non-Fibrous Binder/Filler	100%
		LAYER 2 Orange Peel Texture/ Paint, Whi	No te	None Detected	Carbonates Perlite Non-Fibrous Binder/Filler	100%
0321072-012		LAYER 1	No	None Detected	Cellulose Fiber	10%
500.6		Drywall, White/ Beige			Gypsum Carbonates Non-Fibrous Binder/Filler	90%
		LAYER 2 Joint Compound, White	No	None Detected	Carbonates Perlite Non-Fibrous Binder/Filler	100%
		LAYER 3		None Detected	Cellulose Fiber	<1%
		Orange Peel Texture/ Paint, Whi	te		Carbonates Perlite Non-Fibrous Binder/Filler	99%
0321072-013		LAYER 1	No	None Detected	Cellulose Fiber	10%
500.7		Drywall, White/ Beige			Gypsum Carbonates Non-Fibrous Binder/Filler	90%
		LAYER 2 Joint Compound, White	No	None Detected	Carbonates Perlite Non-Fibrous Binder/Filler	100%
		LAYER 3 Orange Peel Texture/ Paint, White	No te	None Detected	Carbonates Perlite	
					Non-Fibrous Binder/Filler	100%

**Laboratory Report** 0321072

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044 Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

### **Bulk Asbestos Analysis by Polarized Light Microscopy**

NVLAP# 101926-0

Client: BLUE MOUNTAIN ENV. CONSULTING Address:

125 MAIN STREET

WAITSBURG,, WA 99361

Collected: 10/17/2024

Project Name: DEMOLITION ASBESTOS SURVEY-220

W. 1ST AVE., TOPPENISH, WA

Collected By:

RICHARD DeLORME

Job# / P.O. #: A2024 1003

Date Received: 10/21/2024 Date Analyzed: 10/24/2024

Date Reported: 10/24/2024

Submitted By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbesto: Detected	s Asbestos Type I (%)	Non-Asbestos Constituents	
0321072-014 500.8		LAYER 1 Joint Compound, White Note: No Gypsum Wallboard Present	No	None Detected	Carbonates Gypsum Perlite Non-Fibrous Binder/Filler	100%
		LAYER 2 Orange Peel Texture/ Paint, Whit		None Detected	Cellulose Fiber Carbonates Perlite Non-Fibrous Binder/Filler	<1% 99%
0321072-015 500.9		LAYER 1 Joint Compound, White Note: No Gypsum Wallboard Present	No	None Detected	Carbonates Gypsum Perlite Non-Fibrous Binder/Filler	100%
		LAYER 2 Orange Peel Texture/ Paint, Whit		None Detected	Carbonates Perlite Non-Fibrous Binder/Filler	100%
0321072-016 501.1		LAYER 1 Drywall, White/ Beige	No	None Detected	Cellulose Fiber Gypsum Carbonates Non-Fibrous Binder/Filler	10%
		LAYER 2 Joint Compound, White	No	None Detected	Gypsum Quartz Perlite Non-Fibrous Binder/Filler	100%
		LAYER 3 Orange Peel Texture/ Paint, Whit	110	None Detected	Gypsum Quartz Perlite Non-Fibrous Binder/Filler	100%

**Laboratory Report** 0321072

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044 Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

### **Bulk Asbestos Analysis by Polarized Light Microscopy**

NVLAP# 101926-0

Client: BLUE MOUNTAIN ENV. CONSULTING Address:

125 MAIN STREET

WAITSBURG,, WA 99361

Collected: 10/17/2024

Project Name: DEMOLITION ASBESTOS SURVEY-220

W. 1ST AVE., TOPPENISH, WA

Address:

Job# / P.O. #: A2024 1003

Date Received: 10/21/2024

Date Analyzed: 10/24/2024

Date Reported: 10/24/2024 Submitted By: RICHARD DeLORME

Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbesto: Detected	s Asbestos Type i (%)	Non-Asbestos Constituents	
0321072-017 501.2		LAYER 1 Drywall, White/ Beige	No	None Detected	Cellulose Fiber Gypsum	10%
					Carbonates Non-Fibrous Binder/Filler	90%
		LAYER 2 Joint Compound, White	No	None Detected	Gypsum Quartz Perlite Non-Fibrous Binder/Filler	100%
		LAYER 3 Orange Peel Texture/ Paint, Whit		None Detected	Gypsum Quartz Perlite Non-Fibrous Binder/Filler	100%
0321072-018		LAYER 1	No	None Detected	Cellulose Fiber	10%
501.3		Drywall, White/ Beige			Gypsum Carbonates Non-Fibrous Binder/Filler	90%
		LAYER 2 Joint Compound, White	No	None Detected	Carbonates Quartz Non-Fibrous Binder/Filler	100%
		LAYER 3 Orange Peel Texture/ Paint, Whit		None Detected		
		orange roof romaio, raini, viini			Carbonates Quartz Non-Fibrous Binder/Filler	100%
0321072-019		LAYER 1	No	None Detected	Cellulose Fiber	10%
501.4		Drywall, White/ Beige			Gypsum Carbonates Non-Fibrous Binder/Filler	90%
		LAYER 2 Orange Peel Texture/ Paint, Whit		None Detected	Cellulose Fiber	<1%
		Note: Layer is mainly Paint - little Texture present			Carbonates Perlite Non-Fibrous Binder/Filler	99%

Laboratory Report 0321072

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044 Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

### **Bulk Asbestos Analysis by Polarized Light Microscopy**

NVLAP# 101926-0

Client: BLUE MOUNTAIN ENV. CONSULTING

Address: 125 MAIN STREET

WAITSBURG,, WA 99361

Collected: 10/17/2024

Project Name: DEMOLITION ASBESTOS SURVEY-220

W. 1ST AVE., TOPPENISH, WA

Address:

Job# / P.O. #: A2024 1003

Date Received: 10/21/2024

Date Analyzed: 10/24/2024

Date Reported: 10/24/2024

Submitted By: RICHARD DeLORME

Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbesto: Detected	s Asbestos Type I (%)	Non-Asbestos Constituents
0321072-020 501.5	LAYER 1 Joint Compound, White Note: No Gypsum Wallboard Present	No	None Detected	Carbonates Perlite Non-Fibrous Binder/Filler 100%	
		LAYER 2 Orange Peel Texture/ Paint, Whit		None Detected	Carbonates Gypsum Quartz Non-Fibrous Binder/Filler 100%
0321072-021 502.1		LAYER 1 4" Covebase, Gray	No	None Detected	Carbonates Quartz Non-Fibrous Binder/Filler 100%
	LAYER 2 Mastic, Yellow	No	None Detected	Carbonates Gypsum Quartz Non-Fibrous Binder/Filler 100%	
0321072-022 502.2		LAYER 1 4" Covebase, Gray	No	None Detected	Carbonates Quartz Non-Fibrous Binder/Filler 100%
		LAYER 2 Mastic, Yellow	No	None Detected	Carbonates Gypsum Quartz Non-Fibrous Binder/Filler 100%

Laboratory Report 0321072

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044 Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

### **Bulk Asbestos Analysis by Polarized Light Microscopy**

NVLAP# 101926-0

Client: BLUE MOUNTAIN ENV. CONSULTING

Address: 125 MAIN STREET

WAITSBURG,, WA 99361

Collected: 10/17/2024

Project Name: DEMOLITION ASBESTOS SURVEY-220

W. 1ST AVE., TOPPENISH, WA

Address:

Job# / P.O. #: A2024 1003

Date Received: 10/21/2024

Date Analyzed: 10/24/2024

Date Reported: 10/24/2024

Submitted By: RICHARD DeLORME

Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	s Asbestos Type I (%)	Non-Asbestos Constituents	
0321072-023 502.3		LAYER 1 4" Covebase, Gray	No	None Detected	Carbonates Quartz Non-Fibrous Binder/Filler	100%
		LAYER 2 Mastic, Yellow	No	None Detected	Carbonates Gypsum Quartz Non-Fibrous Binder/Filler	100%
0321072-024 503.1		LAYER 1 FRP, White	No	None Detected	Fibrous Glass Carbonates Quartz Non-Fibrous Binder/Filler	20%
		LAYER 2 Mastic, Yellow	No	None Detected	Carbonates Quartz Non-Fibrous Binder/Filler	100%
0321072-025 503.2		LAYER 1 FRP, White	No	None Detected	Fibrous Glass Carbonates Quartz Non-Fibrous Binder/Filler	20%
		LAYER 2 Mastic, Yellow	No	None Detected	Carbonates Quartz Non-Fibrous Binder/Filler	100%

Laboratory Report 0321072

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044 Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

### **Bulk Asbestos Analysis by Polarized Light Microscopy**

NVLAP# 101926-0

Client: BLUE MOUNTAIN ENV. CONSULTING

Address: 125 MAIN STREET

WAITSBURG,, WA 99361

Collected: 10/17/2024

Project Name: DEMOLITION ASBESTOS SURVEY-220

W. 1ST AVE., TOPPENISH, WA

Address:

Job# / P.O. #: A2024 1003

Date Received: 10/21/2024

Date Analyzed: 10/24/2024

Date Reported: 10/24/2024

Submitted By: RICHARD DeLORME

Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbesto: Detected	s Asbestos Type I (%)	Non-Asbestos Constituents	
0321072-026 503.3		LAYER 1 FRP, White	No	None Detected	Fibrous Glass Carbonates Quartz Non-Fibrous Binder/Filler	20%
		LAYER 2 Mastic, Yellow	No	None Detected	Carbonates Quartz Non-Fibrous Binder/Filler	100%
0321072-027 600.1		2x4 Ceiling Tile, White/ Beige	No	None Detected	Cellulose Fiber Mineral Wool Carbonates Perlite Non-Fibrous Binder/Filler	60% 20% 20%
0321072-028 600.2		2x4 Ceiling Tile, White/ Beige	No	None Detected	Cellulose Fiber Mineral Wool Carbonates Perlite Non-Fibrous Binder/Filler	60% 20% 20%
0321072-029 600.3		2x4 Ceiling Tile, White/ Beige	No	None Detected	Cellulose Fiber Mineral Wool Carbonates Perlite Non-Fibrous Binder/Filler	60% 20% 20%
0321072-030 601.1		2x2 Ceiling Tile, White/ Beige	No	None Detected	Mineral Wool Cellulose Fiber Carbonates Perlite Non-Fibrous Binder/Filler	50% 30% 20%

Laboratory Report 0321072

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044 Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

### **Bulk Asbestos Analysis by Polarized Light Microscopy**

NVLAP# 101926-0

Client: BLUE MOUNTAIN ENV. CONSULTING

125 MAIN STREET

WAITSBURG,, WA 99361

Collected: 10/17/2024

Project Name: DEMOLITION ASBESTOS SURVEY-220

W. 1ST AVE., TOPPENISH, WA

Address:

Address:

Job# / P.O. #: A2024 1003

Date Received: 10/21/2024

Date Analyzed: 10/24/2024

Date Reported: 10/24/2024

Submitted By: RICHARD DeLORME

Collected By:

EPA Method: App.E to Sub.E of 40 CFR Part 763 and EPA/600/R-93

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbesto Detecte	s Asbestos Type d (%)	Non-Asbestos Constituents	
0321072-031 601.2		2x2 Ceiling Tile, White/ Beige	No	None Detected	Mineral Wool Cellulose Fiber Carbonates Perlite Non-Fibrous Binder/Filler	50% 30% 20%
0321072-032 601.3		2x2 Ceiling Tile, White/ Beige	No	None Detected	Mineral Wool Cellulose Fiber Carbonates Perlite Non-Fibrous Binder/Filler	50% 30% 20%
0321072-033 900.1		Sink Undercoating, White	No	None Detected	Cellulose Fiber Carbonates Mica Non-Fibrous Binder/Filler	10% 90%
0321072-034 900.2		Sink Undercoating, White	No	None Detected	Cellulose Fiber Carbonates Mica Non-Fibrous Binder/Filler	90%
0321072-035 900.3		Sink Undercoating, White	No	None Detected	Cellulose Fiber Carbonates Mica Non-Fibrous Binder/Filler	10%

Analyst - Matt Kettler

Signatory - Lab Director - Kurt Kettler

Distinctly stratified, easily separable layers of samples are analyzed as subsamples of the whole and are reported separately for each discernible layer. All analyses are derived from calibrated visual estimate and measured in area percent unless otherwise noted. The report applies to the standards or procedures identified and to the sample(s) tested. The test results are not necessarily indicative or representative of the qualities of the lot from which the sample was taken or of apparently identical or similar products, nor do they represent an ongoing quality assurance program unless so noted. This report is for the exclusive use of the addressed client and will not be reproduced wholly or in part for advertising or other purposes over our signature or in connection with our name without special written permission. The report shall not be reproduced except in full, without written approval by our laboratory. The samples not destroyed in testing are retained a maximum of sixty days. The laboratory measurement of uncertainty for the test method is approximately less than 1 by area percent. Accredited by the National Institute of Standards and Technology, Voluntary Laboratory Accreditation Program for selected test method(s) for asbestos. The accreditation or any reports generated by this laboratory in no way constitutes or implication, approval, or endorsement by the National Institute of Standards and Technology. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the Federal Government.

Page	1	of	3	٠

### **CHAIN OF CUSTODY**

EMC Labs, Inc. 9830 S. 51<sup>st</sup> St., Ste B-109 Phoenix, AZ 85044 (800) 362-3373 Fax (480) 893-1726

LAB#: 321072
TAT: 3 day
Pagid: INT 91AM

COMPANY NA	ME: BLUE M	OUNTAIN ENV. & CO	ONSULTING		BILL TO:			(If Differen	ıt Location)	}
	P.O. Box	: 545 / 125 Main Stree	et					·	,	
	Waitsbur	g, WA 99361				··				<del></del>
CONTACT:	Ken Cole	)							· · · · · · · · · · · · · · · · · · ·	
Phone/Fax:	(509) 520	0-6519 / (509) 337-62	31							<del> </del>
Email:	USE GROU	JP EMAIL								H
Now Acce	pting: VISA – N	IASTERCARD		Price Quo	ted: \$		/ San	ple \$_		/ Layers
COMPLE	TE ITEMS 1-4:	(Failure to complete	any items ma	ay cause a c	<b>ielay in</b> pro	cessi	ng <b>or</b>	analyzin	g your s	amples)
1. TURN  ****Prior co  ****Addition  ****Laborat  2. TYPE  3. DISPO	AROUND TIME: [ nfirmation of turnarount nal charges for rush and ory analysis may be suf OF ANALYSIS: SAL INSTRUCTION (If you	4hr rush} [8hr rush] alysis (please call marketing bject to delay if credit terrore) Bulk-PLM] [Aironse] ONS: [Dispose of the document of the	sh} [1-Day]  ng department fo  ns are not met  r-PCM] [Lea  of samples at  ence, EMC will	[2-Day] or pricing detained] [Point EMC] / [R dispose of sa	3-Day is) : Count] [ eturn samp amples 60 d	[5-E Fungi ples to	Day] : AOO	[6-10 Da C, W-C, Ba at my ex	y] ulk, Swa	
'		n Asbestos Survey-22						***	<del></del>	
<u> </u>	Number:		Project N	umber: A20	24 1003			<del></del>		
EMC SAMPLE #	CLIENT SAMPLE#	DATE & TIME SAMPLED 10/17/2024	LOCA	TION/MATERI TYPE	AL	Acce	ples pted / No	AIR SAMP	LE INFO / CO	DMMENTS FLOW RATE
	400.1		Gray Floor le	veler w/Tan	Mastic	a	N	}		
3	400.2						N			
_3_	400.3		<b>→</b>			1	N		-	
4	401.1		Brown Carp	et Tan Mas	stic	Ŧ	N			
り	401.2					1	N			
6	401.3					<b>-</b>	Nł			
1	500.1		Gypsum Wa	llboard w/C	Orange	$-\int_{Y}$	N	<del> </del>		
8	500.2		Peel Texture	Joint Com	pound	<b></b>	N			1
q	500.3			**		Y	N	-		1
10	500.4					Υ	N	<del>                                     </del>	<u></u>	+
11	500.5	-			·	\ \ \				+
13	500.6						<del></del>	<del>                                     </del>		+
13	500.7			,		Y	N			
lu	500.8			<del></del> -,		Y		-	<u> </u>	+
15	500.9					Y				
SPECIAL IN	NSTRUCTIONS:	<u> </u>			<u></u>		······································	1		
	llector: (Print) Richa	rd DeLorme		/Sia	nature) <u>/26</u>	hand	110	Mour	· · · · · ·	
	ed by: <u>Makel (</u> ed by: <b>Obreen (</b>	lyon Da	ate/Time: <u>1400</u>	0/2024 <u>)hrs                                    </u>	ceived by:_	Dorg	een	Celago	_Date/T	Time: 10 3
Relinquish	ed by: <b>Ubreen</b> C	eug- Da	ate/Time: <u>IO</u> 2	New Red	ceived by:_	<b>1</b> 2	<b>-</b>		_ Date/T	-iACT 2 1 20
Relinguish	ed by:		ate/Time		eived hv					oto/Time:

\*\* In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be

in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

Page	2	of	3

### **CHAIN OF CUSTODY**

EMC Labs, Inc. 9830 S. 51st St., Ste B-109 Phoenix, AZ 85044 (800) 362-3373 Fax (480) 893-1726

LAB#:	321	07	7

TAT:

Rec'd:

COMPANY	NAME:	BLUE MOUNTA	IN ENV. & CO	NSULTING	BILL TO:		(If Differen	t Location)	
		P.O. Box 545 / 1	25 Main Stree	t					
		Waitsburg, WA	99361						
CONTACT:		Ken Cole							
Phone/Fax	:	(509) 520-6519	(509) 337-62:	31	···				
Email:		USE GROUP EMAIL		***************************************	<u> </u>				
Now Ad	cepting:	VISA – MASTER	CARD	ļ	Price Quoted: \$	/ Sam	ple \$		_ / Layers
COMP	LETE ITE	MS 1-4: (Failur	e to complete	any items may	cause a delay in pr	ocessing <b>or</b>	analyzing	g your sa	ımples)
**** <u>Prior</u> ****Addir ****Labo 2. TYP 3. DISF	confirmation cional charge ratory analys E OF ANA POSAL IN	STRUCTIONS	s <u>required</u> ease call marketin delay if credit term [K-PLM] [Air [Dispose of tindicate prefer	ng department for p ns are not met r-PCM] [Lead of samples at E ence, EMC will di	ricing details)  [Point Count]  MC] / [Return sam	[Fungi: AOC	, W-C, Bı	ulk, Swal	b, Tape]
	•	7. <u></u>			mber: A2024 1003				
EMC SAMPI #	E	CLIENT SAMPLE#	DATE & TIME SAMPLED 10/17/2024		ON/MATERIAL TYPE	Samples Accepted Yes / No	AIR SAMP	LE INFO / COM	VIMENTS FLOW RATE
16	501.1			Gypsum Wallb	pard w/Heavy	Y N			
17	501.2			Orange Peel T	exture w/Joint Cor	np. Y N			
14	501.3			Ĭ		Y N		1	
10						Y N			
75						YN	<u> </u>		
31	502.1			4" Grav Cove	base w/Mastic	YN		-	
32	502.2			1		Y N		<u> </u>	
an	502.3			1	<del> </del>	YN			
21	503.1	·		FRP w/Mastic		YN		ļ	
32	503.1			170 00000		YN			
200						Y N			
	503.3 600.1			2x4 Suspende	d Coiling Tile	YN	-	-	
30	600.1			ZX4 Susperiue	ta Centrig Tile				<u></u>
200		**************************************		<u> </u>	<u></u>	YN	<u> </u>		
34	000.3					YN			
				4		YN			
	.INSTRUC				····	2 4 / 2	+ A		
		(Print) Richard DeL		10/18/	(Signature)	uncool be	Som		
Relinqui	shed by:	Cherce Color	<u>n</u> D	ate/Time: <u>1400h</u>	rs Received by	Doneen C	elag-	_ Date/Ti	ひいてばな
Relinqui	shed by:	Dreen Celay	D	ate/Time: <u>\</u> O	Received by:	: W	**	_ Date/Ti	ime: 10 21 2
Relinqui	shed by:		Da	ate/Time	Received by:	- 1		Da	t@GTinZe1_202

\*\* In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be

in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

Page	3	of	3	
------	---	----	---	--

### **CHAIN OF CUSTODY**

EMC Labs, Inc. 9830 S. 51st St., Ste B-109 Phoenix, AZ 85044 (800) 362-3373 Fax (480) 893-1726

LAB#:	321	072

TAT:

Rec'd:

COMPANY NA	AME:	BLUE MOUNT	AIN ENV. & CO	NSULTING	BILL TO:		(	lf Differe	nt Location)	
		P.O. Box 545 /	125 Main Stree	t						
		Waitsburg, WA	99361							
CONTACT:		Ken Cole								<del></del>
Phone/Fax:		(509) 520-6519	/ (509) 337-62	31	·					
Email:		USE GROUP EMA	<u> L</u>		·					
Now Acce	epting:	VISA – MASTE	RCARD	P	rice Quoted: \$		/ Samp	le \$_		/ Layers
COMPLE	ETE ITE	MS 1-4: (Failu	re to complete	any items may	cause a delay in pi	rocessi	ng <b>or a</b>	nalyzir	ng your sa	imples)
**** <u>Prior</u> co ****Addition ****Laborat <b>2. TYPE</b>	nfirmation nal charge ory analys OF ANA	STRUCTIONS:	is <u>required</u> lease call marketir delay if credit tern ulk-PLM] [Air [Dispose	ng department for pr ns are not met '-PCM] [Lead] of samples at EN		[Fungi	: AOC,	my ex	Bulk, Swa	b, Tape]
4. Proje	ect Name	e: Pemoltion Asbe								
P.O.	Number			Project Num	ber: A2024 1003					
EMC SAMPLE #		CLIENT SAMPLE#	DATE & TIME SAMPLED 10/17/2024		N/MATERIAL TYPE	Acce	ples pted / No	AIR SAM	PLE INFO / COI	MMENTS FLOW RATE
30	601.1			2X2 Suspended	Ceiling Tiles	0	N			
31	601.2			<b>\</b>			N			
337	601.3			V	******	Y	N			
253	900.1			Stainless Stee	Sink White	1	N			
ðч	900.2	· · · · · · · · · · · · · · · · · · ·		Undercoat		1	N			
85	900.3			V		1 7	N			
		<del></del>				<del>                                     </del>	N			
		··· ,·, ·				† '	N	***	1	
		·		7 1 11111111111111111111111111111111111	- Vt. Mr.	T Y	N		1	
						<del> </del>	N			
					<del></del>	+	N N		<del> </del>	
						+	N			
						+			<u> </u>	
·		· · · · · · · · · · · · · · · · · · ·				<del>- </del>	N		1	
<u> </u>						<del></del>	N			
<u> </u>				·····		Y	N			
SPECIAL II Sample Co Relinquish	ollector:	( <sub>Print)</sub> Richard Del		10/18/2 ate/Time: 1400hr		uchea	el Il	tom.	L-AData/T	:inla1
		breen Celay		ate/Time: 140011		N . IN #			Date/T	227 24
Relinquish	ed by:		Da	ate/Time	Received by	:/			Da	te/Time:
* In the ev	ent of an	y dispute between	the above partie	es for these service	es or otherwise, par	ties agr	ee that j	urisdict		,

in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

### APPENDIX B ASBESTOS SAMPLE PHOTOS



Photo 1: Sample 400 Lab Data: Non-Detect



Photo 2: Sample 401 Lab Data: Non-Detect






Photo 5: Sample 502 Lab Data: Non-Detect



Photo 6: Sample 503 Lab Data: Non-Detect



Photo 7: Sample 600 Lab Data: Non-Detect



Photo 8: Sample 601 Lab Data: Non-Detect



Photo 9: Sample 900 Lab Data: Non-Detect

### APPENDIX C SAMPLE DRAWING

MAIN FLOOR PLAN

### APPENDIX D PAINT CHIP SAMPLE LAB DATA



9830 South 51st Street, Suite B-109 / PHOENIX, ARIZONA 85044 / 480-940-5294 or 800-362-3373 / FAX 480-893-1726 emclab@emclabs.com

### **LEAD (Pb) IN PAINT CHIP SAMPLES**

EMC SOP METHOD #L01/1 EPA SW-846 METHOD 7420

EMC LAB	# <b>:</b>	L107226		:	10/21/2024	
CLIENT:		Blue Mountain E	env. & Consulting REPORT DATE:			10/22/2024
			DATE OF ANALYSI		SIS:	10/22/2024
CLIENT A	DDRESS:	P.O. Box 545/12 Waitsburg, WA		P.O. NO.:		
PROJECT	NAME:	Demolition Lead 1st Ave., Toppen	in Construction Survey-220 W. ish, WA	PROJECT NO.: A2024 1003		024 1003
EMC # L107226-	SAMPLE DATE /24	CLIENT SAMPLE #	DESCRIPTION		REPORTING LIMIT IN PPM	Pb IN PPM
1	10/17	Pb-1	Yellow-GWB-Wall		100	BRL
2	10/17	Pb-2	Yellow-GWB-Wall		100	BRL
3	10/17	Pb-3	Brown-GWB-Wall		100	BRL
4	10/17	Pb-4	Brown-GWB-Wall		100	BRL
5	10/17	Pb-5	White-Wood-Door Casing		100	BRL
6	10/17	Pb-6	White-Concrete-Wall		101	5350

<sup>=</sup> Dilution Factor Changed

Ins. = Insufficient Sample for Analysis \* = Excessive Substrate May Bias Sample Results # = Very Small Amount Of Sample Submitted, May Affect Result

BRL = Below Reportable Limits

This report applies to the standards or procedures identified and to the samples tested only. The test results are not necessarily indicative or representative of the qualities of the lot from which the sample was taken or of apparently identical or similar products, nor do they represent an ongoing quality assurance program unless so noted. Unless otherwise noted, all quality control analyses for the samples noted above were within acceptable limits.

Where it is noted that a sample with excessive substrate was submitted for laboratory analysis, such analysis may be biased. The lead content of such sample may, in actuality, be greater than reported. EMC makes no warranty, express or implied, as to the accuracy of the analysis of samples noted to have been submitted with excessive substrate. Resampling is recommended in such situations to verify original laboratory results. EMC Labs, Inc. (ID 101586) is accredited by the AlHA Laboratory Accreditation Programs, LLC (AlHA-LAP, LLC) in the Environmental Lead accreditation program(s) for Paint, Settled Dust by Wipe, Soil and Airborne Dust Fields of Testing as documented by the Scope of Accreditation Certificate and associated Scope. AlHA-LAP, LLC accreditation complies with the ISO/IEC Standard 17025:2017 requirements. The customer provides the Project number, name, address, sampling date, identification, and description. EMC Labs, Inc. is an EPA Recognized Testing Lab.

These reports are for the exclusive use of the addressed client and are rendered upon the condition that they will not be reproduced wholly or in part for advertising or other purposes over our signature or in connection with our name without special written permission. Samples not destroyed in testing are retained a maximum of sixty (60) days.

ANALYST: Jason Thompson

**QA COORDINATOR:** 

Kurt Kettler

Page  $\underline{1}$  of  $\underline{1}$ 

### **CHAIN OF CUSTODY**

EMC Labs, Inc. 9830 S. 51st St., Ste B-109 Phoenix, AZ 85044 (800) 362-3373 Fax (480) 893-1726 LAB#: L107226 TAT: 3 Day Rec'd: 10/21/2024

COMPANY NA	AME:	BLUE MOUNTA	IN ENV. & CO	DNSULTING		BILL TO:		(If	Different	t Location	ı)	
	_	P.O. Box 545 / 1	25 Main Stree	et								
		Waitsburg, WA	99361		<u>:</u>							
CONTACT:		Ken Cole										
Phone/Fax:	_	(509) 520-6519 /	(509) 337-62	31		****						
Email:	_	USE GROUP EMAIL									·	
Now Acce	epting:	VISA – MASTER	CARD		Price Que	oted: \$		/ Sample	e \$		/ Layer:	S
COMPLE	ETE ITEN	IS 1-4: (Failur	e to complete	any items ma	y cause a	delay in prod	cessi	ing <b>or an</b>	alyzing	your:	samples)	
		TIME: [4hr rus		sh} [1-Day]	[2-Day]			Day] [6			.•	
**** <u>Prior</u> co	nfirmation o	f turnaround time is	required			ث				, 1		
		or rush analysis (ple may be subject <u>to c</u>			· ·	iils)						
	OF ANAL			r-PCM] [Lead	_ <b>የ</b> የ(ካ dl (Poir	nt Countl   IE	iina	i. AOC V	V-C Bi	ilk Sia	ah Tanai	
		TRUCTIONS:		of samples at l							au, rapej	
			indicate prefer	ence, EMC will o	dispose of	samples <u>60 da</u>	ys fr	om analy	sis.)			_
4. Proje	ct Name:	Demoltion Lead	in Constructio	n Sürvey-220 V	V. 1st Ave	, Toppenish,	WA					
-	•											
i	ivallibel		1									
EMC SAMPLE	s	CLIENT AMPLE#	DATE & TIME SAMPLED	LOCAT	FION/MATER TYPE	RIAL			AIR SAMPI ON	LE INFO / C OFF	OMMENTS FLOW	
#			<b>SAMPLED</b> 10/17/2024					/ No			RATE	ĺ
	Pb-1			Yellow-GW	B-Wall		_( <u>v</u>	) N		ļ		
2	Pb-2			Yellow-GW	B-Wall			N				
3	Pb-3			Brown-GWE	3-Wall			N				
4	Pb-4			Brown-GWB	-Wall		¥	N	•			
5	Pb-5			White-Wood	d-Door C	asing	1	N				
la:	Pb-6			White-Conc			(Y	) N				
					, , , , , , , , , , , , , , , , , , ,	•	Y	N N				
			*****	······································			Y	N				
							Y	N			1	
		·					Y	N				
								N				
								N I		-	+	
				<u> </u>	•	-						
					<u> </u>			N				
								N	···		-	
	<u> </u>				<del></del>		Y	N				
	NSTRUCT					1.	- la -		- 1000	10 1	<del></del>	
Sample Co	ollector: (P	rint) Richard DeL	orme	10/1	(Si	gnature)_ <i>f_l</i>	AU,	HM LL	ehbY.			
Relinquish	ied by:_ <i>&amp;</i>	Ward lee	58ML 0	10/10 ate/Time: <u>1400</u>	8/2024 \ )hrsR	eceived by:_	D	В		Date/	Time: <u>/0/2</u>	1121
Relinquish	*	DB		ate/Time: 10/1	13044	eceived by:		Jak .		_ Date/		202
Relinquish	ed by:		D	ate/Time	R	eceived by:_		1			Date/Time:_	
		dispute between t d prevailing party					s agı	ee that ju	ırisdictio	on and	venue will b	e

### APPENDIX E PAINT CHIP SAMPLE PHOTOS






Photo 3: Sample Pb-3 Lab Data: BRL



Photo 4: Sample Pb-4 Lab Data: BRL



Photo 5: Sample Pb-5 Lab Data: BRL



Photo 6: Sample Pb-6 Lab Data: 5350ppm

### APPENDIX F LAB CERTIFICATIONS

### National Institute of Standards and Technology **United States Department of Commerce**



# Certificate of Accreditation to ISO/IEC 17025:2017

**NVLAP LAB CODE: 101926-0** 

EMC Labs, Inc.

Phoenix, AZ

is accredited by the National Voluntary Laboratory Accreditation Program for specific services, listed on the Scope of Accreditation, for:

### **Asbestos Fiber Analysis**

This accreditation demonstrates technical competence for a defined scope and the operation of a laboratory quality This laboratory is accredited in accordance with the recognized International Standard ISO/IEC 17025:2017. management system (refer to joint ISO-ILAC-IAF Communique dated January 2009).

2023-07-01 through 2024-06-30

Effective Dates



For the National Voluntary Laboratory Accreditation Program



### AIHA Laboratory Accreditation Programs, LLC

acknowledges that

EMC Labs, Inc.

9830 S. 51st Street, Suite B-109, Phoenix, AZ 85044-5671

Laboratory ID: LAP-101586

along with all premises from which key activities are performed, as listed above, has fulfilled the requirements of the AIHA Laboratory Accreditation Programs, LLC (AIHA LAP) accreditation to the ISO/IEC 17025.2017 international standard, General Requirements for the Competence of Testing and Calibration Laboratories in the following:

### LABORATORY ACCREDITATION PROGRAMS

$\square$	INDUSTRIAL HYGIENE	Accreditation Expires: February 01, 2026
□	ENVIRONMENTAL LEAD	Accreditation Expires: February 01, 2026
N	ENVIRONMENTAL MICROBIOLOGY	Accreditation Expires: February 01, 2026
П	FOOD	Accreditation Expires:
П	UNIQUE SCOPES	Accreditation Expires:
П	BE FIELD/MOBILE	Accreditation Expires:

Specific Field(s) of Testing/Method(s) within each Accreditation Program for which the above named laboratory maintains accreditation is outlined on the attached Scope of Accreditation. Continued accreditation is contingent upon successful on-going compliance with ISO/IEC 17025:2017 and AIHA LAP requirements. This certificate is not valid without the attached Scope of Accreditation. Please review the AIHA LAP website (www.aihaaccreditedlabs.org) for the most current Scope.

Cheng G. Charten

Criety O Motorial Managing Director, AIHA Laboratory Accreditation Programs, LLC Date Issued: 02/01/2024

Revision21: 10/24/2023

### APPENDIX G PROFESSIONAL CERTIFICATIONS

### STATE OF WASHINGTON

### Department of Commerce

Lead-Based Paint Activities Program

### Richard Joseph DeLorme

Has fulfilled the certification requirements of

WAC 365-230 and has been certified to conduct lead based paint activities as a **Risk Assessor**.

**Issuance Date** Certification #

Expiration Date

03/29/2027

03/25/2024

# Certificate of Completion

This is to certify that on March 8, 2024

### Richard DeLorme

Did attend and satisfactorily complete the training requirements in accordance with TSCA Title II (Section 206) and 40 CFR 763 & Missouri State RSMo 643.230

For designation as an

# AHERA Building Inspector (Refresher)

Certificate No. ASI-BIR-24-059

Refresher Due: March 8, 2025

Presented by:



Michael J. Moore

Training Director/Instructor