

## ATTACHMENT A - EXISTING CONDITIONS

Figure 1

*Existing 24" corrugated metal pipe culvert at 15601 Donner Pass Road. The culvert, depicted by the green line, has an inlet basin on the north side of the road and an outfall into Donner Lake.*



Figure 2

*This image was taken during a camera inspection of the culvert in October 2024. The obstruction depicted is located somewhere underneath the residential structure.*

