



Picture #1  
Erosion under the  
monkey bars from  
runoff rainwater



Picture #2  
Leaf roof metal clamps  
rusted w/oversized  
screws



Picture #3  
Overhead Gilder  
erosion has  
caused exposed  
cement



Picture #4  
Ring Trek  
peeling and  
rusted  
hardware



Picture #5  
Wave slide split  
in backboard