



Alley entrance from Ruth Street. Iron placed by Professional Land Surveyor on right side of photo



Broken concrete north of Alley entrance



Suspected alley
encroachment, rutting

