

604 W Main Street

Rear Door

Current Condition:

- Rear storm door is rotting and needs to be replaced.
- Door is no longer used:
 - No outside stairs
 - Inside, permanent closet built in front of opening



Existing door
is at least 3
years old



Proposed Changed

- Replace storm door with an insulated fiberglass door, no windows
- No hardware
- Paint either off white or green
- Leave transom as is



Similar style to what we think was original kitchen door, from a 2010 picture of a door in the storage room



Similar style to original side door by ramp

Door Color Samples

