

WO#	W1019
Status	Completed
Title	Basic Work Order
Description	Remove Abandoned fire hydrant
Work Performed	Crew excavated and removed out of service fire hydrant to rebuild and put back into service elsewhere. New hydrant was installed in its place in 2008.
Type	Basic Work Order
Owner	Robinsonsafewater@gmail.com[26242]
Assignee	Derrickbostron@icloud.com Sebournka@gmail.com Wardkramer44@yahoo.com
Date Created	2026-03-18 15:10:40
Date Started	2026-03-18 15:13:45
Date Completed	2026-03-18 15:13:45
Date Planned	2026-03-18
Asset	
Recurring	
Attachments	 1000004561.jpg  1000004564.jpg

History

2026-03-18 15:13:45 Robinsonsafewater@gmail.com
Initial Status is Completed

2026-03-18 15:18:24 Robinsonsafewater@gmail.com
Assignees Changed from
Derrickbostron@icloud.com[34943],Wardkramer44@yahoo.com[26250],willardmo123@gmail.com[28697] to
Derrickbostron@icloud.com[34943],Sebournka@gmail.com[26251],Wardkramer44@yahoo.com[26250]

WO#	W1020
Status	Completed
Title	Water Department Work order
Description	Crew excavated on 6" line at water tower to install a 4" tap for a flush point to drain tower more productively in the future for repairs on tower.
Work Performed	Excavated and benched sides for crew to tap in the future.
Type	Basic Work Order
Owner	Robinsonsafewater@gmail.com[26242]
Assignee	Derrickbostron@icloud.com Sebournka@gmail.com Wardkramer44@yahoo.com
Date Created	2026-03-18 15:14:27
Date Started	2026-03-18 15:17:29
Date Completed	2026-03-18 15:17:31
Date Planned	2026-03-18
Asset	
Recurring	
Attachments	 1000004557.jpg  1000004558.jpg  1000004560.jpg
History	
2026-03-18 15:17:37 Robinsonsafewater@gmail.com Initial Status is Completed	

WO#	W1018
Status	Completed
Title	Basic Work Order
Description	Water leak repair on meter setter
Work Performed	Dug up and repaired meter setter and leak on other resident service line by setter after exposing.
Type	Basic Work Order
Owner	Robinsonsafewater@gmail.com[26242]
Assignee	Derrickbostron@icloud.com Sebournka@gmail.com Wardkramer44@yahoo.com
Date Created	2026-03-16 10:36:24
Date Started	2026-03-13
Date Completed	2026-03-13
Date Planned	2026-03-11
Asset	591319:1689
Recurring	
Attachments	 20260313_105909.jpg
History 2026-03-16 10:35:32 Robinsonsafewater@gmail.com Initial Status is Completed	

Hydrant Number	
Year/Make/Model	1972 Mueller
Address	2571 N Honeysuckle Way OOS
Dates Tested	07-01-2005 10-17-2009 08-08-2016 ??-??-2024
Latitude	37.24537
Longitude	-93.41300
GPM Flow	000
Pitot PSI	0
Static PSI	0
Residual PSI	0
Cap Color	Black
Isolation Valve operable	
Isolation Valve Location	None
Repairs Required	No
Parts Used	6-6" Megalug wedges, 6 gaskets and bolts. 1 6" ductile T and 1 6" valve.
Hydrant Draining properly	No

History

Attachments	 20260310_124435.jpg  20260310_124432.jpg  20260310_121506.jpg
-------------	---

Notes	Hydrant removed on 2-14-2026
Ftr ID	235

Description	Service line leak
Location	102 Emily LN
Line Size	3/4
Line Material	Black poly
Cause Of Leak	Fitting leak at Y IN
Repaired By	Kevin, Dave , Derek, Shane
Repaired Date	3/09/2026
Coordinates	37.2928986 -93.4363704
Created By	Greedygrapple@gmail.com
Created Date	2026-03-09 14:49:05
History	
2026-03-09 14:55:35 Greedygrapple@gmail.com Emily we used a 2' piece of cts and 2 thimbles	
Attachments	 20260309_123454.jpg  20260309_123456.jpg
Ftr ID	44

Description	Service line repair
Location	200 Lynn Dr
Line Size	3/4
Line Material	Copper
Cause Of Leak	Setter valve failed
Repaired By	Kevin, Dave, Derek shane
Repaired Date	3/09/2026
Coordinates	37.3066654 -93.4358106
Created By	Greedygrapple@gmail.com
Created Date	2026-03-09 14:45:48
History	
2026-03-09 14:54:51 Greedygrapple@gmail.com Lynne we used a meter valve, meter pit ring and lid.	
Attachments	 20260309_094359.jpg
	 20260309_123441.jpg
	 20260309_094402.jpg
Ftr ID	43

Description	Fire hydrant removal for relocation
Location	Slope side of main street feed
Line Size	8
Line Material	AC Transite pipe
Cause Of Leak	N/A
Repaired By	Kevin, Dave, Derbear and Shane
Repaired Date	3/03/26
Coordinates	37.2129606 -93.4583451
Created By	Robinsonsafewater@gmail.com
Created Date	2026-03-05 13:22:14

History

2026-03-05 14:17:05 Robinsonsafewater@gmail.com
 Fire hydrant removed for relocation for access for fire emergency services.

Attachments	 1000004504.jpg  1000004502.jpg  1000004497.jpg  1000004496.jpg
-------------	---

Hydrant Number	
Year/Make/Model	
Address	2617 N Honeysuckle Way OOS
Dates Tested	07-01-2005 10-17-2009 08-12-2016 ??-??-2024
Latitude	37.24630
Longitude	-93.41280
GPM Flow	000
Pitot PSI	0
Static PSI	0
Residual PSI	0
Cap Color	Black
Isolation Valve operable	
Isolation Valve Location	Yes
Repairs Required	No
Parts Used	6" Valve, 6" MJ T 2 6" Mega Lug Wedges, 6 " Anchor coupler 12" in Length. 2 6" hymax, 85" of 6" C900 pipe amd Tbolts
Hydrant Draining properly	Yes

History

2026-02-26 09:55:10 Robinsonsafewater@gmail.com

Service line repaired approximately 3' from hydrant T going east across Honeysuckle

Attachments



1000004434.jpg



1000004423.jpg



1000004422.jpg



1000004432.jpg

Notes

Hydrant And valve replaced and working properly on 2-17-2026 and completed

Ftr ID

266

Description	Water Leak
Location	State Hwy AB/Farm rd 88
Line Size	6"
Line Material	PVC
Cause Of Leak	6" x 2" reducer failed
Repaired By	Kevin, Kramer and Shane
Repaired Date	02/12/2026
Coordinates	37.2851809 -93.4337211
Created By	Djseemann@gmail.com
Created Date	2026-02-14 09:39:37

History

2026-02-14 09:47:04 Djseemann@gmail.com
2" Romac, 2' of 2" PVC

2026-02-14 09:47:28 Djseemann@gmail.com
2" PVC compression

2026-02-14 09:48:33 Djseemann@gmail.com
6x2 plug cap Megalug wedge and 6" gasket and 6 T bolts

Attachments



20260212_112757.jpg



20260212_112720.jpg



20260212_112722.jpg



1000004408.jpg



1000004404.jpg

Ftr ID

41

Project Name	6" Waterline Lowering and Valve installation
Segment ID	
Status	Active
Pipe Material	PVC
Diameter (in)	6.00
Pressure Class (psi)	165
Installation Year	2026
Length (ft)	30.00
Work Type	Relocation
Old Main Material	PVC
Old Main Diameter (in)	6.00
Service Area	Old Willard Hills
Street Name	Main And Creighton
Contractor	City Of Willard
Engineer	Shane/Kevin/Dave
Bid Date	
Construction Start	2026-01-14
Construction End	2026-01-15
In Service Date	2026-01-15
Funding Source	
As-Built Verified	<input type="checkbox"/>
Notes	
Attachments	 <p>20240322_130305[1].jpg</p>  <p>Snapchat-1653512569.jpg</p>



Snapchat-625196361.jpg



IMG_20260114_113213.jpg



IMG_20260114_113211.jpg

History

2026-01-29 07:36:03 Robinsonsafewater@gmail.com
Existing Waterline was too shallow and exposed in the ditch.

2026-01-29 08:36:32 Robinsonsafewater@gmail.com
Water crew removed 35' of 6" waterline that sat in the storm ditch visibly and installed four 22.5 ductile MJ fittings, 8 Mega Lus, 6 MJ Gaskets, 2 Trans Gaskets 35 feet of C900 and 1 Romac Coupler.

2026-01-29 08:37:15 Robinsonsafewater@gmail.com
Crews Also Installed 1 6" Valve on the South side of drainage ditch

Ftr ID

6

Description	6" Waterline 90 upgrade
Location	805 Hwy AB
Line Size	6"
Line Material	Glued PVC
Cause Of Leak	Glued 90 pushed apart
Repaired By	Kevin, Dave Shane
Repaired Date	1-7-2026
Coordinates	37.2881869 -93.4335472
Created By	Robinsonsafewater@gmail.com
Created Date	2026-01-06 15:11:10

History

2026-01-06 15:14:42 Robinsonsafewater@gmail.com
 Water crew exposed top 90 and bottom 90 for removal on 1/6/2026

Attachments



1000004021.jpg



1000004022.jpg



1000004025.jpg



1000004033.jpg



1000004034.jpg



1000004041.jpg



1000004040.jpg



1000004036.jpg

Ftr ID

10

Project Name	Miller and Mill st project
Segment ID	
Status	Active
Pipe Material	PVC
Diameter (in)	4.00
Pressure Class (psi)	
Installation Year	2026
Length (ft)	4ft
Work Type	Replacement
Old Main Material	PVC
Old Main Diameter (in)	4.00
Service Area	Willard School irrigation
Street Name	Miller/mill st
Contractor	Public works
Engineer	Kevin. Dave
Bid Date	
Construction Start	
Construction End	
In Service Date	
Funding Source	
As-Built Verified	<input type="checkbox"/>
Notes	
Attachments	 20260112_143705.jpg  20260112_143709.jpg  20260112_103435.jpg
History	

Description	3" Waterline Repair
Location	EE Hwy
Line Size	3"
Line Material	PVC
Cause Of Leak	Auger Head from Ozark Coop
Repaired By	Kevin, Dave, Shane, Trevor
Repaired Date	12/18/2025
Coordinates	37.2426757 -93.4651718
Created By	Robinsonsafewater@gmail.com
Created Date	2026-01-05 15:11:58
History	
Attachments	 <p>1000004028.jpg</p>  <p>1632515011000003572.jpg</p>
Ftr ID	8

Description	Water Service repair
Location	6926 W Dogwood
Line Size	1"
Line Material	Black Pex
Cause Of Leak	Split in line under road
Repaired By	Kevin, Dave, Shane
Repaired Date	12/16/2025
Coordinates	37.2486902 -93.4267259
Created By	Robinsonsafewater@gmail.com
Created Date	2026-01-05 14:52:09

History

<p>Attachments</p>	 <p>1000003408.jpg</p>  <p>1000003548.jpg</p>  <p>1000003547.jpg</p>
<p>Ftr ID</p>	<p>7</p>

Description	Water service line
Location	1672 N Farm Rd
Line Size	1" Service Line
Line Material	Black Pex
Cause Of Leak	Outdated pex split under road
Repaired By	Kevin, Dave, Shane
Repaired Date	11/22/2025
Coordinates	37.2312863 -93.4218854
Created By	Robinsonsafewater@gmail.com
Created Date	2026-01-05 14:49:37
History	
Attachments	 1000003170.jpg
	 1000003169.jpg
	 1000003182.jpg
Ftr ID	6

Description	Corp turned off, leak under road Repair band installed on old existing tap
Location	Farm Rd 89
Line Size	8"
Line Material	AC
Cause Of Leak	Out of service tap
Repaired By	Kevin, Dave Shane
Repaired Date	11/19/2025
Coordinates	37.2191557 -93.4589567
Created By	Pubwks@cityofwillard.org
Created Date	2025-02-08 15:12:20
History	
Attachments	 <p>Snapchat-1675549093.jpg</p>  <p>Snapchat-766910393.jpg</p>
Ftr ID	1