



Level 01 Floor Plan 1/8" = 1'-0"






Level 02 1/8" = 1'-0"





Level 01 1/8" = 1'-0"






Level 02 Floor Plan 1/8" = 1'-0"

105 W Jefferson additions or alterations

- 1) Exterior
 - a) N
 - i) 1 new downstairs exterior door facing N
 - ii) Two upstairs windows
 - iii) Alteration to downstairs windows facing N to door
 - iv) "Hidden" security camera (not visible from street)
 - b) W
 - i) Alteration to emergency exit door to window
 - ii) Potential exterior ladder for rooftop access
 - iii) Alteration to current downstairs door to large window (N side facing W)
 - c) S
 - i) New emergency egress, landing and stairs with additional balcony area
 - ii) Slight alteration to downstairs door (left to right swing) exit towards alley vs towards church)
 - iii) Visible security camera (visible from alley)
 - d) E
 - i) Alteration to 1st floor window changed to double doors
 - ii) Gas line going over building removed
 - iii) New to code electrical base meters
 - e) Entire Exterior
 - i) New paint color
 - ii) New signage
 - iii) Visible security cameras (visible from street and alley)

- 2) Interior 1st floor
 - a) Removal of walls (offices turned to open space)
 - b) Removal of drop ceiling
 - c) Original offices that do remain drop ceiling turned to drywall or bead board
 - d) Bathrooms
 - i) Shower added to original private office bath
 - ii) Urinal removed from ADA bath
 - iii) 2nd commode removed from employee bath
 - iv) All trades, electrical, plumbing, mechanical updated to todays code.
 - v) All windows updated to todays code (low E tempered glass)
 - vi) Insulation better than minimum code standards
 - vii) Removal of interior door connecting 1st and 2nd floor
- 3) Interior 2nd floor
 - i) Walls removed for open space
 - ii) Drop ceilings removed in remaining offices
 - iii) Drywall ceilings to replace removed drop ceilings
 - iv) No change to bathrooms
 - v) All trades, electrical, plumbing, mechanical updated to todays code
 - vi) All windows ypdated to todays code
 - vii) Insulation better than minimum code standard
 - viii) Alteration of some office doors from wood to glass



*