INLAND TRUCK PARTS & SERVICE

'An Employee Owned Company'

P.O. Box 3112
RAPID CITY, SD 57709

INVOICE

Invoice # IN-2001163
Cust PO #
SO # SO-2796620
Date 05/29/2026
Writer Andy Gay

Invt:Cust 14:14 **Cust acct#** 010132 **PS#**

Sold to: City Of Deadwood Trolley Dept
102 Sherman Street

Ship to: City of Deadwood Trolley Department
62 Dunlop Avenue
DEADWOOD, SD 57732

Contact
Contact phone
Payment terms Due on the 10th
Primary phone
Ship via None Specified46
Prepay and Add

Vehicle info: **Year/Make/Model** 2021 / OTHER / Villager **Cust Unit #** #4
VIN/Short VIN 1F66F5DN9M0A05699 / M0A05699 **Miles/Hours** 76645 / 0

Repair Order no. RO - RO-0354605 **Operation #** 1

Condition Check power steering

Correction The customer had a concern about power steering issues.
Pulled the trolley into the shop and began pulling the power steering tank apart, only to find the oil was burnt-smelling and had a brown tint.
Drained the fluid, pulled the oil filter, disconnected and removed the power steering pump.
Flushed the system, cleaned and inspected all hoses and mounting surfaces.
Installed the new pump and filter, and filled the system with fresh fluid.
Took the trolley on a road test and returned to the building to inspect for leaks.

Part number	Description	Ord	Del	B/O	List Price	Unit price	Ext. price
760_BT9388	Power Steering Spin-on (12)	1	1	0	73.50	52.84	52.84
125_PART	FORD TRUCK PARTS	1	1	0	0.00	1,624.50	1,624.50
FC4Z3A674B Power Steering Pump							
Core exchange							
NAP_9832	P/S FLUID	3	3	0	34.47	14.93	44.79
Labor							740.00
Shop supplies							48.10

Total merchandise	1,770.23
Total cores	0.00
Total labor	740.00
Tax amount	0.00
Invoice total	$2,510.23

Received by

See warranties on final page