



Tax Invoice

Invoice : 7617080
Invoice Date (Tax Point) : 02-JAN-26
Page No.: 1 of 4

Seller: Terex USA, LLC, 142 Gembler Rd, San Antonio Bexar TX 78219-3112, United States
Accounts Receivable Contact: Tel: 1-877-794-5284 Email: GBS.US.AR@Terex.com

Bill To:
CITY OF CARTERSVILLE
PO BOX 1390
Cartersville GA 30120-1390
UNITED STATES
Attn:

Ship To:
CITY OF CARTERSVILLE
320 S. ERWIN STREET
CARTERSVILLE GA 30120
UNITED STATES

Sold To:
CITY OF CARTERSVILLE
PO BOX 1390
Cartersville GA 30120-1390
UNITED STATES

Customer Purchase Order	Payment Terms	Tracking	Shipping Reference	Payment Due Date	Terex Contact	Customer Account Number
500	30 Days Invoice Date		984573900	01-FEB-26	Oberdorff, Ms. Emily A (Em)	269036
Date Shipped	Ship Via	Incoterms® FCA, Sellers Premises Incoterms® 2010		Order Number	Currency	Ship From
02-JAN-26				1010199240	USD	San Antonio, US

Line	Product	COO	Qty	UoM	Net Price	Extended Amount	Tax Code
1	FS48-LBR-GA Labor Notes: null		48.5	Hour	192.00	9,312.00	GAVERTEX
2	FS48-TRAVEL Travel Notes: null		6	Hour	186.00	1,116.00	GAVERTEX
3	ALT35270055 VALVE, HYDRAULIC, ALTEC CB 3250 PSI Notes: null		2	Each	380.43	760.86	GAVERTEX

These commodities, technology, or software are subject to the United States Export Administration Regulations. If you choose to export them, you, as the exporter, must apply with all applicable law.

Wire Transfer: Account Name : Terex USA, Account Number : 375 185 1851, SWIFT : BOFA US3N
Remit To: TEREX USA, LLC 4686 COLLECTIONS CENTER DRIVE, CHICAGO, IL 60693

Please ensure payment is submitted to the bank account noted on this invoice and will be received by the Payment Due Date. The form of payment chosen will impact the length of time payments take to be received. Your Payment Terms and Credit Arrangements may be impacted if payment is not received by Payment Due Date.





Tax Invoice

Invoice : 7617080
Invoice Date (Tax Point) : 02-JAN-26
Page No.: 2 of 4

Seller: Terex USA, LLC, 142 Gemblar Rd, San Antonio Bexar TX 78219-3112, United States
Accounts Receivable Contact: Tel: 1-877-794-5284 Email: GBS.US.AR@Terex.com

Line	Product	COO	Qty	UoM	Net Price	Extended Amount	Tax Code
4	ALT39050001 OIL SEAL Notes: null		2	Each	20.81	41.62	GAVERTEX
5	ALT970020948 NUT LOCK; 88-14 UNF; HYDRAULIC CYLINDER Notes: null		2	Each	10.85	21.70	GAVERTEX
6	EXP-PTFREIGHT Part Freight Notes: null		1	Each	138.42	138.42	GAVERTEX
7	EXP-SHOP Shop Supplies / Environmental Notes: null		1	Each	225.00	225.00	GAVERTEX
8	EXP-FUEL-SURCHARGE-FS EXP-FUEL-SURCHARGE-FIELD SERVICE Notes: null		1	Each	33.66	33.66	GAVERTEX

These commodities, technology, or software are subject to the United States Export Administration Regulations. If you choose to export them, you, as the exporter, must apply with all applicable law.

Wire Transfer: Account Name : Terex USA, Account Number : 375 185 1851, SWIFT : BOFA US3N
Remit To: TEREX USA, LLC 4686 COLLECTIONS CENTER DRIVE, CHICAGO, IL 60693

Please ensure payment is submitted to the bank account noted on this invoice and will be received by the Payment Due Date. The form of payment chosen will impact the length of time payments take to be received. Your Payment Terms and Credit Arrangements may be impacted if payment is not received by Payment Due Date.





Tax Invoice

Invoice : 7617080
Invoice Date (Tax Point) : 02-JAN-26
Page No.: 3 of 4

Seller: Terex USA, LLC, 142 Gembler Rd, San Antonio Bexar TX 78219-3112, United States
Accounts Receivable Contact: Tel: 1-877-794-5284 Email: GBS.US.AR@Terex.com

Notes:

WorkOrder Number : WO-0000219246
Tech# : FS48-930

---MACHINE DETAILS---

MAKE : ALTEC
MODEL: A72T
UNIT : 500
S/N : 0400CT0262
PO# 500

Complaint: Basket leveling not operating properly basket dumping

Cause: Basket leveling cylinder

Correction: Operated unit to diagnosis issue with basket dumping, diagnose as leveling cylinder packing bad. Ordered parts as needed for repairs. Returned to unit to repair. Lowered boom tip to ground to access leveling cylinders. Removed covers from boom tip to access boom tip leveling cylinders. Thinking could access and remove leveling cylinders without removing boom tip from upper boom. After examination of boom tip discovered only way to access cylinders would remove boom tip. Begin process to remove boom tip from unit. Removed jib winch assembly from boom tip. Slide basket and mounting bracket off basket pivot pin. Disconnect hose tension rod from boom tip, disconnect hoses as needed for boom tip removal. Removed boom tip to upper boom mounting bolts. Slide boom tip out from upper boom and place on worktable. Removed leveling cylinders from boom tip. Disassemble leveling cylinders, furnished and installed new seal kits for both leveling cylinders, furnished and installed new piston nuts and torque to specs. Reassemble leveling cylinders, furnished and installed new counterbalance valves for leveling cylinders. Bench test leveling cylinders before installing in boom tip, to check for leaks and to purge air from leveling cylinders. Reinstall leveling cylinders into boom tip weldment. Reattach leveling chains to leveling cylinders. Reinstall boom tip weldment into upper boom loosely to check operation of leveling system before permanently installing boom tip weldment. Reconnect leveling cylinder hoses. Operated leveling system to be sure leveling system performing properly. After verifying leveling working properly proceed to permanently installing boom tip into upper boom, using new mounting bolts. Cleaned basket shaft where basket weldment mounts to basket shaft. Reinstall basket Assy onto basket pivot shaft. Reinstall jib winch assembly onto basket pivot shaft. Route and attach various hoses at boom tip. Reinstall hose tension rod to boom tip and apply tension. Checked unit operation and for leaks. Reinstalled covers. Stow unit for road travel.

Subtotal	11,649.26
Total Charges	0.00
Total Taxes	0.00
Total Amount	11,649.26
Payment Received	0.00
Amount Due(USD)	11,649.26

These commodities, technology, or software are subject to the United States Export Administration Regulations. If you choose to export them, you, as the exporter, must apply with all applicable law.

Wire Transfer: Account Name : Terex USA, Account Number : 375 185 1851, SWIFT : BOFA US3N
Remit To: TEREX USA, LLC 4686 COLLECTIONS CENTER DRIVE, CHICAGO, IL 60693

Please ensure payment is submitted to the bank account noted on this invoice and will be received by the Payment Due Date. The form of payment chosen will impact the length of time payments take to be received. Your Payment Terms and Credit Arrangements may be impacted if payment is not received by Payment Due Date.





Tax Invoice

Invoice : 7617080
Invoice Date (Tax Point) : 02-JAN-26
Page No.: 4 of 4

Seller: Terex USA, LLC, 142 Gembler Rd, San Antonio Bexar TX 78219-3112, United States
Accounts Receivable Contact: Tel: 1-877-794-5284 Email: GBS.US.AR@Terex.com

Tax Code	Tax Rate	Tax Amount		
GAVERTEX	0.00%	0.00		

These commodities, technology, or software are subject to the United States Export Administration Regulations. If you choose to export them, you, as the exporter, must apply with all applicable law.

Wire Transfer: Account Name : Terex USA, Account Number : 375 185 1851, SWIFT : BOFA US3N
Remit To: TEREX USA, LLC 4686 COLLECTIONS CENTER DRIVE, CHICAGO, IL 60693

Please ensure payment is submitted to the bank account noted on this invoice and will be received by the Payment Due Date. The form of payment chosen will impact the length of time payments take to be received. Your Payment Terms and Credit Arrangements may be impacted if payment is not received by Payment Due Date.

