



No. 002138
305 Best Ave.
Hinckley, MN 55037
ahrsales24hrservice@scicable.com

24 hour Service
218-380-1386

Date _____

5-21-25

Terms

per Travis Kohlen

Name

Firehouse Bar

Phone

320-279-3966

Address

Hinchley, NW. 55037 - po. Box 366 - City Hall

Customer Complaint

Beide Walhirs cooler warm

1.5 hrs 5-21- Arrived found liquid line from outside condenser
iced up - Plugged - restricted refrigerant liquid line
filter dryer - got the refrigerant to flow again
but - new dryer needs to be installed - parts ordered -
- ~~ⓧ~~ - Recommend - replacing the equipment - will get new prices ~~ⓧ~~

1.5 hrs. 5-27 - Pumped system down - resealed copper vessel in new copper to fit new refrigerant filter dryer replaced and flared new dryer if part needs replacing - Coolant works normal.

→ ★ New Equipment Costs and Refrigerant costs went up; To install new EVAP. and outside condenser with labor job done with "out" Copeland set replacement \$12,500. with new Copeland set A 14,500.

OTHER CHARGES	
truck charges & supplies	\$ 25.00
torch-torch material	\$ 40.00
vacuum pump refrigerant equip	\$ 15.00
Total Other	\$ 80.00

LABOR

Service taken	3 hrs @ 25. ⁰⁰ per hr.
---------------	-----------------------------------

Total Labor	375.00
-------------	--------

Total Materials	175.00
-----------------	--------

Total Other	480.00
-------------	--------

Surcharge	# 10.00
-----------	---------

TOTAL 619.00Date Completed 11/1/84

5-27-25	Total Materials	175 ⁰⁰
---------	-----------------	-------------------

Total Materials

Work ordered by _____

1 Boris Hoheler

Signature

ered by 1 Mr. W. H. Wheeler
on file mailed bill to City

I hereby acknowledge the satisfactory completion of the above described work.

Thank You

BALANCE DUE IN 30 DAYS
ANY UNPAID BALANCE WILL RECEIVE
A FINANCE CHARGE OF
1.5% PER MONTH, 18% PER YEAR.

609,49775.04090

Eric