

INVOICE

Stringfellow Mobile Diesel
702 N Madison Ave
Anthony, KS 67003

stringfellowmobilediesel@gmail.com
+1 (316) 200-6615

RECEIVED

JUL 01 2026



BY: _____

Bill to
Anthony City

#7 Digger Repair

Invoice details

Invoice no.: 0549
Terms: Net 30
Invoice date: 07/01/2026
Due date: 07/31/2026

Unit: #7
VIN: 1HTWEAAN46J337949
Miles: 30858

03 32 3040

\$8902.15

192794

#	Product or service	Description	Qty	Rate	Amount
1.	Labor	 Drove to location and connected scan tool monitored ICP. Found that pressure would drop randomly. Under partial load ICP would stay low and not match desired. A new sensor and IPR valve was installed but they were not OEM parts. Replaced sensor with OEM sensor. During removal, pressure tested rail and found that there was a slight leak. Resealed injectors and HP oil rail. Started truck after replacement of the sensor and truck would not start. Crank sensor code appeared. Found that crank sensor end was damaged. R/R crank sensor. Started truck still had an issue with ICP. Inspected IPR valve and found that it was bent. R/R IPR valve. Problem still exists. Monitored pressure and found that IPR valve duty cycle kept going up when pressure wouldn't build. This could be cause by HPOP failure. Pressure would eventually rise and issue would go away. Dead head HPOP and pressure was low. HPOP will need replaced. R/R pump. Other repairs performed, welded exhaust due to broken pipe, Fan hub was leaking, and engine belt was coming apart. R/R fan hub. R/R belt. Reinstalled interior after repair and test drove truck. No more issues. Truck ran great.	16.5	\$130.00	\$2,145.00
2.	Miles	Miles driven to repair location and to pick up parts	180	\$1.50	\$270.00
3.	Misc Shop Supplies	Covers standard use of consumable products such as brake clean, rags, loctite	1	\$5.00	\$5.00

4.	FLT061050000	Fan Hub	1	\$395.62	\$395.62
5.	1842461C1	8 Ribbed Belt	1	\$48.78	\$48.78
6.	5011334R91	High Pressure Pump	1	\$3,558.92	\$3,558.92
7.	1812348C1	Sleeve, Fuel Line	4	\$13.24	\$52.96
8.	1835985C92	Crank Sensor	1	\$285.00	\$285.00
9.	1845536C92	Sensor ICP	1	\$315.00	\$315.00
10.	1842624C92	Injector Seal Kit	6	\$43.90	\$263.40
11.	1842626C96	HP Oil Rail Kit	1	\$202.00	\$202.00
12.	2522072C91	Injector Puck Assembly	6	\$96.90	\$581.40
13.	Diagnostic Hookup	Scan and diagnose fault codes. Clear fault codes after repair.	1	\$40.00	\$40.00
14.	M8CFLN10P	M8-1.25 Grade 10.9 Flange Nut	1	\$0.42	\$0.42
15.	M8X100BLT	M8x100MM Bolt	1	\$3.39	\$3.39
16.	25SNT8Y	1/4 Grade 8 Flat Washer	1	\$0.22	\$0.22

Subtotal \$8,167.11

Sales tax \$735.04

Total \$8,902.15

Ways to pay



Please make checks payable to Stringfellow Mobile Diesel.

Note to customer

Thank you for your business!

View and pay