

Inspection Summary

6115 D Tractor

Serial #L06715D539055 Warranty End Date: 01/01/01
 Stock # PowerGard Type: None
 Inspection Date: 12/19/23 PowerGard End Date: 01/01/01
 Repair Order#: Engine Hours: 5757

Needs Replaced: **19**

Recommended: **0**

Approved: 19

Declined: 0

Total Parts: **\$4,220.00**

Total Labor: **\$5,074.51**

Total Parts & Labor: \$9,294.51

Inspection Cost: **\$0.00**

Total Warranty Estimate: **\$0.00**

*Subject to warranty approval process

Grand Total: \$9,294.51

: CITY OF ANTHONY

PO BOX 504
 ANTHONY, KS 67003
 h:
 m:

Technician
 Tateyn Rieger

Acct #: 127272

*Note: tax, service accessories, welding, paint and repairs with no estimated cost are not included in quote.

Legend = Parts = Labor = Total = Warranty

Approved

Needs Replaced			
\$4,220.00	\$5,074.51	\$9,294.51	\$0.00
Recommended			
\$0.00	\$0.00	\$0.00	\$0.00
Totals			
\$4,220.00	\$5,074.51	\$9,294.51	\$0.00

Declined

Needs Replaced			
\$0.00	\$0.00	\$0.00	\$0.00
Recommended			
\$0.00	\$0.00	\$0.00	\$0.00
Totals			
\$0.00	\$0.00	\$0.00	\$0.00

6 0 CAB		\$725.00	\$1,665.02	\$2,390.02	\$0.00
Steering Column	Declined <input type="checkbox"/> Approved <input checked="" type="checkbox"/>	Parts Estimate	Labor Estimate	Total Estimate	Warranty
updated Steering wheel - Remove & Install Technician Comments:Steering column does not stay up as it should.	<input type="checkbox"/> <input checked="" type="checkbox"/>	\$120.00 Qty: 2	\$179.63 Job Code: 6115D/4309/10	\$299.63	<input type="checkbox"/>
Lights - All Outside Lights & Warning Lights	Declined <input type="checkbox"/> Approved <input checked="" type="checkbox"/>	Parts Estimate	Labor Estimate	Total Estimate	Warranty
updated Halogen bulb (each) - Remove & Install Technician Comments:LH tail light/turn signal does not work and is missing cover. Front LH warning light on roof is missing cover.	<input type="checkbox"/> <input checked="" type="checkbox"/>	\$175.00 Qty: 4	\$379.98 Job Code: 6115D/1406LGT/E/10	\$554.98	<input type="checkbox"/>
updated Work lights - Remove & Install Technician Comments:Front roof lights do not work.	<input type="checkbox"/> <input checked="" type="checkbox"/>	\$230.00 Qty: 2	\$379.98 Job Code: 6115D/1406/FTH/10	\$609.98	<input type="checkbox"/>

Windows	Declined	Approved	Parts Estimate	Labor Estimate	Total Estimate	Warranty
updated Right Hand window seal - Remove & Install Technician Comments:LH seal also.	<input type="checkbox"/>	<input checked="" type="checkbox"/>	☞ \$70.00 Qty: 1	🔧 \$414.53 Job Code: 6115D/7320/DWS/R/10	💰 \$484.53	<input type="checkbox"/>
updated Rear window gas cylinder (each) - Remove & Install	<input type="checkbox"/>	<input checked="" type="checkbox"/>	☞ \$115.00 Qty: 2	🔧 \$196.90 Job Code: 6115D/7374/SCK/10	💰 \$311.90	<input type="checkbox"/>
updated Rear window lock lever - Remove & Install	<input type="checkbox"/>	<input checked="" type="checkbox"/>	☞ \$15.00 Qty: 1	🔧 \$114.00 Job Code: 6115D/7374/LK/10	💰 \$129.00	<input type="checkbox"/>

1 0 CHASSIS ☞ \$500.00 🔧 \$252.17 💰 \$752.17 🛡️ \$0.00

Chassis Electrical System	Declined	Approved	Parts Estimate	Labor Estimate	Total Estimate	Warranty
updated Battery - Remove & Install Technician Comments:Battery only has 1039 CCA and should have 1400. Battery tester says to replace.	<input type="checkbox"/>	<input checked="" type="checkbox"/>	☞ \$500.00 Qty: 1	🔧 \$252.17 Job Code: 6115D/1401/10	💰 \$752.17	<input type="checkbox"/>

3 0 POWERTRAIN ☞ \$1,950.00 🔧 \$1,784.20 💰 \$3,734.20 🛡️ \$0.00

MFWD Front Axle	Declined	Approved	Parts Estimate	Labor Estimate	Total Estimate	Warranty
updated Drive shaft (MFWD)- Recondition Technician Comments:Replace Front and rear seals and u joints.	<input type="checkbox"/>	<input checked="" type="checkbox"/>	☞ \$750.00 Qty: 1	🔧 \$808.33 Job Code: 6115D/3259/MFW/20	💰 \$1,558.33	<input type="checkbox"/>
updated Steering Steering cylinder - Recondition Technician Comments:Steering cylinder on RH side is leaking. Also ball joints are worn out on both sides.	<input type="checkbox"/>	<input checked="" type="checkbox"/>	☞ \$1,200.00 Qty: 2	🔧 \$690.88 Job Code: 6115D/4303/20	💰 \$1,890.88	<input type="checkbox"/>
updated Toe in - Adjust Technician Comments:Front tire wear is uneven.	<input type="checkbox"/>	<input checked="" type="checkbox"/>	☞ \$0.00 Qty: 1	🔧 \$284.99 Job Code: 6115D/4324/25	💰 \$284.99	<input type="checkbox"/>

2 0 ENGINE ☞ \$300.00 🔧 \$324.71 💰 \$624.71 🛡️ \$0.00

Electrical System	Declined	Approved	Parts Estimate	Labor Estimate	Total Estimate	Warranty
updated Alternator - Remove & Install Technician Comments:Alternator pulley is bent.	<input type="checkbox"/>	<input checked="" type="checkbox"/>	☞ \$100.00 Qty: 1	🔧 \$238.35 Job Code: 6115D/1405/10	💰 \$338.35	<input type="checkbox"/>
updated Intake System Air filter housing to turbo hose. Technician Comments:Hose is not on the turbo all the way.	<input type="checkbox"/>	<input checked="" type="checkbox"/>	☞ \$200.00 Qty: 1	🔧 \$86.36 Job Code: No Job Code	💰 \$286.36	<input type="checkbox"/>

7 0 SERVICE ITEMS ☞ \$745.00 🔧 \$1,048.41 💰 \$1,793.41 🛡️ \$0.00

MFWD Service	Declined	Approved	Parts Estimate	Labor Estimate	Total Estimate	Warranty
updated MFWD axle oil - Service	<input type="checkbox"/>	<input checked="" type="checkbox"/>	☞ \$65.00 Qty: 1	🔧 \$157.18 Job Code: 6115D/4008/29	💰 \$222.18	<input type="checkbox"/>
updated MFWD hub oil (both) - Service	<input type="checkbox"/>	<input checked="" type="checkbox"/>	☞ \$65.00 Qty: 1	🔧 \$189.99 Job Code: 6115D/7728/B/29	💰 \$254.99	<input type="checkbox"/>

Engine Oil and Filter	Declined	Approved	Parts Estimate	Labor Estimate	Total Estimate	Warranty
Engine oil & filter - Change	<input type="checkbox"/>	<input checked="" type="checkbox"/>	⚙️ \$150.00 Qty: 1	🛠️ \$238.35 Job Code: 6115D/7750/53	💰 \$388.35	<input type="checkbox"/>
Engine Air Filters	Declined	Approved	Parts Estimate	Labor Estimate	Total Estimate	Warranty
updated Engine air filters - Change	<input type="checkbox"/>	<input checked="" type="checkbox"/>	⚙️ \$160.00 Qty: 1	🛠️ \$89.81 Job Code: 6115D/7701/A/53	💰 \$249.81	<input type="checkbox"/>
Fuel Filter	Declined	Approved	Parts Estimate	Labor Estimate	Total Estimate	Warranty
Fuel filter (both) - Change	<input type="checkbox"/>	<input checked="" type="checkbox"/>	⚙️ \$65.00 Qty: 1	🛠️ \$169.27 Job Code: 6115D/7702/B/53	💰 \$234.27	<input type="checkbox"/>
Hydraulic Oil and Filter	Declined	Approved	Parts Estimate	Labor Estimate	Total Estimate	Warranty
updated Transmission filter - Change	<input type="checkbox"/>	<input checked="" type="checkbox"/>	⚙️ \$180.00 Qty: 1	🛠️ \$105.36 Job Code: 6115D/7708/53	💰 \$285.36	<input type="checkbox"/>
Cab Filters	Declined	Approved	Parts Estimate	Labor Estimate	Total Estimate	Warranty
updated Cab air filters - Change	<input type="checkbox"/>	<input checked="" type="checkbox"/>	⚙️ \$60.00 Qty: 1	🛠️ \$98.45 Job Code: 6115D/7717/CAB/53	💰 \$158.45	<input type="checkbox"/>