

**Department Reports
1.16.2025**

ELECTRIC DISTRIBUTION

POWER PLANT

STREET

Grading lake and town
Street sweeping
Hauling leaves
Pothole patching
Help take down Christmas decorations
Haul off ashes from lake burn site
Crack fill E Main and N LL&G (still have Main from West St to Springfield to finish)

WATER/WASTEWATER

MECHANIC

#49 A CHECK ON COURTESY CAR, BATTERY POWER, FUEL & DRIVEABILITY.

CHIP SEALER SPRAY WAND WAND HANDLE BROKE OFF DRILLED HOLE, INSTALLED 7/16 HELI COIL THREAD REPAIR. REINSTALLED HANDLE.

#1 E 2018 F550 BUCKET TRUCK SERVICE: CHANGED OIL & FILTER, AIR FILTER, ENGINE FUEL FILTER, WATER SEPERATOR/FUEL FILTER IN FRONT OF FUEL TANK, TIRE ROTATION, BRAKE CHECK, FOUND ALL PADS TO BE WORN TO 2/32. REPLACED FRONT & REAR BRAKE PADS. FOUND MASTER CYLINDER RESOVIOR CRACKED, R&R CAP, PRESSURE WASHED TRUCK UNDER AND TOP SIDE. CRANK CASE VENTALATION ON DRIVER SIDE TOP BACK OF ENGINE LOOKS TO BE THE ISSUE WITH THE SMALL OIL LEAK. WILL ORDER PARTS NEEDED AND CHANGE SOON.

#5 W 2016 F350 SERVICE: CHANGE OIL & FILTER, AIR FILTER, ADDED BG44K FUEL TREATMENT, FILLED TRUCK TANK UP WITH GAS, TIRE ROTATION, BRAKE CHECK, FOUND FRONT SHOCKS BLOWN OUT. REMOVE & REPLACED FRONT SHOCKS. WAS ASKED TO LOOK FOR 4X4 OR FRONTEND ISSUE AS A NOISE IS BEING HEARD WHEN WHEELS ARE IN MOTION, FOUND ALL TO BE OK, TIGHT, EVERYTHING FULL OF FLUIDS & NOT MAKING NOISE WHEN I TEST DRIVE TRYING TO FIND NOISE. TRUCK BACK IN SERVICE.

#30 S 2007 FORD DUMP TRUCK WASHED TRUCK TOP SIDE & UNDER. BRAKES MAKING NOISE, BRAKE CHECK GOOD, TOOK APART E-BRAKE TO FIND LOTS OF DUST AND GRIT IN DRUM, CLEANED BRAKE PADS & DRUM, NO MORE NOISE, SERVICE: CHANGE OIL & FILTER, AIR FILTER, FUEL FILTER, TRANSMISSION FILTER, FOUND LOOSE TIE RODS IN FRONT END CHECK, ORDERED PARTS TO DO NEXT WEEK. LIFT BED HYD CYLINDER LEAKING, NEED TO REMOVE CYLINDER SOON TO REBUILD, STEERING BOX LEAKING, NEED TO CHANGE SEAL OUT SOON, THESE TWO JOBS ARE VERY COMPLEX & TIME CONSUMING. WILL DO ANOTHER DAY WHEN CAUGHT UP.

#11 PEW 2005 F150 HEADLIGHT HOUSINGS FOGGED OVER BAD, CAN'T SEE MUCH OF HEADLIGHTS ON ROAD. REMOVE AND REPLACE HEAD LIGHT HOUSINGS & NEW BULBS. TOUCHED UP PAINT ON HOOD FOR BETTER APPERANCE REPUTATION.

#8 S 1981 CHEVY PU WATER PUMP BAD. ORDERED PUMP TO REPLACE NEXT WEEK.