Department Reports 7/25/2025

ELECTRIC DISTRIBUTION

Tickets, locates

Report of leaking transformer on S Jennings; fixed for now

Meter change out ant trimmed limbs from service at 535 S Jennings

Took down welcome flags

Replaced bulbs at 911 Memorial

Replaced blown arrestors in rural

Mounted breaker box and outlet boxes in Kayak shed

Repaired street lights on light list

Took down electrical service at 945 N Jennings for demolition

Report of outages in east rural; caused by limbs on phase

Report of outage in west rural; caused by lightning

Report of lights flickering at 114 E Main; caused from old wire connector

Turn on/off orders

POWER PLANT

Rounds

STREET

WATER/WASTEWATER

Rounds, tickets, locates Water leak repair Installed mini-split Spraying weeds Pothole sewer at the lake

MECHANIC

#49 A 2014 FORD EXPLORER CHECKED ON AIRPORT COURTESY CAR TO INSURE STARTS AND HAS FUEL.

#18 PK 2001 F150 LOOKING OVER REPAIR WORK THAT WAS DONE ON AC SYSTEM LAST FRIDAY, AC SYSTEM STILL HOLDING AND BLOWING COLD AFTER SITTING ALL WEEKEND.

#70 EWSL JOHN DEERE TRACTOR MOWER ASSISTED LAKE DEPT. WITH INSTALLING EXHAUST PIPE, CHECKED FRONT AXLE DIFF. OIL, AS FRONT DRIVE LINE SEAL LOOKS TO BE LEAKING, FRONT DIFF FLUID LEVEL IS OK. INSPECTION ON TIRES, NEEDS REAR DRIVE TIRES AS THESE ARE DRY ROTTED AND COMING APART AROUND THE GRIP AREA OF THE TREAD, & VERY LOW ON TREAD GRIP LUGS.

#81 PD 2023 DURANGO SERVICE, CHANGE OIL AND FILTER, AIR FILTER, 44K BG FUEL TREATMENT, TIRE ROTATION, BRAKE CHECK, THE SMELL OF COOLANT PRESENT, COOLANT LINE/HOSE'S INSPECTION, FOUND EGR OIL/COOLANT HARD LINE LEAKING ANTIFREZZE AT WELD WHERE PIPE SPLITS OFF TO A SMALLER SIZE, ORDERED OEM LINE FROM NEWBEERY'S

AS THIS PART IS DEALER ITEM ONLY AT THIS TIME. IT WILL BE A FEW DAYS TILL PART IS IN, FOR NOW SO CAR CAN STAY IN USE WITHOUT LEAKING COOLANT, I REPAIRED LINE WITH QUICK DRY HIGH HEAT JB WELD. WILL REPALCE LINE WHEN PART COMES IN. WASHED OUTSIDE OF VEHICLE.

PICKED UP SHOP, SWEEP FLOOR, FILE WORK ORDER'S & UPDATE PREVENTIVE MANTENANCE SHEET.

#80 W 2006 F150 ENGINE OVER HEATS WHEN LEFT IDLING AT JOB SITES, FLUSH SYSTEM, REMOVE AND REPLACE THERMOSTAT, CLEAN OUT RADIATOR, ADD NEW COOLANT, RADIATOR SUPPORT COVER HOLD DOWN PINS WORN OUT, INSTALLED NEW COVER PINS, NEW SERPENTINE BELT, TOPPED OFF GAS TANK & ADDED BG 44K FUEL TREATMENT TO HELP ENGINE RUN SMOOTHER AS IT SEEMS TO HAVE A SLIGHT STUMBLE IN THE IDLE. WASHED OUT SIDE OF TRUCK.

#17 PK GRASSHOPPER MOWER REPAIRED PULL CORD FOR DECK DISCHARGE CHUTE (WE PULL CHUTE UP WHEN LOADING/UNLOADING MOWER ON TRAILER SO IT DON'T RIP THE CHUTE OFF THE DECK AS IT HITS THE TRAILER SIDE FRAME WHEN ITS DOWN WHILE LOADING)

#70 EWSL JOHN DEERE TRACTOR MOWER LOOKING INTO NEW DRIVE TIRES AS OLD ONES ARE IN POOR SHAPE, DRY ROTTED, SPLITING APART, TREAD GRIP MISSING AND LUGS WORN DOWN. RECEIVED TIRE QUOTE FROM COOP TO TURN IN TO GET APPROVED.

NEW ELGIN STREET SWEEPER HAS ARRIVED! DEMONSTRATION OF MACHINE, TEST RUNNING MACHINE, LEARNING UP KEEP AND HOW TO CLEAN MACHINE PROPERLY FROM VINCE AND JOE FROM KEY EQUIPMENT.

#66 2007 BOBCAT S250 SERVICE, CHANGE OIL AND FILTER, AIR FILTERS, FUEL FILTER, ADDED BG FUEL TREATMENT, TOPPED OFF TANK WITH DIESEL, WASHED MACHINE AND ENGINE BAY.

#81 & 83 PD DURANGOS PICKED UP ORDERED PARTS FROM NEWBWEEY'S.

APPLIED VECHILE NUMBER STICKERS TO SEVERAL UNITS THAT WERE NOT NUMBERED.

#81 PD 2023 DURANGO FOUND EGR COOLER LINE TO BE LEAKING, REMOVE AND REPLACE EGR COOLER LINE, TOP OFF WITH COOLANT. TEST DRIVE. NO MORE LEAK.

#83 PD 2021 DURANGO REPLACE PASS. SIDE BROKEN SUN VISIOR HOLDER CLIP.

UPDATING EQUIPMENT VIN SHEETS, MANTENANCE SHEETS, FILTER SHEETS.