

STAFF REPORT

Removal of Historic Landmark Status, James Madison Williams House

December 17, 2019 Town Council Meeting



The purpose of the public hearing is to consider the facts, recommendation, and receive public comment in order to formulate a decision on the proposed application for the removal of the Historic Landmark status.

A public hearing notice has been posted in accordance with applicable requirements.

BACKGROUND INFORMATION:

Location: 4525 Green Level West Road
Applicant/ Property Owner: Eliza C. Williams

PROJECT DESCRIPTION:

Acreage: 6.46 Acres
PIN: 0713943728 (portion of)

EXISTING CONDITIONS/BACKGROUND:

On Wednesday, May 22, 2019 the Apex Historic Landmark known as the James Madison Williams House was tragically lost to a fire. It was a complete loss and nothing was able to be salvaged from the farmhouse structure. The farmhouse was the center of the landmark designation and since it no longer remains the site has lost its historical significance. Although the six outbuildings associated with the property remain, without the principal farmhouse, these structures do not possess the special character and integrity for local landmark designation.

REQUEST:


The applicant is requesting the removal of the Historic Landmark status for the James Madison Williams house located at 4525 Green Level West Road, in the Town of Apex, North Carolina, and owned by Eliza C. Williams, so that the Williams family can build a new family home on the site.

**James Madison Williams
House**

Batchelor Rd

Green Level West Rd





North Carolina Department of Natural and Cultural Resources
State Historic Preservation Office

Ramona M. Bartos, Administrator

Governor Roy Cooper
Secretary Susi H. Hamilton

Office of Archives and History
Deputy Secretary Kevin Cherry

November 7, 2019

Gary Roth
Capital Area Preservation, Inc.
P.O. Box 28072
Raleigh, NC 27611

RE: Proposed de-designation of the **James Madison Williams House, 4525 Green Level West Road, Apex, Wake County**

Dear Mr. Roth:

Thank you for notifying our office of the proposed de-designation of the James Madison Williams House located at 4525 Green Level West Road in Apex. We understand from your email of Thursday, October 24, 2019, that the property was tragically lost due to a fire several months ago. Although the six outbuildings associated with the property remain, we understand that without the principle property these structures do not possess the special character and integrity for local landmark designation. Thus, the proposed de-designation of the property appears to be appropriate.

We have updated our records to reflect that the James Madison Williams House is no longer extant. We request a copy of the de-designation ordinance to include in our files once it is available.

This letter serves as our comments on the proposed de-designation of the James Madison Williams House. Please contact me at 919-814-6575 should you have any questions about our comments.

Sincerely,

A handwritten signature in blue ink that reads "Amber E. Stimpson".

Amber E. Stimpson
Local Preservation Commissions / CLG Coordinator

CC: Commission Chair



Enclosure

November 7, 2019

To Whom it May Concern,

On Wednesday, May 22, our family home and Apex Historic Landmark, known as the James Madison Williams House, was tragically lost to a fire. It was a complete loss and nothing was able to be salvaged from the structure. It was my understanding that the main farmhouse was the center of the landmark designation, and since it no longer remains, the site has its historic significance. We are requesting that the property be de-designated as an Apex Historic Landmark so that we can build a new family home on the site. Please let me know if you need anything else. Thank you.

Sincerely,

Jimmy Williams on behalf of the Williams Family

Incident Number:19-0024721

Alarm Date:05/22/2019

FDID:09200

Wake County
Basic Fire Report

Basic Information

Location: Exact Location 4525 GREEN LEVEL WEST RD
Street Address Apex, NC 27523
TIMES
Alarm: 05:45:00
Arrival: 06:30:00
Controlled:
Cleared: 11:17:00

Incident Type: 111 Building fire
Assistance Rendered: Cause and Origin Investigation
Requesting Agency: 04 Town of Apex Fire Dept
Shift: A A Shift
District: 04 Apex
Actions Taken: 86 Investigate
Haz Mat Release: N None

GPS Coordinates:
Lat: 35.770907
Lon: -78.935093

Property Information

Property Use: 419 1 or 2 family dwelling
Mixed Property Use: NN Not mixed use
Property Value: 200,804.00 Property Loss Dollars: 200,804.00
Contents Value: 30,000.00 Contents Loss Dollars: 30,000.00

Involvements:

Name: Address: Phone: Involvement Type:
Williams, Jimmy 4525 GREEN LEVEL WEST RD Apex, NC 27523 919-369-8964
Williams, Eliza 4525 GREEN LEVEL WEST RD Apex, NC 27523

Responding Personnel and Units: Totals: Units: 1 Personnel: 2

Personnel:

Staff ID Name Unit Rank Activity
200 Stanley, David R WC1 FSR 901 General Office Work
200 Stanley, David R WC1 FSR 820 Fire Investigations
202 Gupton, H. Lee WC1 FSR 820 Fire Investigations
202 Gupton, H. Lee WC1 FSR 820 Fire Investigations
202 Gupton, H. Lee WC1 FSR 820 Fire Investigations

Units Times:

Unit: Notified: Roll: Arrival: Cleared: In Service:
WC1 05:45:00 05:45:00 06:30:00 11:17:00 11:17:00

Narrative:

WC-1 David Stanley responded to the above listed address at the request of Apex Fire Department Command. Upon arrival he met with Command (Apex Battalion Chief Beasley) and received an incident briefing and a formal request for an origin and cause investigation. Given the proximity to shift change, WC-1 Stanley contacted on coming WC-1 Lee Gupton and requested that he respond directly to the scene. WC-1 Stanley began processing the scene immediately by obtaining a verbal witness statement from the occupant of the residence and a signed consent to search. A visual observation of the scene was performed, and the scene was photographically documented. WC-1 Gupton will be listed as the Lead Investigator for this incident and will be responsible for this report and the associated narrative.

05/22/2019 20:04:40 LLGupton

This investigation was inactivated based on an email received from the Wake County Sheriff's Department Lieutenant Brent David of the Criminal Investigative Division on 5/5/2019

*** Denotes that dates on this incident occurred over multiple days.

Incident Number:19-0024721

Alarm Date:05/22/2019

FDID:09200

Wake County
Basic Fire Report

06/05/2019 06:40:04 LLGupton

Authorizations:

Lead Investigator: 202 Gupton, H. Lee

Rank: FSR Fire Services Responder

Initial Responder: 200 Stanley, David R

Rank: FSR Fire Services Responder

*** Denotes that dates on this incident occurred over multiple days.

Incident Number:19-0024721

Alarm Date: 05/22/2019

FDID:09200

Wake County
Fire/Structure Fire Report

Fire Information:

Residential Units: 1 On-Site Materials or Products: On-Site Materials or Products Usage:
Buildings Involved: 1
Acres Burned: 0

Ignition Details:

Area of Origin: 74 Attic: vacant, crawl space above top story, Contributing Factors:

Heat source: UU Undetermined NN None

Item First Ignited: UU Undetermined Human Factors:

N None

Type of Material First Ignited:

Cause of Ignition: 5A Undetermined

Equipment Involved:

NNN None

Make: Model: Serial Number:

Year: Power Source: Portability:

NN None

Involvement Type: N None

Model: Year: 0

Plate: State: Serial Number/VIN:

Structure Fire Information:

Structure Information:

Structure Type: 1 Enclosed building Number of Stories Damaged by Flame:

Building Status: 2 In normal use

Floors Above Grade: 2 Minor: 0 1-24%

Floors Below Grade: Significant: 0 25-49%

Main Floor Size: 3,414 Heavy: 0 50-74%

Floor of Origin: 2 Extreme: 2 75-100%

Fire Spread: 4 Confined to building of origin

Dectectors and Extinguishment Systems:

Detectors Present: 1 Present AES Presence: N None Present

Detector Type: 1 Smoke

Power Supply: 1 Battery only

Detector Operation: 2 Detector operated

Effectiveness: 1 Detector alerted occupants, occupants

FDID:09200

Wake County

Arson/Arson Involvements Report

Case/Scene:

Agency Referred To: WCSO Wake Co. Sheriff's Dept
330 S. Salisbury Street
P.O. Box 550
P.O. Box 550

Case Status: 3 Investigation inactive

Fire Involvement on 1st Arrival:

Cause and Origin Narrative:

SUMMATION

WC-1 David Stanley responded to the above listed address at the request of Apex Fire Department Command. Upon arrival he met with Command (Apex Battalion Chief Beasley) and received an incident briefing and a formal request for an origin and cause investigation. Given the proximity to shift change, WC-1 Stanley contacted on coming WC-1 Lee Gupton and requested that he respond directly to the scene. WC-1 Stanley began processing the scene immediately by obtaining a verbal witness statement from the occupant of the residence. A visual observation of the scene was performed, and the scene was photographically documented. Given that the owner/occupant with the reasonable expectation of privacy left the scene shortly after the initial interview due to health concerns, this fire will be investigated using the exigent circumstance exception to the warrant requirements. WC-1 Gupton will be listed as the Lead Investigator for this incident and will be responsible for this report and the associated narrative.

PARTICIPATING INVESTIGATORS

H. Lee Gupton, NC-CFI, Deputy Fire Marshal, Wake County Fire Services, WC-1 C-Shift, Lead Investigator
David Stanley, NC-CFI, Deputy Fire Marshal, Wake County Fire Services, WC-1 A-Shift, Initial Responder
Chad Edmunds, Special Agent, ATF, Investigative Assistance/Investigative Resource

BUILDING CONSTRUCTION

The structure was determined to be a two-story, wood-frame, single-family residence consisting of approximately 3414 square feet of conditioned space according to Wake County Tax Records. Based on tax record information and owner statements, the structure was originally built in 1911 and was renovated in the mid 1950's. The structure was known as the James Madison Williams House and was built in what was known as the Queen Anne style of design and construction based on information obtained from the Capital Area Preservation Society. The floor of the original structure was of rough sawn wood floor joist which at some point was enclosed with a masonry foundation wall to create a ventilated crawlspace. The wall studs, second level floor/ceiling assembly and roof structure were also constructed of rough sawn lumber. The roof sheathing consisted of one-inch thick skip-sheathing and covered with tin shingles. The interior wall and ceiling finishes were of drywall which covered the tongue and groove finishes that were original to the structure. The substrate of the floors was determined to be the original heart-pine flooring and covered with carpet and vinyl sheet goods. The finished bedrooms of the second level occupied only between 25% and 30% of the of the overall floor level. The remainder of the space was unconditioned and used primarily for storage. The dwelling was provided with battery operated smoke detectors on each floor level and in each bedroom based on statements provided by the owner and her son. In addition, a monitored security system was present within the structure and smoke detection components were incorporated into the system. It is not known if the battery-operated smoke detectors functioned. However, based on occupant statements, the notification appliance of the security/fire detection system did activate and awoke the occupant. The structure was occupied and secured at the time of the incident. An examination of the mechanical components of the structure revealed that the lower level was conditioned by a propane powered gas-pack that was located along the rear of the structure. The second level was conditioned by a gas furnace located in the unfinished area of the second floor. The condenser for this furnace was located along the rear of the structure as well. Gas logs were present within the fire place and all gas appliances noted above were fed from a remotely located above-ground propane tank in the rear yard. The electrical power was supplied via an overhead service drop to a 200-Ampere meter base located along the front left corner. This meter feed a 200-Ampere main breaker 42 circuit panel located under the enclosed portion of the carport along the front wall. Based on occupant/owner statements, no abnormalities had been experienced with the electrical system.

Arson/Arson Involvements Report

FIRE DEPARTMENT ACTIONS

Apex Fire Department along with automatic aid from Cary Fire Department and North Chatham Fire Department were dispatched to the above listed address in reference to a reported structure fire. Due to closest unit response and proximity Cary Engine 8 was the first apparatus to arrive and reported a working structure that was fully involved. Cary Engine 8 Officer (Captain Andy Hiscock) established command and performed a size up. Engine 8 deployed a 5-inch large diameter hose lay to the roadway for a water shuttle operation. Upon arrival of Cary Battalion 2 (Battalion Chief Kevin Annis), Command was transferred to him. As Apex Fire Department Battalion Chief 5 Michael Beasley arrived on scene, Command was transferred to him. Cary Engine 8 deployed attack lines to the rear of the structure to cool large propane tanks. North Chatham units provided the water shuttle operation while Apex and Cary Fire Departments performed suppression and overhaul operations. Eventually foam was used to extinguish the fire. WC-1 was dispatched automatically as a resource when this incident was upgraded to a working fire.

WITNESS STATEMENTS

Written witness statements were provided by the first arriving fire department personnel on board Cary Engine 8. Refer to the written statements in this file from Captain Andy Hiscock, Firefighter Phillip Bass, Firefighter Kenneth Gordon, Firefighter William Kochies and Firefighter Russell Fuller.

An initial interview was conducted by WC-1 Stanley upon arrival with the owner/occupant Eliza Williams. A more formal interview was conducted by WC-1 Gupton at approximately 11:15 hours after she was requested to return to the scene. The statement is transcribed below;

Mrs. Williams stated that she was awoken by the horn of the ADT burglar alarm system and she assumed someone was attempting to break into the residence. She proceeded from her bedroom to check all the doors throughout the first-floor level and found nothing wrong. On her way back to her bedroom, she noticed that smoke was coming down the stairwell and was starting to roll out onto the twelve-foot ceilings of the first floor. She stated that the smoke was light gray in color at that time. She stated that she proceeded to her bedroom, got dressed, grabbed her pocketbook and then proceeded back through the residence to the carport exit door bypassing at least two other exit doors as this was habit given that they always exit through the carport door. Once in the carport area, she stated that she realized that she did not have her phone. She stated that she proceeded back through the residence to her bedroom, unplugged her phone and attempted to call 911 from the bedroom, but the call dropped. She then called her son while proceeding back to the carport door and exited the structure. She advised that when she exited she went to the backyard where she could see flames protruding through the roof along the rear of the roof structure. She then moved to the front yard and waited for the fire department's arrival. She stated that she was upset, emotional and already had a scheduled doctor's appointment that morning and contacted her daughter to come pick her up and carry her to the scheduled appointment. In addition, she has lost her eyeglasses and all diabetic medications as a result of the fire and needed to have her daughter take her to the doctor, pharmacy and ophthalmologist to obtain needed medications and eyeglasses.

A verbal witness statement was obtained from Jimmy Williams, the son of Eliza Williams at the scene by WC-1 Gupton at approximately 08:45 hours and is transcribed below;

Mr. Williams advised on structural and finish elements throughout the structure. He stated that there were 9-volt battery operated smoke detectors located throughout the dwelling which he was responsible for and he made certain that the batteries were changed regularly as his mother resided alone within the structure. In addition, an ADT monitored burglar alarm system was in place within the dwelling. The system did have smoke detection components tied to the burglar alarm. The two smoke detectors tied to this system were located on the first floor in the main corridor and the second-floor detector was located along the rear wall above the air-return near the door leading to the attic storage area. He stated that the upper level consisted of an open area below the turret and bedrooms located to the left and right sides of this open area. A smaller door leading to the unfinished storage area was located along the rear wall that separated the finished area from the unfinished storage area. He advised that the only electrical components present in the storage area were those associated with the gas furnace located just inside the door to the unfinished area and one overhead light that was mounted to a cross member and suspended from the roof structure. This light was controlled by a switch on the finished side of the wall and to the left of the door leading to the unfinished area. In addition, the air return was present in this same area as well as the ADT smoke detector. He stated that the gas line for the gas furnace was believed to have been run up through the wall from the crawlspace of the first floor, but was uncertain. He stated that they had experienced no issues with the furnace or electrical components of the structure. Furthermore, the air-conditioning to the second level via the gas furnace air-handler was in the off position as it had not gotten hot enough in the upper level to have it operating yet. He provided information with respect to the

Arson/Arson Involvements Report

renovation that occurred at some point in the mid 1950's where all of the original tongue and groove wall and ceiling finishes were covered in drywall and electricity was introduced into the structure.

FIRE SCENE PROCESSING

The fire scene processing began immediately upon arrival of WC-1 Stanley by obtaining initial photographs and performing initial interviews with the occupant and her son. An incident briefing was conducted with Command and they advised that this was determined to be located within the Apex Fire Department's Fire Response District, but due to proximity, Cary Fire Department Engine 8 was the first to arrive. As suppression efforts were still underway, he contacted on-coming WC-1 Gupton and requested that he respond directly to the scene with a spare vehicle. WC-1 Stanley remained on the scene and coordinated with Command. WC-1 Gupton contacted Chad Edmunds of the Bureau of Alcohol, Tobacco and Firearms for assistance as an external resource. Once all parties had arrived on scene, an in-depth interview with Mr. Williams was conducted and visual observations of the remains of the structure were made. The owner/occupant Eliza Williams was requested to return to the scene or investigators could meet her at another location as she was extremely emotional about the loss of the dwelling. Once she had returned to the scene, an in-depth interview with her was conducted. Given the second floor was obliterated by the fire and only portions of the first-floor walls and floor remained intact, the information obtained from the interviews were used to form a hypothesis of the fire origin. Statements made by Eliza Williams were that when she exited the structure, the two vehicles parked under the carport were not involved in the fire. In addition, Jimmy Williams stated that when he arrived on scene (prior to the fire department), that the vehicles were just beginning to become involved. The statements of Captain Andy Hiscock advised that upon his initial size up, both vehicles were involved. Statements by Eliza Williams were that upon exiting the structure and carport area, she could see fire on the rear of roof. Based on a building layout of the second floor provided by Jimmy Williams, this portion of the roof would have been directly above the unfinished storage area of the second level.

Potential ignition sources were discussed in the storage area and the only ones known to be present were those of the gas furnace and its associated electrical and gas components. The other was that of the overhead light and associated wiring present the storage area. The weather conditions prior to the incident were reportedly 70 degrees Fahrenheit with a 55% relative humidity and winds from the east at 9 miles per hour.

CONCLUSION

It is the consensus of the investigators involved that this fire be classified as undetermined given that no specific ignition source or ignition sequence could be determined. The area of origin is that of the unfinished storage area of the second-floor level. This incident will remain under investigation until such time as additional information may be forthcoming. Although no indications of criminal activity were observed, given that this fire cause is left undetermined, a referral was sent to the Wake County Sheriff's Office per departmental policy.



FDID	State	Incident #	Exposure	CAD #	Station	Shift
09205	NC	190001586	0	19-001584	5	A
Incident Date	Event / Call Time		Incident Action			
5/22/2019	04:31:02		11 Extinguishment by fire service personnel			
Incident Type			86 Investigate			
111	Building fire					

Times

Alarm Time	Enroute	Arrival	Last Unit Cleared	Time Controlled
04:32:14	04:34:15	04:42:39	15:35:52	
EMS Unit	EMS Dispatch	EMS Enroute	EMS Arrival	With Patient

General

Location Type	Property ID		
1 - Street address	4525 GREEN LEVEL WEST RD Apex		
District/Box	State	City	Zip Code
County	NC - North Carolina	Apex	27523
Number/Milepost	Street or Highway		Apt./Suit/Room
4525	GREEN LEVEL WEST RD		
Number/Milepost	Crossing street		

Narrative

Apex, Cary and North Chatham Fire Departments responded to a structure fire at 4525 Greenlevel West Rd. Cary Engine 8 was first on scene and reported heavy fire showing and established command. Cary Battalion 2 was the first chief officer on scene and assumed command from Engine 8. Due to the level of fire involvement all fire attack was defensive from the exterior of the structure. The only occupant was able to escape before any fire department resources arrived. There were no reported injuries to civilian or fire service personnel. Fire department units remained on scene until Wake County fire marshals completed their investigation, at that point the property was turned back over to the owners.

Fire

Total of Buildings Involved 1

Total Acres Burned

Less Than One Acre Burned

Ignition

Area of Fire Origin

UU Undetermined

Heat Source

UU Undetermined

Item First Ignition

UU Undetermined

Type of Material First Ignited

uu Undetermined

Cause of Ignition

U - Cause undetermined after investigation

Equipment Involved

Brand

Model

Serial Number

Year

Equipment Power Source

Equipment Portability

If Age is a Factor

Age

Human Factors Gender

Suppression Factors

411 Delayed detection of fire

412 Delayed reporting of fire

Factor Contributing To Ignition

UU Undetermined

Human Factors Contributing To Ignition

N - None

On Site Material

Mobile Property Involved

Involvement Type

Property Type

Make

Model

Year

License Plate

State

VIN

Structure Fire

Structure Type

1 - Enclosed building

Structure Status

2 - In normal use

Fire Spread

4 - Confined to building of origin

Main Floor Size**Length**

X

Width

OR

Square Feet

3414

Floor of Origin

2

Building Height**Stories Above Grade**

2

Stories Below Grade

0

Stories Flame Damage**Minor****Significant****Extreme****Heavy**

2

Detector Presence

1 - Present

Detector Type

1 - Smoke

Detector Power Supply

U - Undetermined

Detector Operation

2 - Detector operated

Detector Effectiveness

1 - Detector alerted occupants -

Detector Failure Reason**AES Presence**

N - None Present

AES Type**AES Operation****AES Failure Reason****Number Of Sprinklers**

Arson

General Information**Case Status****Availability Of Material First Ignited****Extent of Fire Involvement on Arrival****Entry Method****Incendiary Device****Container****Ignition/Delay Device****Fuel****Property Ownership****Suspected Motivation Factors****Apparent Group Involvement****Initial Observations****Laboratories Used****Other Investigative Information****Other Information****Juvenile Information**

Property

Is Residential **Number of Residential Units:** 1

Estimated Dollar Value and Losses

PRE-INCIDENT VALUES

Property \$500,000.00

Contents \$250,000.00

LOSSES (If no loss, leave blank)

Property \$500,000.00

Contents \$250,000.00

Property Use / HazMat / Detector Status

Property Use

419 1 or 2 family dwelling

Mixed Property Use

65 - Farm use

HazMat Release

Detector Status

1 - Detector alerted occupants

Mutual Aid

Notify Date/Time **Cancel Date/Time** **Arrival Date/Time** **Cleared Date/Time**

Agency Information

Fire Department

Cary Fire Department

FDID

09203

State

NC

Custom Department Identifier

Mutual Aid Purpose

Agency Incident #

19-0004425

Aid

Fire Apparatus Provided 6

Fire Personnel Provided 21

Rescue Apparatus Provided

Rescue Personnel Provided

EMS Apparatus Provided

EMS Personnel Provided

Other Apparatus Provided

Other Personnel Provided

Notify Date/Time Cancel Date/Time Arrival Date/Time Cleared Date/Time

Agency Information

Fire Department North Chatham Volunteer Fire Department	FDID 01905	State NC
Custom Department Identifier	Mutual Aid Purpose	Agency Incident # 1922997

Aid

Fire Apparatus Provided 5	EMS Apparatus Provided
Fire Personnel Provided 7	EMS Personnel Provided
Rescue Apparatus Provided	Other Apparatus Provided
Rescue Personnel Provided	Other Personnel Provided

Response

Apparatus ID	CAD App ID	Dispatch (DP)	Dispatch (DC)	Enroute (ER)	Arrival (AR)	Cleared	# of Personnel
BAT5	BAT5	04:32:15	04:32:15	04:34:35	04:44:21	12:09:04	1

Apparatus Narrative

BATT5 of type Chief officer Car responded after receiving a STRUCTURE FIRE-SINGLE RESIDENT call at 05/22/19 04:32:15. Apparatus went enroute at 05/22/19 04:34:35. arrived on site at 05/22/19 04:44:21. after performing Incident command. by Michael G Beasley,

Actions for Apparatus	
81	Incident command

- On arrival we found a single family structure well involved in fire Crews made an exterior defensive attack due to the structure already well involved in fire.

Personnel	Arrival Time	Clear Time	Actions Taken
Michael Beasley	04:44:21	12:09:04	

Apparatus ID	CAD App ID	Dispatch (DP)	Dispatch (DC)	Enroute (ER)	Arrival (AR)	Cleared	# of Personnel
E35	E35	04:32:14	04:32:14	04:34:15	04:42:39	11:58:37	3

Apparatus Narrative

Engine 35 arrived on scene to a working house fire. Upon arrival Cary Fire Department established Fire Command and initiated an exterior, defensive attack as the home was at least two thirds involved with fire. Engine 35's personnel formed a Rapid Intervention Team with Cary Rescue 7. We were then asked by Command to protect exposures and to extinguish the fire from a safe distance. We used two different attack lines that were already in use. We switched to a foam operation with our Pro Paks but went back to attack nozzles. Veasey, Wallace, and Hamilton were relieved by Dague, Cirasole, and Wilson after 0800. We drove the CERT Van back to Station 5.

Actions for Apparatus	
73	73 Provide manpower

Personnel	Arrival Time	Clear Time	Actions Taken
Robert Veasey	04:42:39	11:58:37	73 - Provide
Lawrence Hamilton	04:42:39	11:58:37	73 - Provide
Loren Wallace	04:42:39	11:58:37	73 - Provide

Apparatus ID	CAD App ID	Dispatch (DP)	Dispatch (DC)	Enroute (ER)	Arrival (AR)	Cleared	# of Personnel
TANK31	TANK31	04:45:32	04:45:32	04:56:28	05:13:14	07:44:56	1

Apparatus Narrative

TANK 1 of type Tanker & pumper combination responded after receiving a STRUCTURE FIRE-SINGLE RESIDENT call at 05/22/19 04:45:32. Apparatus went enroute at 05/22/19 04:56:28. arrived on site at 05/22/19 05:13:14. Team cleared site at 05/22/19 07:44:56. after performing Provide water. by Jonathon Baker,

Actions for Apparatus	
76	Provide water

- What was found when you arrived on scene?
- What was done to mitigate the situation?
- What was the outcome?

Personnel	Arrival Time	Clear Time	Actions Taken
Jonathon Baker	05:13:14	07:44:56	

Apparatus ID	CAD App ID	Dispatch (DP)	Dispatch (DC)	Enroute (ER)	Arrival (AR)	Cleared	# of Personnel
TANK35	TANK35	04:45:32	04:45:32	11:50:44	12:28:27	15:35:52	0

Apparatus Narrative

Did not respond

Apparatus ID	CAD App ID	Dispatch (DP)	Dispatch (DC)	Enroute (ER)	Arrival (AR)	Cleared	# of Personnel
E34	E34	11:50:44	11:50:44	11:50:44	12:01:38	15:35:52	2

Apparatus Narrative

E34 of type Engine responded after receiving a STRUCTURE FIRE-SINGLE RESIDENT call at 05/22/19 11:50:44. Apparatus went enroute at 05/22/19 11:50:44. arrived on site at 05/22/19 12:01:38. Team cleared site at 05/22/19 15:35:52. by Joshua B Stone, Zachary R Lindsey,

Engine 34 stood by during investigation and cooled hot spots.

Personnel	Arrival Time	Clear Time	Actions Taken
Joshua Stone	12:01:38	15:35:52	
Zachary Lindsey	12:01:38	15:35:52	

Owner /Involved Person and Entities

Owner Full Name	Owner / Involved	Person / Entity	Phone Number	Entity Name
Williams,Eliza C	1 - Owner	1 - Person		

Authorization

Member Making Report

Member Making Report	Member Making Assignment	Report Completed Date
Michael Beasley	Battalion Chief	5/23/2019

Officer In Charge

Officer In Charge	Officer In Charge Assignment
Michael Beasley	Battalion Chief

Review

Report Reviewed By	Report Reviewed Date
Michael Beasley	5/23/2019

CAD Details

EventDetails: AgencyCode: AFD ReportNumber: 19001584 CadInciNumber: 190522065 NatureCode: 69E6
NatureDescription: STRUCTURE FIRE-SINGLE RESIDENT EventPriorityCode: P PriorityDispatchDeterminant:
69E06 LocationTypeCode: 1 StreetNumber: 4525 StreetDirection/: StreetName: GREEN LEVEL WEST
StreetType: RD StreetPostDirection/: ApartmentSuite/: ApartmentSuiteUnfiltered/: FullAddress: 4525 GREEN
LEVEL WEST RD CityCode: APEX CityCodeDescription: APEX State: NC ZipCode: 27523 SiteName/:
SiteCADKey/: SiteTypeCode/: XStreetDirection/: XStreetName/: XStreetType/: XStreetPostDirection/:
EventLatitude: 35.76897 EventLongitude: -78.93483 SPGeox: 2019335.00 SPGeoy: 734785.00 DMSLatitude: 35
46 8.29 N DMSLongitude: 78 56 5.39 W DMMLatitude: 35 46.1382 N DMMLongitude: 78 56.0898 W
AdditionalAddressInfo: DIST: 237.05 ft (S)COUNTY JURISDICTION (N) EventStartTime: 2019-05-22 04:31:02
FirstDispatchTime: 2019-05-22 04:32:14 FirstEnrouteTime/: FirstOnSceneTime/: UnderControlTime/:
LastUnitClearTime/: FirstTransportTime/: LastTransportArriveTime/: EventCompletedTime/: LastExportTime:
2019-05-22 04:32:16 PatientContactTime/: EventDistrict: 035 EventStation: S35 EventBeat/:
EventReportingArea: 350 CadResponsePlan: APXN CadResponsePlanCategory: 69MD CallerName: VERIZON
CallerAddress: 2 NC 540 SB CallerNumber: 9193698964 CallSource: W911 E911Used: T CallTakerUserId:
LPAUL CallTakerName: Paul,Lauren DispatcherUserId: TBAZEMOR DispatcherName: BAZEMORE, TIFFANY
EventDispositionCode/: MultipleEventDispositions/: FirstAgencyArriveTime/: CadNotes/: PrimaryUnit: E35
LinkedEvents: Event: AgencyCode: CPD ServiceType: LAW ReportNumber/: CadInciNumber: 190522067
Event: AgencyCode: WCEM ServiceType: EMS ReportNumber/: CadInciNumber: 190522068 Event:
AgencyCode: CFD ServiceType: FIRE ReportNumber: 19004425 CadInciNumber: 190522069



TOWN OF APEX

POST OFFICE BOX 250
APEX, NORTH CAROLINA 27502
PHONE 919-249-3426

PUBLIC NOTIFICATION OF PUBLIC HEARINGS

Historic Landmark De-Designation James Madison Williams House

Pursuant to the provisions of North Carolina Statutes Section § 160A-400.1. through § 160A-400.15. and to the Town of Apex Unified Development Ordinance (UDO) Section 2.2.11, notice is hereby given of public hearings before the Town Council of the Town of Apex. The purpose of these hearings is to consider the following:

The house known as the James Madison Williams House caught fire on May 22, 2019 and was a total loss.

Applicant/Property Owner: Eliza C. Williams
Property Address: 4525 Green Level West Road
Acreage: ± 6.46
Property Identification Number (PIN): 0713943738 (only a portion)
2045 Land Use Map Designation: Low Density Residential
Zoning of Property: Rural Residential (RR)

Public Hearing Location: Apex Town Hall
73 Hunter Street, Apex, North Carolina
Council Chambers, 2nd Floor

Town Council Public Hearing Date and Time: December 17, 2019 7:00 P.M.

Vicinity Map:



All interested parties may appear at the public hearing and be heard with respect to the application. Maps showing the location for the above site(s) to be considered in addition to a copy of the [2045 Land Use Map](#) can be inspected at the Apex Town Hall or call 919-249-3426, Department of Planning and Community Development, for further information. To view the petition and related documents on-line: <https://www.apexnc.org/DocumentCenter/View/30056/>

Dianne F. Khin, AICP
Planning Director



TOWN OF APEX
 POST OFFICE BOX 250
 APEX, NORTH CAROLINA 27502
 PHONE 919-249-3426

**PUBLIC NOTIFICATION
 OF PUBLIC HEARINGS**

**Historic Landmark De-Designation
 James Madison Williams House**

Pursuant to the provisions of North Carolina Statutes Section § 160A-400.1. through § 160A-400.15. and to the Town of Apex Unified Development Ordinance (UDO) Section 2.2.11, notice is hereby given of public hearings before the Town Council of the Town of Apex. The purpose of these hearings is to consider the following:

The house known as the James Madison Williams House caught fire on May 22, 2019 and was a total loss.

Applicant/Property Owner: Eliza C. Williams
Property Address: 4525 Green Level West Road
Acreage: ± 6.46
Property Identification Number (PIN): 0713943738 (only a portion)
2045 Land Use Map Designation: Low Density Residential
Zoning of Property: Rural Residential (RR)

Public Hearing Location: Apex Town Hall
 73 Hunter Street, Apex, North Carolina
 Council Chambers, 2nd Floor

Town Council Public Hearing Date and Time: December 17, 2019 7:00 P.M.

Vicinity Map:



All interested parties may appear at the public hearing and be heard with respect to the application. Maps showing the location for the above site[s] to be considered in addition to a copy of the [2045 Land Use Map](#) can be inspected at the Apex Town Hall or call 919-249-3426, Department of Planning and Community Development, for further information. To view the petition and related documents on-line: <https://www.apexnc.org/DocumentCenter/View/30045>.

Dianne F. Khin, AICP
 Planning Director

Published Dates: November 27, 2019 – December 17, 2019