



930 S. West St.

Wichita, KS 67213

(316) 943-4246

December 18, 2025

**City of Arkansas City
Arkansas City, KS**

Model: D51EX-22

S/N: B12518

Tracking issues. Hydraulic oil was contaminated with water causing the pump to fail.

Parts: HST pump, drive motor hoses and new oil.	\$ 12,157.93
Labor:	\$ 4,296.00
Expendable Supplies:	\$ 343.68
Troubleshooting total: For diagnosis and oil flushing.	\$ 8,246.34

Job Total:	\$ 25,043.95
-------------------	---------------------

This is an estimate only and may be subject to a 10% to 15% variance plus or minus and is for above repairs only. Estimate does not include freight or tax. Estimate is valid for 30 days from date written and expires on 1/17/2026 .

Thank you for the continued opportunity to earn your business. If I can be of assistance with any other parts or service need, please feel free to reach out to me at any time.

Derrick Sutton

Service Manager

O: (316) 943-4246

C: (316) 644-8935